

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0363/2023/EQ
DATE : 11-Apr-23
WIP : 15858

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/4/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TNG TEE KIAN
ADDRESS : BLK 35 JALAN RUMAH TINGGI
#07-499
SINGAPORE 150035
TELEPHONE : HP +65 83680889
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100484946-06
VEHICLE NO : **SCX 6000 Z**
MODEL CODE : AUDI Q5 2.0 TFSI QUATTRO
MODEL YEAR : 30/9/2016
ENGINE NO : CNC 174552
CHASSIS NO : WAUZZZ8R9HA029276
MILEAGE : 115,434
DATE IN : 10-Apr-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Apr-23
PLACE OF ACCIDENT : JUNCTION OF BARTLEY ROAD AND UPPER SERANGOON
ROAD TOWARDS WOODLEIGH

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 6000 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,600.00 ✓	
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILTIAE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 280	
5	TO CARRY OUT BLEEDING FOR ABS CONTROL UNIT.	S/N \$ 780.00 ?	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,800.00 3000	
TOTAL LABOUR CHARGES		: \$ 13,020.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 6000 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, BOTH UPPER A-PILLAR AND BOTH FRONT DOOR. <i>X.</i>	\$ 8,500.00	<i>3500</i> <i>3300</i> <i>6 x 550 = 3300</i> <i>Hinge XL = 200</i> <i>3500</i>
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	<i>X</i>
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	<i>192</i>
TOTAL LABOUR CHARGES		: \$ 22,184.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,066.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 304.00	+	
3	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 248.00	?	
4	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1	\$ 134.00	✓	
5	FRONT BUMPER PULL STRAP <i>new</i>	4	\$ 245.00	+	
6	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 88.00	?	
7	FRONT BUMPER TOP COVER <i>Delced</i>	1	\$ 151.00	✓	
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	1	\$ 415.00	✓	
9	FRONT BUMPER SIDE REINFORCEMENT <i>Dented</i>	1	\$ 798.00	✓	
10	FRONT BUMPER CENTER LOWER COVER <i>new</i>	1	\$ 77.00	✓	
11	FRONT BUMPER SIDE REINFORCEMENT BRACKET <i>Best</i>	1	\$ 285.00	✓	
12	FRONT BUMPER GUIDE SECTION - LH <i>dyed</i>	1	\$ 44.00	✓	
13	FRONT BUMPER SUPPORT - LH / RH <i>LH dyed</i>	2	\$ 72.00	36	
14	CAUTION SIGN STICKER <i>3 new</i>	1	\$ 17.00	✓	
15	AIR CONDITIONER STICKER <i>3 new</i>	1	\$ 9.00	✓	
16	FRONT PARKING AID SENSOR - INNER / OUTER <i>1 piece done</i>	3	\$ 815.00	271	
17	FRONT PARKING AID SEAL RING <i>3 new</i>	4	\$ 6.00	+	
18	FRONT BUMPER WIRING SET <i>3 new</i>	1	\$ 573.00	+	
19	HORN HIGH TONE - LH ?	1	\$ 226.00	?	
20	HORN BRACKET - LH ?	1	\$ 30.00	?	
SUB TOTAL SPARE PARTS		:	\$ 7,603.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER - LH / RH <i>LH Distorted</i>	2	\$ 2,380.00	<i>1690.</i>
22	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2	\$ 149.00	<i>+</i>
23	FRONT FENDER BRACKET - LH <i>?</i>	1	\$ 63.00	<i>Best</i>
24	FRONT FENDER BRACKET - CENTER <i>Best</i>	1	\$ 59.00	<i>✓</i>
25	FRONT FENDER BRACKET - REAR	1	\$ 59.00	<i>✓</i>
26	FRONT FENDER RIVET <i>new</i>	6	\$ 24.00	<i>✓</i>
27	FRONT FENDER BRACE - LH <i>Best</i>	1	\$ 104.00	<i>✓</i>
28	FRONT FENDER CLOSING ELEMENT - LH REAR <i>?</i>	1	\$ 124.00	<i>?</i>
29	FRONT FENDER SEAL - LH / RH <i>?</i>	2	\$ 76.00	<i>?</i>
30	FRONT WHEEL HOUSING LINER - LH / RH <i>LH crumpled</i>	2	\$ 618.00	<i>309.</i>
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	2	\$ 229.00	<i>+</i>
32	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 200.00	<i>+</i>
33	FRONT NOISE INSULATION <i>new</i>	1	\$ 966.00	<i>+</i>
34	FRONT FENDER LINING - LH / RH <i>?</i>	2	\$ 412.00	<i>?</i>
35	BONNET <i>Distorted</i>	1	\$ 4,651.00	<i>✓</i>
36	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 158.00	<i>✓</i>
37	BONNET HINGE - LH / RH <i>Best</i>	2	\$ 242.00	<i>✓</i>
38	BONNET CATCH HOOK <i>?</i>	1	\$ 165.00	<i>?</i>
39	BONNET LOCK <i>Jammed</i>	1	\$ 241.00	<i>✓</i>
40	BONNET LOCK CABLE <i>?</i>	1	\$ 58.00	<i>?</i>
SUB TOTAL SPARE PARTS			\$ 10,978.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET EDGE PROTECTION <i>new</i>	1	\$ 33.00	✓
42	BONNET LOCK COVER ?	1	\$ 27.00	?
43	BONNET GAS FILLED STRUT <i>new</i>	2	\$ 271.00	+
44	BONNET SEAL - LH OUTER <i>new</i>	1	\$ 103.00	✓
45	FRONT DAMPING - LH REAR ?	1	\$ 27.00	?
46	ENGINE BONNET SOUND ABSORBER <i>crushed</i>	1	\$ 376.00	✓
47	HEADLIGHT MOUNTING - LH / RH ?	2	\$ 280.00	
48	HEADLIGHT GAS DISCHARGE LAMP - LH / RH <i>LH crushed</i>	2	\$ 6,650.00	3325.
49	HEADLIGHT RETAINING PLATE - LH / RH ?	2	\$ 184.00	?
50	HEADLIGHT HEAT SINK - LH <i>new</i>	1	\$ 1,216.00	+
51	GAS DISCHARGE LAMP <i>new</i>	1	\$ 462.00	+
52	GAS DISCHARGE LAMP CONTROL UNIT <i>new</i>	1	\$ 1,390.00	+
53	DAY DRIVING LIGHTS POWER MODULE <i>new</i>	1	\$ 690.00	+
54	HEADLIGHT HOSE - LH <i>new</i>	1	\$ 39.00	+
55	HEADLIGHT RETAINING PLATE - LH ?	1	\$ 29.00	?
56	HALOGEN FOG LAMP ?	1	\$ 361.00	?
57	LIFT CYLINDER - LH / RH ?	2	\$ 474.00	?
58	LIFT CYLINDER HOSE <i>new</i>	1	\$ 208.00	+
59	LIFT CYLINDER WASH WATER RESERVOIR ?	1	\$ 253.00	?
60	RADIATOR GRILLE <i>Smashed</i>	1	\$ 2,257.00	✓
SUB TOTAL SPARE PARTS		:	\$ 15,330.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	"QUATTRO" INSCRIPTION <i>new</i>	1	\$ 118.00	✓
62	RADIATOR GRILLE STRIKER PLATE <i>could</i>	1	\$ 155.00	✓
63	LOCK CARRIER <i>Distorted</i>	1	\$ 1,299.00	✓
64	OUTSIDE TEMPERATURE SENSOR BRACKET <i>?</i>	1	\$ 22.00	?
65	A/C CONDENSER <i>Dented</i>	1	\$ 865.00	✓
66	A/C CONDENSER REFRIGERANT HOSE <i>?</i>	1	\$ 450.00	+
67	A/C CONDENSER REFRIGERANT PIPE <i>new</i>	1	\$ 661.00	+
68	A/C CONDENSER REFRIGERANT PIPE <i>new</i>	1	\$ 812.00	+
69	A/C CONDENSER PRESSURE SENDER <i>?</i>	1	\$ 207.00	?
70	A/C SERVICE VALVE CORE <i>?</i>	1	\$ 57.00	?
71	CHARGE AIR COOLER <i>new</i>	1	\$ 665.00	+
72	CHARGE AIR COOLER PRESSURE HOSE <i>new</i>	1	\$ 272.00	+
73	CHARGE AIR COOLER PRESSURE PIPE <i>new</i>	1	\$ 272.00	+
74	FRONT PULSATION DAMPER <i>?</i>	1	\$ 93.00	?
75	CHARGE AIR COOLER PRESSURE HOSE <i>new</i>	1	\$ 71.00	+
76	RADIATOR WITH OIL COOLER <i>?</i>	1	TBC	?
77	RADIATOR SUPPORT <i>?</i>	1	\$ 45.00	?
78	RADIATOR RUBBER BUSH - LOWER <i>?</i>	2	\$ 9.00	?
79	RADIATOR RUBBER BUSH - UPPER <i>?</i>	2	\$ 17.00	?
80	READY-MIX COOLANT <i>new</i>	6	\$ 326.00	✓
SUB TOTAL SPARE PARTS		:	\$ 6,416.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	RADIATOR TWIN FAN RING ?	1	\$ 318.00 ?	
82	RADIATOR COVER - UPPER ?	1	\$ 36.00 ?	
83	RADIATOR SEALING STRIP - LOWER ?	1	\$ 57.00 ?	
84	RADIATOR AIR GUIDE - LH / RH LH pmd	2	\$ 84.00 42.	
85	RADIATOR FAN ?	1	\$ 913.00 ?	
86	RADIATOR FAN ?	1	\$ 827.00 ?	
87	RADIATOR FAN CONTROL UNIT ?	1	\$ 983.00 ?	
88	FRONT INTAKE MANIFOLD ?	1	\$ 43.00 ?	
89	FRONT BELLOWS RESONATOR ?	1	\$ 126.00 ?	
90	FRONT AIR FILTER ?	1	\$ 400.00 ?	
91	FRONT AIR FILTER ADAPTER ?	1	\$ 14.00 ?	
92	FRONT INTAKE MANIFOLD ?	1	\$ 96.00 ?	
93	FRONT AIR CLEANER ADAPTER ?	1	\$ 20.00 ?	
94	FRONT ABS UNIT ?	1	\$ 7,212.00 ?	
95	FRONT ABS UNIT BRACKET ?	1	\$ 32.00 ?	
96	FRONT FLAT CONTACT HOUSING WITH GASKET ?	1	\$ 69.00 ?	
97	FRONT APRON SUPPORT - LH ?	1	\$ 189.00 ?	
98	FRONT BRAKE PIPE FROM HYDRAULICS TO BRAKE HOSE - LH ?	1	\$ 87.00 +	
99	FRONT BRAKE PIPE FROM HYDRAULICS TO BRAKE HOSE - RH ?	1	\$ 105.00 +	
100	FRONT BRAKE HOSE He new	2	\$ 181.00 +	
SUB TOTAL SPARE PARTS		:	\$ 11,792.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6000 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	FRONT FENDER CONNECTING PLATE - LH UPPER ?	1	\$ 429.00	?
102	FRONT FENDER CLOSING ELEMENT - LH LOWER ?	1	\$ 617.00	?
103	FRONT WATER DEFLECTOR STRIP - LH / RH ?	2	\$ 160.00	+
104	FRONT ROOF CHROME MOLDING - LH / RH ?	2	\$ 1,498.00	+
105	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH ?	2	\$ 740.00	+
106	FRONT NUMBER PLATE ?	S/N	\$ 60.00	✓
107	ACRYLIC SEALANT ?	S/N	\$ 180.00	?
108	CAVITY WAX ?	S/N	\$ 140.00	?
109	STONE CHIP ?	S/N	\$ 180.00	?
110	METAL FILLER POWDER ?	S/N	\$ 280.00	?
111	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS			: \$ 56,903.00	
TOTAL LABOUR CHARGES			: \$ 22,184.00	
GRAND TOTAL			: \$ 79,087.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Wong*
SURVEYED DATE : *12/04/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 11 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT