



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 1206Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (WCP)	BUCKLED	210.00	210.00
6	REAR BUMPER CLIP @\$2.00 (WCP)	NECESSARY	12.00	12.00
2	TAILLAMP @\$250.00 (WCP)	SERVICEABLE	500.00	-
1	REAR BOOT (WCP)	BENT	350.00	350.00
1	REAR BOOT LOGO (WCP)	NECESSARY	35.00	35.00
1	REAR BOOT OUTER CENTRE MOULDING (WCP)	WARPED	90.00	90.00
1	REAR BOOT EMBLEM - COROLLA (WCP)	NECESSARY	25.00	25.00
1	REAR BOOT EMBLEM -ALTIS (WCP)	NECESSARY	25.00	25.00
1	REAR BOOT INNER LOCK (WCP)	DENTED	145.00	145.00
1	REAR END PANEL (WCP)	TO REPAIR SEE LABOUR	200.00	-
1	REAR NUMBER PLATE LAMP HOLDER (WCP) (ADDITIONAL)	DENTED	105.00	105.00
2	TAILLAMP SIDE GARNISH @\$20.00 (WCP) (ADDITIONAL)	CUT	40.00	40.00
	COST PLUS 15%		260.55	155.55
			1,997.55	1,192.55
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REVERSE CAMERA (SN)	DENTED	350.00	350.00
			550.00	550.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT,CUT, WELD AND RENEW REAR ANEL AND RE-ALIGN TO SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		700.00	600.00
	TO PUTTY AND RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOOT & REAR COMPARTMENT.		700.00	650.00
	TO REMOVE AND REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND REST SYSTEM.		50.00	50.00
	RUSTPROOFING.		30.00	30.00
			1,480.00	1,330.00
<b>GRAND TOTAL</b>			<b>4,027.55</b>	<b>3,072.55</b>

Report Ref No. CS/GAI23003808/Kqy3m4



RECOMMENDED COST OF REPAIRS			<b>3,072.55</b>
-----------------------------	--	--	-----------------

Report Ref No. CS/GAI23003808/Kqy3m4

A handwritten signature in black ink, appearing to be 'KSC'.

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.