

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: 68046037 FAX: 62353354
ATTN: Motor Claim Department

Claim No: ES2300391

Date: 13 Apr 2023

Policy No:

Veh Reg No: SMV1206Y

Make/Model: TOYOTA TOYOTA
COROLLA STANDARD

Chassis No: MR2BE3BE500010990

Engine No:

Reg. Date: 3072.55

WS Ref: TP GA
Claim Type: Third Party
Accident Date: 11/04/2023
TP Veh Reg No: YP9452P

Not attached

Recovery B4 party

5 days

Estimate Repair Cost to Vehicle No : SMV1206Y

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 REAR BUMPER ✓	210.00	1 PC	210.00	—
2 REAR BUMPER CLIP ✓	2.00	6 PCS	12.00	—
3 TAILLAMP X	250.00	2 PCS	500.00	—
4 REAR BOOT ✓	350.00	1 PC	350.00	—
5 REAR BOOT LOGO ✓	35.00	1 PC	35.00	—
6 REAR BOOT OUTER CENTRE MOULDING ✓	90.00	1 PC	90.00	—
7 REAR BOOT EMBLEM - COROLLA ✓	25.00	1 PC	25.00	—
8 REAR BOOT EMBLEM - ALTIS ✓	25.00	1 PC	25.00	—
9 REAR BOOT INNER LOCK ✓	145.00	1 PC	145.00	—
10 REAR END PANEL R	200.00	1 PC	200.00	—
			1,592.00	—
	Add 15%		238.80	1,830.80
Special Net				
11 REVERSE CAMERA sensor ✓	0.00	1 PC	200.0000	—
12 REVERSE CAMERA 7	0.00	1 PC	350.0000	—
				550.00
Labour				
13 TO REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT, CUT, WELD AND RENEW REAR PANEL AND RE-ALIGN TO SAME	0.00	1 LA	700.0000	600
14 TO PUTTY AND RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOOT & REAR COMPARTMENT	0.00	1 LA	700.0000	650
15 TO REMOVE AND REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND REST SYSTEM	0.00	1 LA	50.0000	—
16 RUSTPROOFING	0.00	1 LA	30.0000	—
				1,480.00

Supp: 1m rear no plate lamp holder \$105
2m tail lamp side garnish \$20x22 \$40
\$145

Parts \$892
Supp \$145
\$1037
15% \$155.55
\$1181.55
1330
\$3072.50

Total S\$ 3,860.80
Add GST @ 8% 308.86
Total Amount payable S\$ 4,169.66

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: 68046037 FAX: 62353354
ATTN: Motor Claim Department

Claim No: ES2300391
Estimate No: ES2300391/WS
Date: 14 Apr 2023
Policy No:
Veh Reg No: SMV1206Y
Make/Model: TOYOTA TOYOTA
COROLLA STANDARD
Chassis No: MR2BE3BE500010990
Engine No:
Reg. Date:

WS Ref: TP GA
Claim Type: Third Party
Accident Date: 11/04/2023
TP Veh Reg No: YP9452P

Estimate Repair Cost to Vehicle No : SMV1206Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 REAR NUMBER PLATE LAMP HOLDER	105.00	1 PC	105.00	✓
2 TAILLAMP SIDE GARNISH	20.00	2 PC	40.00	✓
			145.00	
	Add 15%		21.75	166.75
Total				S\$ 166.75
GST Amount				S\$ 13.34
Total Amount payable				<u>S\$ 180.09</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE