



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 7925C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	BENT	879.00	581.00
1	FRT BUMPER SIDE RETAINER LH	CRACKED	45.00	45.00
1	FRT BUMPER BRACKET LH	NOT NECESSARY	52.00	-
1	FRT BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	189.00	-
1	FRT BUMPER GRILLE	NOT NECESSARY	212.00	-
1	FRT BUMPER FOGLAMP COVER LH	NOT NECESSARY	124.00	-
1	FRT BUMPER FOGLAMP LH	NOT NECESSARY	358.00	-
1	FRT HEADLAMP LH	CRACKED	2,159.00	1,588.00
1	FRT HEADLAMP LOWER BRACKET LH	NOT NECESSARY	75.00	-
1	FRONT FENDER LH	DENTED	698.00	577.10
1	FRONT FENDER COWLING LH	NOT NECESSARY	159.00	-
1	FRONT FENDER EMBLEM HYBRID	NECESSARY	62.00	62.00
1	FRT SHOCKABSORBER LH	NOT NECESSARY	452.00	-
1	FRT LOWER ARM LH	NOT NECESSARY	581.00	-
1	FRT KNUCKLE ARM LH	NOT NECESSARY	587.00	-
1	FRT WHEEL BEARING LH	NOT NECESSARY	198.00	-
	LESS 25% DISCOUNT		-1,707.50	-713.28
			5,122.50	2,139.82
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT BUMPER CLIP (SN)	NECESSARY	50.00	20.00
1	FRT FENDER INNERSHIRED CLIP SET LH (SN)	NOT NECESSARY	50.00	-
1	FRONT RIM LH (SN)	NOT NECESSARY	800.00	-
1	FRT TYRE LH (SN)	NOT NECESSARY	250.00	-
			1,150.00	20.00
<u>LABOUR</u>				
	CHECK WIRING.		100.00	20.00
	R+R FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	WHEEL ALIGNMENT.		100.00	40.00
	RESET TROUBLE CODE.	NOT NECESSARY	400.00	-
	REALIGN HEADLAMP.		120.00	20.00

Report Ref No. CS/LIP23003814/Wqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	KNOCK.		800.00	300.00
	SPRAY.		800.00	400.00
			2,670.00	780.00
GRAND TOTAL			8,942.50	2,939.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/LIP23003814/Wqy3m4

MARKET VALUE: \$163,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$98,913.00=NETT VALUE: \$64,087.00

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.