



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23003814/Wqy3m4 Date: 09/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 8105J	Veh. Inspected	SNH 7925C
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS23/0709	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	13/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MR2BZ3BE300010779	Colour	GREY
	Odometer	13419 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/04/2023	Inspection Date	13/04/2023
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)REGISTRATION DATE: 28 NOV 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	