

ASS. REC. BY:

REF:

AGZ/ 230038261KV

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJY 6037E

Policy No.

Claims No. C10021654/JY

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

23488/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

S/HF 759T

Yr Regn:

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Perant Latitude

c.c

1995

Colour

m White/Red

A/C:

Insured / Std / NI / NA

Sp. Reading

607841

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL 15AUC 283369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/4/23

D.O.I.

13/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time, File Return to?

18/4/23-typist

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / L.B. (\$) 4150

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHF759T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Apr 2023
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003269
Chassis No.:	VF1ABL15AUC283369
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2024
PARF Rebate Amount:	\$12,998.00

Intended COE Rebate Details

COE Expiry Date:	29 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$5,626.00
Total Rebate Amount:	\$18,624.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Apr 2023

OK

Not Authorised
L1 By \$4150/h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF759T

AAD2304-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF759T

VF1ABL15AUC283369

200303878K

RENAULT

LATITUDE

12/4/2023

SJY6037E/AUTO GEN

30/6/2016

13 APR 2023

PART		LIST
1 BUMPER COVER FRT	\$	B ₁ 747.20 ✓
1 BUMPER SPOILER FRT	\$	D ₁ 344.70 ✓
1 BUMPER BRACKET KIT FRT RH	\$	S ₁ 101.40 X
1 BUMPER RETAINER FRT RH	\$	CM 101.40 ✓
1 BUMPER FOG LAMP GRILLE RH	\$	M ₁ 207.21 ✓
1 RADIATOR GRILLE	\$	P ₁ 969.90 X
1 RADIATOR GRILLE FRAME	\$	S ₁ 686.00 X
1 FRAME FULL SUPPORT PANEL	\$	S ₁ 592.70 X
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$	CM 116.47 ✓
1 BONNET	\$	B ₁ 1,312.70 ✓
1 BONNET HINGE LH	\$	R 237.40 X
1 BONNET HINGE RH	\$	R 237.40 X
1 BONNET LOCK	\$	R 152.80 X
1 FENDER PANEL FRT RH	\$	B ₁ 437.10 ✓
1 WHEELARCH FRT RH	\$	M ₁ 191.40 ✓
1 WIPER RESERVOIR	\$	nd 179.60 ✓
1 HEADLAMP RH	\$	B ₁ 743.60 ✓
	\$	7,358.98
10%	\$	735.90
	\$	6,623.08

Special Nett

1 FRONT BUMPER CLIP	\$	ne 66.00 ✓
1 FENDER LINER CLIP	\$	ne 65.00 ✓
TOTAL	\$	131.00
TOTAL PARTS	\$	6,754.08

Trans-cab Auto Services Pte Ltd**AAD2304-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF759T**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6601 44 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 4001
To Rust-Proofing Of The Affected Areas.	\$	170.00 601
To check steering geometry and computer wheel alignment	\$	220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
TOTAL	\$	6,560.00

Over All Total \$ 19,937.16**(LUMP SUM)****Repair Days**~~05 DAYS~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: