

ASS. REC. BY:

REF:

AGZ/ 230038261KV

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHF 759T

Yr Regn: _____

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Perant. Latitude

C.C

1995

Colour _____

m White/Red

A/C:

Insured / Std / NI / NA

Sp. Reading _____

607841

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VF1ABL 15AUC 283369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Firm 89

Front

R/Bal. _____

7

mm

Rear

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

12/4/23

D.O.I. _____

13/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA not ready

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation

S - RS - SI

Firms

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authorised
Library

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF759T

AAD2304-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

13 APR 2023

SHF759T

VF1ABL15AUC283369

200303878K

RENAULT

LATITUDE

12/4/2023

SJY6037E/AUTO GEN

30/6/2016

PART	LIST
1 BUMPER COVER FRT	\$ R 747.20 ✓
1 BUMPER SPOILER FRT	\$ D 344.70 ✓
1 BUMPER BRACKET KIT FRT RH	\$ PL 101.40 X
1 BUMPER RETAINER FRT RH	\$ CM 101.40 ✓
1 BUMPER FOG LAMP GRILLE RH	\$ M 207.21 ✓
1 RADIATOR GRILLE	\$ PL 969.90 X
1 RADIATOR GRILLE FRAME	\$ PL 686.00 X
1 FRAME FULL SUPPORT PANEL	\$ PL 592.70 X
1 BUMPER BRACKET FRT RH (Headlamp Lower)	\$ CM 116.47 ✓
1 BONNET	\$ R 1,312.70 ✓
1 BONNET HINGE LH	\$ R 237.40 X
1 BONNET HINGE RH	\$ R 237.40 X
1 BONNET LOCK	\$ R 152.80 X
1 FENDER PANEL FRT RH	\$ B 437.10 ✓
1 WHEELARCH FRT RH	\$ M 191.40 ✓
1 WIPER RESERVOIR	\$ R 179.60 ✓
1 HEADLAMP RH	\$ R 743.60 ✓
	\$ 7,358.98
	10% \$ 735.90
	\$ 6,623.08

Special Nett

1 FRONT BUMPER CLIP	\$ R 66.00 ✓
1 FENDER LINER CLIP	\$ R 65.00 ✓
TOTAL	\$ 131.00
TOTAL PARTS	\$ 6,754.08

Trans-cab Auto Services Pte Ltd

AAD2304-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF759T

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6601 404 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 4001
To Rust-Proofing Of The Affected Areas.	\$	170.00 601
To check steering geometry and computer wheel alignment	\$	220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
TOTAL	\$	6,560.00

Over All Total	\$	19,937.16
-----------------------	-----------	------------------

(LUMP SUM)**Repair Days****05 DAYS****3 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHF759T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Apr 2023
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003269
Chassis No.:	VF1ABL15AUC283369
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2024
PARF Rebate Amount:	\$12,998.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$5,626.00
Total Rebate Amount:	\$18,624.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Apr 2023

OK