

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SMN1771Z 2019 JULY
VEHICLE MODEL : MINI ONE
CHASSIS NO : WMWXU520002L02211

TP Budget Direct
Hui Rong

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR <i>Defect</i>	1	\$ 1,345.00	\$ 1,345.00
2	FRONT DOOR LOCK <i>Defect</i>	1	\$ 398.00	\$ 398.00
3	FRONT DOOR WEATHERSTRIPE <i>new</i>	1	\$ 295.00	\$ 295.00
4	FRONT DOOR OUTER HANDLE <i>the new</i>	1	\$ 242.00	\$ 242.00
5	FRO DOOR INNER TRIM BOARD <i>Defect</i>	1	\$ 841.00	\$ 841.00
6	FRONT DOOR GLASS REGULATOR GEAR <i>new</i>	1	\$ 298.00	\$ 298.00
7	FRONT DOOR GLASS REGULATOR MOTOR <i>new</i> Dmg	1	\$ 409.00	\$ 409.00
8	FRONT DOOR GLASS OUTER CHROME MOULDING <i>new</i>	1	\$ 132.00	\$ 132.00
9	FRONT DOOR WING MIRROR <i>lit</i>	1	\$ 1,140.00	\$ 1,140.00
10	FRONT DOOR WING MIRROR GLASS <i>new</i>	1	\$ 281.00	\$ 281.00
11	FRONT DOOR WING MIRROR COVER <i>new</i>	1	\$ 98.00	\$ 98.00
12	FRONT FENDER <i>Defect</i>	1	\$ 781.00	\$ 781.00
13	FRONT FENDER ARC GARNISH <i>lit</i>	1	\$ 212.00	\$ 212.00
14	FRONT FENDER INNER SHIELD <i>the new</i>	1	\$ 188.00	\$ 188.00
15	FRONT FENDER SIGNAL LAMP <i>3AL</i>	1	\$ 59.00	\$ 59.00
16	FRONT FENDER SIGNAL LAMP GARNISH <i>for</i>	1	\$ 38.00	\$ 38.00
17	FRONT FENDER TOP CHROME MOULDING <i>new</i>	1	\$ 71.00	\$ 71.00
18	ROCKER PANEL OUTER GARNISH <i>Defect</i>	1	\$ 694.00	\$ 694.00
19	FRONT WHEEL RIM <i>lit</i>	1	\$ 1,195.00	\$ 1,195.00
20	FRONT LOWER ARM <i>2</i>	1	\$ 494.00	\$ 494.00
21	FRONT SHOCK ABSORBER <i>3AL</i>	1	\$ 389.00	\$ 389.00
22	FRONT KNUCKLE ARM <i>new</i>	1	\$ 745.00	\$ 745.00
23	FRONT WHEEL HUB	1	\$ 388.00	\$ 388.00
24	FRONT WHEEL HUB BEARING	1	\$ 179.00	\$ 179.00

TOTAL PRICE: \$ 10,912.00
LESS 10% \$ 1,091.20
SUB TOTAL PRICE: \$ 9,820.80

6437
5793.30
S.N. 600

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT DOOR INNER TRIM BOARD CLIPS <i>3AL</i>	1 SET	\$ 50.00	\$ 50.00
2	FRONT FENDER ARC GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
3	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	ROCKER PANEL OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
5	FRONT TYRE <i>new</i>	1	\$ 250.00	\$ 250.00

TOTAL: \$ 410.00

90

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	400	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	50	
5	TO RTRANSFER DOOR FITTINGS	\$ 150.00	60	
6	TO REMOVE FRONT UNDERCARRIAGE	\$ 350.00	X	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	
8	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	X	
TOTAL:		\$ 2,850.00		

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,230.80

TOTAL LABOUR COST: \$ 2,850.00

TOTAL REPAIR COST: \$ 13,080.80

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

Total: 7603.30

w/s: 6K

05 Days

(6K)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: