

(08/13/13) web

ASS. REC. BY: Rene

REF:

CS/FU123003830/Rqy3

601N

08-2024/NOV

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: YN 6975Cat Workshop m/s CYCLE & CARRIAGEof 299, PANDORA GARDEN

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

20K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YN 6975C

Yr Regn:

2014 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ SPRINTER1.9c 2143

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

354743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDB9066532.5921651

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim. or

Tyre Size:

F:

195/75R16

R:

12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

31/03/23

D.O.I.

18/04/23

Survey held at

CYCLE CP67

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 10K

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR YN6975C*4C-E

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 16387
Reg No/Reg Date YN6975C*4C-EO/ 26/11/2014
Date In/Mileage / 0
Chassis No WDB9066532S921651
Engine No 65195509485263
Make/Model MBCV/516CDI/3665 Spr
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	12/04/2023/ 16:38		610 / Philip Cheong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 00940101 TO REMOVE, REPLACE WELD & REPAIR FRONT DAMAGED PARTS				2700.00
A 00940101 To remove and refit radiator assy				360.00
A 00940101 To remove and refit air con condertion ,top up gas				840.00
A 00940101 To remove and refit radiator fan & air con fan				720.00
A 00940101 To numbering sticker				1600.00
A 00940101 To spray painting				1920.00
A 00940101 1 pc handlamp caver				840.00
M BLINKER LAMP	1.00	114.17	00.00	114.17
M CROSS MEMBER	1.00	1022.71	00.00	1022.71
M BRACING	1.00	20.86	00.00	20.86
M BRACING	1.00	24.47	00.00	24.47
M HEADLAMP	1.00	909.13	00.00	909.13
M BEAM	1.00	326.52	00.00	326.52
M BUMPER FRT	1.00	1031.07	00.00	1031.07
M FRONT FENDER	1.00	533.50	00.00	533.50
M BRACKET	1.00	41.50	00.00	41.50
M EDGE PROTECTION	1.00	14.07	00.00	14.07
M BRACKET	1.00	41.50	00.00	41.50

ESTIMATE

4 days

P/P

18/04/23

@0945

EXCESS: 250

Revert

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer
Signature:

Authorized signatory and company stamp

Nett 13,499.50
8% GST on 13499.50 1079.96

Total Payable 14,579.46

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Company

Owner ID: 601N

Vehicle No.: YN6975C

Vehicle to be Exported: No

Intended Deregistration Date: 19 Apr 2023

Vehicle Make: MERCEDES BENZ

Vehicle Model: SPRINTER 516CDI 3665 HIGH ROOF A/T ABS

Primary Colour: White

Manufacturing Year: 2014

Engine No.: 65195533485263

Chassis No.: WDB9066532S921651

Maximum Power Output: -

Open Market Value: \$55,273.00

Original Registration Date: 26 Nov 2014

First Registration Date: 26 Nov 2014

Transfer Count: 0

Actual ARF Paid: \$2,764.00

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

COE Expiry Date: 25 Nov 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$61,000.00

COE Rebate Amount: \$9,760.00

Total Rebate Amount: \$9,760.00

The information contained herein is correct as at 19 Apr 2023

OK