



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 8259X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|-----------------------------------|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 50.00 | 20.00 |
| 1 | REAR BUMPER (SN) | DEFORMED | 1,865.00 | 1,865.00 |
| 1 | BUMPER SKIRT (SN) | DEFORMED | 940.00 | 940.00 |
| 1 | SET BRACKET (SN) | NECESSARY | 181.00 | 181.00 |
| 1 | BUMPER MOULDING (SN) | NOT NECESSARY | 685.00 | - |
| 1 | BUMPER BRACKET (SN) | NOT NECESSARY | 268.00 | - |
| 1 | BUMPER BRACKET LH (SN) | NOT NECESSARY | 186.00 | - |
| 1 | FIX STIFFENER L (SN) | NOT NECESSARY | 220.00 | - |
| 1 | BUMPER ABSORBER (SN) | NOT NECESSARY | 833.00 | - |
| 1 | FIXING STUD (SN) | NECESSARY | 51.00 | 51.00 |
| 1 | BADGE (SN) | NECESSARY | 94.00 | 94.00 |
| 1 | BRAND EMBLEM (CITROEN) (SN) | NECESSARY | 91.00 | 91.00 |
| 1 | BRAND EMBLEM (LOGO) (SN) | NECESSARY | 91.00 | 91.00 |
| 1 | TAILGATE LIGHT LH (SN) | NOT NECESSARY | 432.00 | - |
| 1 | FINISHER BUMPER (SN) (ADDITIONAL) | DEFORMED | 155.00 | 155.00 |
| | | | 6,142.00 | 3,488.00 |
| <u>LABOUR</u> | | | | |
| REPLACE REAR BUMPER, REAR BUMPER LOWER, REAR LH TAILLAMP & AFFECTED REPAIR ON TAILGATE & END PANEL. | | | 3,040.00 | 1,140.00 |
| PAINT WORK ON REAR BUMPER, TAILGATE & END PANEL. | | | 2,200.00 | 1,100.00 |
| REMOVE & INSTALL REAR PARKING ASSISTS FOR FACILITATE REPAIR. | | | 150.00 | 80.00 |
| REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR. | | NOT NECESSARY | 200.00 | - |
| TO APPLY SEALANT ON AFFECTED AREA. | | NOT NECESSARY | 160.00 | - |
| PERFORM RUST PREVENTION. | | NOT NECESSARY | 80.00 | - |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM. | | | 150.00 | 60.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|-----------|---------------------------|-------------------|
| | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM. | | 380.00 | 380.00 |
| | | | 6,360.00 | 2,760.00 |
| GRAND TOTAL | | | 12,502.00 | 6,248.00 |
| RECOMMENDED COST OF REPAIRS | | | | 6,248.00 |

Report Ref No. CS/UOI23003831/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.