



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
CHER LEW CHYE		Cust No/Name /CHER LEW CHYE	
BLK 810 YISHUN RING ROAD		Reg No/Reg Date SNF8259X / 24/06/2022	
#13-4191		Date In/Mileage / 0	
SINGAPORE 760810		Chassis No VR7ARHNSSLN012715	
Contact No Mobile: 92395039		Engine No 10XVDV1908237	
		Make/Model CIT/C5 AIRCROSS 1.2	
		Colour/Trim POW POLAR WHITE / S/ 51F SILICA GREY CL	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	12/04/2023/ 12:29	TLK	282 / Kevin Leong	20197

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPALCE REAR BUMPER, REAR BUMPER LOWER, REAR LH TAILLAMP & AFFECTED 760 REPAIR ON TAILGATE & END PANEL				✓ 1140 3040.00
E PNT98000 PAINT WORK ON REAR BUMPER, TAILGATE & END PANEL 550				✓ 1100 2200.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSISTS FOR FACILITATE REPAIR				✓ 80 150.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				x 200.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				x 160.00
M SUNDRY PERFORM RUST PREVENTION				x 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 60 150.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				✓ 4 ✓ 380.00
M SUNDRY SUNDRIES				✓ 20 50.00
M REAR BUMPER	1.00	1865.00	0.00	de 1865.00 ✓
M BUMPER SKIRT	1.00	940.00	0.00	de 940.00 ✓
M BRACKET SET	1.00	181.00	0.00	re 181.00 ✓
M BUMPER MOULDING	1.00	685.00	0.00	re 685.00 x
M BUMPER BRACKET	1.00	268.00	0.00	re 268.00 x
M BUMPER BRACKET LH	1.00	186.00	0.00	re 186.00 x
M FIX STIFFENER L	1.00	220.00	0.00	re 220.00 x
M BUMPER ABSORBER	1.00	833.00	0.00	re 833.00 x
M FIXING STUD	1.00	51.00	0.00	re 51.00 ✓
M BADGE	1.00	94.00	0.00	re 94.00 ✓
M BRAND EMBLEM (CITROEN)	1.00	91.00	0.00	re 91.00 ✓
M BRAND EMBLEM (LOGO)	1.00	91.00	0.00	re 91.00 ✓
M TAILGATE LIGHT LH	1.00	432.00	0.00	re 432.00 ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by

Tan Jia Min 97445749/62563561
 WP 15/5/23 0320pm
 Plp Resurvey before paint 4-5 days

Authorized signatory and company stamp

Parts	5,937.00
Labour	6,120.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	290.00
Total (w/o GST)	12,347.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring removal of the windscreen.



Exceptional Journeys

INSURANCE CO.: UOI

Supplementary Parts For Registration No.: SNF 8259 X

<u>Materials</u>		<u>Cost (\$)</u>
1	Finisher bumper	155.00 <i>de</i>
Total		155.00
8% GST		12.40
Grand total		<u>\$ 167.40</u>

Thank You.

Yours faithfully

[Signature]
LOI AI TING
SENIOR OFFICER-ADMIN
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240