



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SMP6177X

VOLKSWAGEN NEW GOLF

WVWZZZ1KZ9W468216

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR NUMBER PLATE LAMP @62 <i>crackd</i>		124.00	/
2	REAR BUMPER <i>Distorted</i>		1198.00	/
3	REAR BUMPER SIDE HOLDER @75 <i>RH and</i>		150.00	75
4	REAR BUMPER REINFORCEMENT <i>Dented</i>		498.00	/
5	REAR BUMPER SIDE REFLECTOR @65 <i>LH crackd</i>		170.00	65
6	REAR BUMPER CENTRE GUIDE <i>crackd</i>		198.00	/
7	REAR BUMPER LOWER GARNISH <i>Dented</i>		401.00	/
8	REVERSE SENSOR @260 <i>2 pieces damaged</i>		1040.00	520
9	REVERSE SENSOR HOLDER @25 <i>new</i>		100.00	/
10	REVERSE SENSOR WIRE HARNESS <i>snapped</i>		368.00	/
11	REAR END PANEL <i>Dented</i>		971.00	/
12	REAR END PANEL TOP GARNISH <i>crackd</i>		245.00	/
13	TAILLAMP @602 <i>LH crackd</i>		1204.00	602
14	TAILLAMP LOWER BRACKET @73 <i>LH crackd</i>		146.00	73
15	TAILLAMP LPANEL @215 <i>LH Dented</i>		430.00	215
16	TAILGATE <i>Distorted</i>		1495.00	-
17	TAILGATE LOCK <i>and</i>		268.00	/
18	TAILGATE WEATHERSTRIPE <i>cut</i>		296.00	/
19	TAILGATE REFLECTOR @441 <i>LH crackd</i>		882.00	441
20	TAILGATE INNER TRIM BOARD UPPER <i>new</i>		279.00	+
21	TAILGATE INNER TRIM BOARD LOWER <i>crackd</i>		485.00	/
22	TAILGTE WIPER MOTOR <i>new</i>		525.00	+
23	TAILGATE GLASS MOULDING <i>new</i>		169.00	/
24	VOLKSWAGEN LOGO <i>and</i>		110.00	/
25	REAR LH FENDER <i>Buckled</i>		1499.00	/
26	REAR FENDER INNER TRIM BOARD @359 <i>LH crackd</i>		718.00	359
27	REAR FENDER INNER SHIELD @210 <i>LH torn</i>		420.00	210
28	SPARE TYRE PANEL <i>Regis</i>		1368.00	+
29	SPARE TYRE PANEL TOP COVER <i>Dented</i>		328.00	/
30	SPARE TYRE PANEL SIDE SPONGE @302 <i>Dented</i>		604.00	/
31	REAR EXHAUST PIPE <i>Bent</i>		1166.00	/
32	RAER EXHAUST PIPE MOUNTING <i>new</i>		39.00	+
33	REAR EXHAUST PIPE GASKET <i>new</i>		36.00	/
			17930.00	
less 10%			1793.00	10%
			16137.00	
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE <i>crackd</i>		30.00	/
2	REAR NUMBER PLATE HOLDER <i>new</i>		30.00	+
3	REAR BUMPER CLIPS <i>new</i>		50.00	30
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		20.00	/
5	REAR END PANEL SEALANT <i>new</i>		60.00	/
6	TAILGATE SEALANT <i>new</i>		60.00	/
7	TAILGATE INNER TRIM BOARD UPPER CLIPS <i>new</i>		30.00	20
8	TAILGATE INNER TRIM BOARD LOWER CLIPS <i>new</i>		30.00	/

9	TAILGATE GLASS SEALANT	3 per	60.00	✓
10	MONSTER TUNE EMBLEM		80.00	✓
11	REAR CAMERA	2 1 per new	480.00	X
12	REAR LH FENDER SEALANT	1 per new	60.00	X
13	REAR FENDER INNER TRIM CLIPS	new	60.00	30
14	REAR FENDER INNER SHIELD CLIPS	new	60.00	20
15	SPARE TYRE PANEL INSULATION PAD	new	280.00	X
Total Parts			1390.00	

440



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SMP6177X

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	LABOUR		
1	PANEL BEATING	2000.00 1200	
2	SPRAY PAINTING	1600.00 1000	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	150.00 100	
5	TO REMOVE UPHOLSTERY & REAR SEAT	280.00 80	
12	TO TRANSFER TAILGATE FITTINGS	150.00 80	
13	TO REMOVE TAILGATE GLASS	180.00 120	
14	TO REMOVE REVERSE SENSOR	100.00 50	
15	TO REMOVE REAR CAMERA	100.00 50	
16	TO REMOVE REAR VIDEO CAMERA	100.00 50	
17	TO PERFORM DIAGNOSTIC TEST	200.00 +	
18	TO REMOVE REAR EXHAUST PIPE	150.00 80	
	Labour Total :	5110.00	
TOTAL (PARTS & LABOUR):		22637.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

h/s 13/04/23

09 Days

total 15069.10

L/s 12K