



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003833/Uqy3q2	
			Date: 10/05/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SDP 5431A	<b>Veh. Inspected</b>	SKB 305E
	<b>Policy No.</b>	D23MTPV01003862	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2301444/THE	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	BETTY WONG	<b>Assign Date</b>	13/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA VIOS E (A)	<b>c.c</b>	1497
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
	<b>Chassis No.</b>	MR053HY9305170029	<b>Colour</b>	BLUE
	<b>Odometer</b>	115522 KM	<b>Steering</b>	AFFECTED
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	185/60 R15	FIRENZA	6 mm
	<b>L/H Front Tyre</b>	185/60 R15	FIRENZA	6 mm
	<b>R/H Rear Tyre</b>	185/60 R15	WINDFORCE	6 mm
	<b>L/H Rear Tyre</b>	185/60 R15	WINDFORCE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	12/04/2023	<b>Inspection Date</b>	14/04/2023
	<b>Survey held at</b>	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>12 Working Days</b>	