



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: HO WINNIE			Ref: CS/HSB23003844/Unp3m4 Date: 07/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7220A	Veh. Inspected	SNF 9276P	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S3M04LGD	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	13/04/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	GK82202841	Colour	BLUE	
Odometer	23890 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60R15	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/04/2023	Inspection Date	17/04/2023	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	