

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23003846/UYA3Q2**Date:** 07/07/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001678642
Claimant Vehicle No :	FBM7540U	Insured Vehicle No :	SFV80G
Date of Loss:	08/04/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM7540U	Engine No:	KC32E0002652
Make & Model:	HONDA CB150R, 149cc	Chassis No:	MLHKC2888J5002652
Reg. Date:	15/03/2018 (Man. Year: 2017)	Odometer:	42329 km
Colour:	Black		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	150/60-17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,150.00	2,129.00	2,021.00	48.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	340.00	500.00	59.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,990.00	2,469.00	2,521.00	50.52
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	4,990.00	1,900.00	3,090.00	61.92
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	13/04/2023		
Date Inspected:	13/04/2023	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 07 Jul 2023)	
Parts:	N/A	HONDA CB150R 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM7540U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	175.00 FL	*150.00 FL
2	1		*HANDLE -BAR	Bent	280.00 FL	*280.00 FL
3	1		*HANDLE -BAR ENDS	N/S Cut	90.00 FL	*40.00 FL
4	1		*SET HAND GRIPS	Cut	80.00 FL	*80.00 FL
5	1		*CLUTCH LEVER	Cut	135.00 FL	*135.00 FL
6	1		*FRONT SIGNAL -L/H	Cut	165.00 FL	*165.00 FL
7	1		*FRONT SIDE MIRROR -L/H	Cut	190.00 FL	*160.00 FL
8	1		*FRONT FOOTREST -L/H	Cut	195.00 FL	*110.00 FL
9	1		*FRONT FOOTREST BRACKET -L/H	Not Necessary	280.00 FL	*- FL
10	1		*GEAR PEDAL	Cut	195.00 FL	*150.00 FL
11	1		*REAR FOOTREST -L/H	Cut	170.00 FL	*110.00 FL
12	1		*REAR FOOTREST BRACKET	Not Necessary	280.00 FL	*- FL
13	1		*REAR RIM SHAFT	Cut	180.00 FL	*180.00 FL
14	1		*SIDE STAND	Repair	175.00 FL	*- FL
15	1		*SET REAR NUMBER PLATE	Bent	38.00 FS	*15.00 FS
16	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
17	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
18	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
19	1		*ERP I.U	Serviceable	180.00 FS	*- FS
20	1		*FRONT RIM SLIDER	Cut	280.00 FS	*110.00 FS
21	1		*ENGINE SLIDER	Cut	380.00 FS	*150.00 FS
22	1		*REAR BOX	Cut	580.00 FS	*450.00 FS
23	1		*REAR BOX BRACKET	Serviceable	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,409.00	2,285.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	259.00	156.00
Total Parts (\$\$)	4,150.00	2,129.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REPAIR FORK ASSY	New	280.00	60.00
3	TO PROVIDE LABOUR	New	480.00	280.00
			Gross Labour Cost (S\$)	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >