

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd

22 Gemmill Lane
 Singapore 069257
 Tel : 6223 - 9433
 Fax : 6224 - 3903

Xiao Chen

Quotation

DATE : 02.05.2023
 VEH NO : SLT4167D
 MODEL : Mazda 5
 D O A : 11.04.2023
 YR REF : GBC7455K

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLT4167D (MAZDA 5)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>RH cruld</i>	2	115.20 <i>57.60</i>
2	Rear Bumper <i>Distorted</i>	1	962.40 ✓
3	Rear Bumper Side Holder - LH & RH <i>Dist</i>	2	96.20 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	130.20 ✗
5	Rear Bumper Beam <i>Bent</i>	1	237.40 ✓
6	Rear End Panel <i>Dented</i>	1	542.30 ✓
7	Rear End Panel Top Garnish <i>Distorted</i>	1	181.20 ✓
8	Tail Lamp - LH & RH <i>ut</i>	2	1,186.80 ✓
9	Tailgate <i>Distorted</i>	1	1,637.00 ✓
10	Tailgate Lock <i>Dist</i>	1	286.90 ✓
11	Tailgate Weatherstripe <i>ut</i>	1	295.40 ✓
12	Tailgate Outer Garnish <i>Missing</i>	1	459.40 ✓
13	Tailgate Reflector - LH & RH <i>cruld</i>	2	818.40 ✓
14	Tailgate Inner Trim Board <i>Distorted</i>	1	432.80 ✓
15	Tailgate Damper - LH & RH <i>new</i>	2	559.00 ✗
16	Tailgate Hinges - LH & RH <i>new</i>	2	89.80 ✗
17	Tailgate Lock Switch <i>Dist</i>	1	248.20 ✓
18	Tailgate Wiper Motor <i>new</i>	1	365.40 ✗
19	Tailgate Glass Moulding <i>new</i>	1	168.20 ✓
20	Mazda Logo <i>missing</i>	1	48.90 ✓
21	Mazda 5 Wording <i>new</i>	1	49.60 ✓
22	Emblem <i>new</i>	1	49.10 ✓
23	Rear Fender Inner Trim Board - LH & RH <i>new</i>	2	1,091.60 ✗
24	Spare Tyre Panel <i>Repair</i>	1	1,181.40 ✗
25	Spare Tyre Panel Top Board <i>Distorted</i>	1	389.50 ✓
26	Tools Tray <i>cruld</i>	1	404.80 ✓
27	Rear Exhaust Pipe <i>new</i>	1	1,109.20 ✗
28	Rear Exhaust Mounting <i>new</i>	1	38.90 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SLT4167D (MAZDA 5)

Grand Total

\$ 16,648.48

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 9771.68

4/s: 7-8k

08 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: