

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0371/2023/EQ
DATE : 13-Apr-23
WIP : 15426

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : GBJ 3592 L**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR HOO POH SAN KELVIN
ADDRESS : 49 HINDHEDE WALK
#10-08
SINGAPORE 587976
TELEPHONE : HP +65 91762854
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ22-004082
VEHICLE NO : **SLP 3560 D**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 31/5/2017
ENGINE NO : CYG 016746
CHASSIS NO : WAUZZZ4G1HN044125
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Apr-23
PLACE OF ACCIDENT : NEWTON FLYOVER, SLOW TRAFFIC

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 3560 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500	
3	TO RESPRAY REAR BUMPER.	\$	1,000.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 3560 D

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$	3,677.00	<i>+</i>
2	REAR BUMPER FIXING PARTS <i>Not m</i>	1	\$	301.00	<i>X</i>
3	REAR BUMPER SPOILER <i>Not m</i>	1	\$	565.00	<i>X</i>
4	REAR BUMPER SECURING STRIP <i>Not m</i>	1	\$	264.00	<i>X</i>
5	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$	190.00	<i>X</i>
6	REAR BUMPER REINFORCEMENT BEAM	1	\$	1,140.00	<i>X</i>
7	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$	34.00	<i>X</i>
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	78.00	<i>+</i>
9	REAR BUMPER GUIDE SECTION - CENTER	1	\$	126.00	<i>+</i>
10	REAR BUMPER HOLDING STRAP - LH / RH	2	\$	152.00	<i>+</i>
11	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$	158.00	<i>+</i>
12	REAR PARKING AID SENSOR - INNER / OUTER	2	\$	543.00	<i>X</i>
13	REAR PARKING AID SEAL RING <i>Not m</i>	4	\$	6.00	<i>+</i>
14	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$	1,300.00	<i>+</i>
15	SUNDRIES <i>?</i>		\$	400.00	<i>?</i>
TOTAL SPARE PARTS			:	\$	8,934.00
TOTAL LABOUR CHARGES			:	\$	2,752.00
GRAND TOTAL			:	\$	11,686.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *20/04/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT