

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0371/2023/EQ
DATE : 13-Apr-23
WIP : 15426

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : GBJ 3592 L**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR HOO POH SAN KELVIN
ADDRESS : 49 HINDHEDE WALK
#10-08
SINGAPORE 587976
TELEPHONE : HP +65 91762854
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ22-004082
VEHICLE NO : **SLP 3560 D**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 31/5/2017
ENGINE NO : CYG 016746
CHASSIS NO : WAUZZZ4G1HN044125
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Apr-23
PLACE OF ACCIDENT : NEWTON FLYOVER, SLOW TRAFFIC

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 3560 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
3	TO RESPRAY REAR BUMPER.	\$	1,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 3560 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,677.00	
2	REAR BUMPER FIXING PARTS	1	\$ 301.00	
3	REAR BUMPER SPOILER	1	\$ 565.00	
4	REAR BUMPER SECURING STRIP	1	\$ 264.00	
5	REAR BUMPER CLOSING ELEMENT - LH / RH	2	\$ 190.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,140.00	
7	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	
9	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 126.00	
10	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 152.00	
11	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$ 158.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
13	REAR PARKING AID SEAL RING	4	\$ 6.00	
14	EXHAUST TAIL PIPE TRIM - LH / RH	2	\$ 1,300.00	
15	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 8,934.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 11,686.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT