PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

REFERENCE : PA/TP/0368/2023/EQ

DATE : 12-Apr-23 **WIP** : 15794

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/4/2023

YOUR INSURED VEH NO: SLM 3566 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MRS TEO KAH SAN, EMILIA

ADDRESS : 54 JOO CHIAT AVENUE

SINGAPORE 428164

 TELEPHONE
 : HP +65 97411420

 TYPE OF CLAIM
 : THIRD PARTY CLAIM

 POLICY NO
 : 7210010975-01

VEHICLE NO : EN 3589 R

MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC

 MODEL YEAR
 : 29/1/2021

 ENGINE NO
 : CZD C21271

CHASSIS NO : WAUZZZF3XM1050047

MILEAGE : DATE IN : -

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 10-Apr-23

PLACE OF ACCIDENT : CHANGI ROAD CLOSE TO INTERSECTION WITH STILL ROAD





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EN 3589 R

			ESTIMATED	SURVEYOR'S
S/N	NATURE OF JOBS		CHARGES	RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.00	
3	TO RESPRAY REAR BUMPER AND REAR LID.		\$ 2,500.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 4,652.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EN 3589 R

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,839.00	
2	REAR BUMPER FIXING PARTS	1	\$ 230.00	
3	REAR BUMPER SPOILER	1	\$ 540.00	
4	REAR BUMPER TOW EYE COVER	1	\$ 51.00	
5	REAR BUMPER CROSS REINFORCEMENT - CENTER	1	\$ 114.00	
6	REAR BUMPER BRACKET	1	\$ 57.00	
7	REAR BUMPER REFLECTOR - LH / RH	2	\$ 98.00	
8	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00	
9	REAR TAILGATE OPENING SENSOR LINE	1	\$ 230.00	
10	REAR AERIAL KEY ACCESS	1	\$ 81.00	
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 736.00	
12	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 68.00	
13	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 150.00	
14	REAR PARKING AID SENSOR - INNER / OUTER	3	\$ 815.00	
15	REAR PARKING AID SEAL RING	4	\$ 11.00	
16	REAR WHEEL COVER - LH / RH	2	\$ 598.00	
17	PACKING ADHESIVE	1	\$ 22.00	
18	AUDI EMBLEM	1	\$ 152.00	
19	"Q3" INSCRIPTION	1	\$ 110.00	
20	SUNDRIES		\$ 400.00	
	TOTAL SPARE PARTS	:	\$ 6,793.00	
	TOTAL LABOUR CHARGES	:	\$ 4,652.00	
	GRAND TOTAL	:	\$ 11,445.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO ALLAN WU

BODY REPAIR MANAGER CLAIMS CONSULTANT