



QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT23001100	Page	1
	300 BEACH ROAD #17-04/07	Date	: 12. Apr 2023		
	THE CONCOURSE	Customer No.	: WZL009		
	SINGAPORE 199555	Svc Advisor	: YOU PO SOON		
Registration No	: SJE1331T	Engine No	: L15B71624993		
Chassis No	: MRHFC1660GT000169	Date Time	: 12. Apr 2023 8:10:32 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2016	Surveyor Name	:		
Owner's Name	: LUAR SIOK HONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 11/4/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: MS LUAR						
	OWNER INSURER: SINGLIFE						
	ACC DATE: 11/4/2023						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC						
	TP VEH: YN6516U						
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	34.79	469.71
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	30.80	25	23.10	1.85	24.95
71108-TEA-T10	GARNISHL.FR.BUMPER SIDE	1	16.50	25	12.37	0.99	13.36
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.62	8.42
91505-TM8-003	CLIP,BUMPER	17	2.30	25	29.32	2.35	31.67
71130-TEA-T00	BEAM COMPFR.BUMPER	1	399.20	25	299.40	23.95	323.35
60261-TBA-A00ZZ	PANELL.FENDER	1	450.80	25	338.10	27.05	365.15
60263-TBA-A00ZZ	BRACKET AL.FR.FENDER	1	34.00	25	25.50	2.04	27.54
74151-TEA-T10	FENDER L.FR INNER	1	58.90	25	44.17	3.53	47.70
90682-SEA-003	CLIP ABUMPER	4	2.60	25	7.80	0.62	8.42
91501-TR0-003	CLIP,INNER FENDER	11	2.80	25	23.10	1.85	24.95
42700-TEA-T81	DISKALUMINIUM WHEEL	1	562.00	25	421.50	33.72	455.22
44600-TBC-A00	HUB ASSYFR.	1	85.30	25	63.97	5.12	69.09
44300-TEA-T51	BEARING ASSYFR.HUB	1	85.30	25	63.97	5.12	69.09
33150-TEA-T11	HEADLIGHT ASSYL.	1	1373.00	25	1029.75	82.38	1112.13
34350-TET-H01	LIGHT ASSYL.SIDE TURN	1	67.50	25	50.62	4.05	54.67
77930-TEA-B21	SENSOR ASSYFR.CRASH	1	82.50	25	61.87	4.95	66.82
Sum Item					2945.06	235.60	3,180.66

Printed on 12/4/2023 8:19:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SJE1331T
Chassis No : MRHFC1660GT000169
Model : CIVIC 1.5 TURBO VTIS YM2016
Owner's Name : LUAR SIOK HONG
Ins Policy No. :
Date of Accident : 11/4/2023

Document No. : SQT23001100
Date : 12. Apr 2023
Customer No. : WZL009
Svc Advisor : YOU PO SOON
Engine No : L15B71624993
Date | Time : 12. Apr 2023 8:10:32 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	220.00		220.00	17.60	237.60
Sum Ext. Service					220.00	17.60	237.60
BOSUN	SUNDRIES	1	50.00	20	50.00	4.00	54.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	160	180.00	14.40	194.40
BMS02R	REMOVE & RENEW CRASH SENSOR & RESET SYSTEM.	1	450.00	350	450.00	36.00	486.00
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)	1	1000.00	840	1000.00	80.00	1080.00
BKFE11R	REMOVE & RENEW FR L FENDER INCLUDING	1	2200.00	1300	2200.00	176.00	2376.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1700.00	1040	1700.00	136.00	1836.00
Sum Labor					5580.00	446.40	6,026.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 8,745.06 699.60 9,444.66

Total (Inclusive of GST) 9,444.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/4/2023 8:19:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.