



# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

|                  |                               |                    |                           |      |   |
|------------------|-------------------------------|--------------------|---------------------------|------|---|
| Customer         | : LONPAC INSURANCE BHD        | Document No.       | : SQT23001100             | Page | 1 |
|                  | 300 BEACH ROAD #17-04/07      | Date               | : 12. Apr 2023            |      |   |
|                  | THE CONCOURSE                 | Customer No.       | : WZL009                  |      |   |
|                  | SINGAPORE 199555              | Svc Advisor        | : YOU PO SOON             |      |   |
| Registration No  | : SJE1331T                    | Engine No          | : L15B71624993            |      |   |
| Chassis No       | : MRHFC1660GT000169           | Date   Time        | : 12. Apr 2023 8:10:32 AM |      |   |
| Model            | : CIVIC 1.5 TURBO VTIS YM2016 | Surveyor Name      | :                         |      |   |
| Owner's Name     | : LUAR SIOK HONG              | Survey Date        | :                         |      |   |
| Ins Policy No.   | :                             | Authorisation Date | :                         |      |   |
| Date of Accident | : 11/4/2023                   |                    |                           |      |   |

| Item            | Description                   | Qty | Unit Price | Disc % | Amount      | 8% GST Amount | Amount incld GST |
|-----------------|-------------------------------|-----|------------|--------|-------------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: ) |     |            |        |             |               |                  |
|                 | OWNER: MS LUAR                |     |            |        |             |               |                  |
|                 | OWNER INSURER: SINGLIFE       |     |            |        |             |               |                  |
|                 | ACC DATE: 11/4/2023           |     |            |        |             |               |                  |
|                 | SURVEYED BY:                  |     |            |        |             |               |                  |
|                 | DATE:                         |     |            |        |             |               |                  |
|                 | REF NO:                       |     |            |        |             |               |                  |
|                 | TP INSURER: LONPAC            |     |            |        |             |               |                  |
|                 | TP VEH: YN6516U               |     |            |        |             |               |                  |
| 71101-TEA-T00ZZ | FACEFR.BUMPER                 | 1   | 579.90     | 25     | 434.92 ✓    | 34.79         | 469.71           |
| 71190-TEA-T00   | BEAML.FR.BUMPER UPPER         | 1   | 30.80      | 25     | 23.10 X NN  | 1.85          | 24.95            |
| 71108-TEA-T10   | GARNISHL.FR.BUMPER SIDE       | 1   | 16.50      | 25     | 12.37 X NN  | 0.99          | 13.36            |
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE        | 1   | 10.40      | 25     | 7.80 X NN   | 0.62          | 8.42             |
| 71198-TEA-T01   | SPACERL.FR.BUMPER SIDE        | 1   | 10.40      | 25     | 7.80 ✓      | 0.62          | 8.42             |
| 91505-TM8-003   | CLIP,BUMPER                   | 17  | 2.30       | 25     | 29.32 ✓     | 2.35          | 31.67            |
| 71130-TEA-T00   | BEAM COMPFR.BUMPER            | 1   | 399.20     | 25     | 299.40 X NN | 23.95         | 323.35           |
| 60261-TBA-A00ZZ | PANELL.FENDER                 | 1   | 450.80     | 25     | 338.10 ✓    | 27.05         | 365.15           |
| 60263-TBA-A00ZZ | BRACKET AL.FR.FENDER          | 1   | 34.00      | 25     | 25.50 ✓     | 2.04          | 27.54            |
| 74151-TEA-T10   | FENDER L.FR INNER             | 1   | 58.90      | 25     | 44.17 ✓     | 3.53          | 47.70            |
| 90682-SEA-003   | CLIP ABUMPER                  | 4   | 2.60       | 25     | 7.80 ✓      | 0.62          | 8.42             |
| 91501-TR0-003   | CLIP,INNER FENDER             | 11  | 2.80       | 25     | 23.10 ✓     | 1.85          | 24.95            |
| 42700-TEA-T81   | DISKALUMINIUM WHEEL           | 1   | 562.00     | 25     | 421.50 ✓    | 33.72         | 455.22           |
| 44600-TBC-A00   | HUB ASSYFR.                   | 1   | 85.30      | 25     | 63.97 X NN  | 5.12          | 69.09            |
| 44300-TEA-T51   | BEARING ASSYFR.HUB            | 1   | 85.30      | 25     | 63.97 X NN  | 5.12          | 69.09            |
| 33150-TEA-T11   | HEADLIGHT ASSYL.              | 1   | 1373.00    | 25     | 1029.75 ✓   | 82.38         | 1112.13          |
| 34350-TET-H01   | LIGHT ASSYL.SIDE TURN         | 1   | 67.50      | 25     | 50.62 ✓     | 4.05          | 54.67            |
| 77930-TEA-B21   | SENSOR ASSYFR.CRASH           | 1   | 82.50      | 25     | 61.87 X NN  | 4.95          | 66.82            |
| Sum Item        |                               |     |            |        | 2945.06     | 235.60        | 3,180.66         |

Printed on 12/4/2023 8:19:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD  
300 BEACH ROAD #17-04/07  
THE CONCOURSE  
SINGAPORE 199555  
Registration No : SJE1331T  
Chassis No : MRHFC1660GT000169  
Model : CIVIC 1.5 TURBO VTIS YM2016  
Owner's Name : LUAR SIOK HONG  
Ins Policy No. :  
Date of Accident : 11/4/2023

Document No. : SQT23001100  
Date : 12. Apr 2023  
Customer No. : WZL009  
Svc Advisor : YOU PO SOON  
Engine No : L15B71624993  
Date | Time : 12. Apr 2023 8:10:32 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 2

| Item              | Description                                           | Qty | Unit Price | Disc % | Amount    | 8% GST Amount | Amount incld GST |
|-------------------|-------------------------------------------------------|-----|------------|--------|-----------|---------------|------------------|
| BO-WHEEL ALIGN X4 | WHEEL ALIGNMENT X4                                    | 1   | 220.00     |        | 220.00 ✓  | 17.60         | 237.60           |
| Sum Ext. Service  |                                                       |     |            |        | 220.00    | 17.60         | 237.60           |
| BOSUN             | SUNDRIES                                              | 1   | 50.00      |        | 50.00 ✓   | 4.00          | 54.00            |
| BML01I            | INSPECT FR LIGHTING MECHANISMS & FOCUS                | 1   | 180.00     |        | 180.00 ✓  | 14.40         | 194.40           |
| BMS02R            | REMOVE & RENEW CRASH SENSOR & RESET SYSTEM.           | 1   | 450.00     |        | 450.00 ✓  | 36.00         | 486.00           |
| BMU11R            | REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)         | 1   | 1000.00    |        | 1000.00 ✓ | 80.00         | 1080.00          |
| BKFE11R           | REMOVE & RENEW FR L FENDER INCLUDING                  | 1   | 2200.00    |        | 2200.00 ✓ | 176.00        | 2376.00          |
| BP03R             | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.<br>(3P) | 1   | 1700.00    |        | 1700.00 ✓ | 136.00        | 1836.00          |
| Sum Labor         |                                                       |     |            |        | 5580.00   | 446.40        | 6,026.40         |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 8,745.06 699.60 9,444.66

Total (Inclusive of GST) 9,444.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/4/2023 8:19:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.