



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2005153426-01	Date of Loss:	11/04/2023
Vehicle Reg. No.:	SMJ4888Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	QE ELEMECH ENGINEERING PTE LTD		
Driver:	ANG KIAN SIM(HONG JIANSHEG)		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	26/03/2019
Vehicle Colour:	BLUE		
Engine No:	2NRX433578	Chassis No:	MR2B23F3901171578
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Remarks:	VEHICLE CURRENTLY LYING AT WOODLANDS WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	3,084.40
Miscellaneous Items	35.00
Labour	1,500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,619.40
+ GST 8.00% (\$\$)	369.55
Nett Amount (\$\$)	4,988.95

This claim is handled by: **SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2023)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SMJ4888Y/13/04/2023 14:28	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	0.00	0.00	*180.00 F BUC
2	1		*1 PC FRT BUMPER REINFORCEMENT	0.00	0.00	*160.00 F ?
3	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE	0.00	0.00	*105.00 F ?
4	1		*1 PC FRT BUMPER RH SIDE RETAINER	0.00	0.00	*45.00 F ?
5	1		*6 PCS FRT BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F NEC
6	1		*1 PC FRT GRILLE ASSY	0.00	0.00	*190.00 F ?
7	1		*1 PC FRT GRILLE LOGO	0.00	0.00	*40.00 F CUT
8	1		*2 PCS HEADLAMPS @190/PC	0.00	0.00	*380.00 F ?
9	1		*1 PC BONNET	0.00	0.00	*230.00 F BUC
10	1		*2 PCS BONNET HINGES @34/PC	0.00	0.00	*68.00 F ?
11	1		*1 PC BONNET INNER LOCK	0.00	0.00	*55.00 F ?
12	1		*1 PC FRT SUPPORT PANEL	0.00	0.00	*240.00 F R
13	1		*1 PC AIRCON CONDENSER	0.00	0.00	*380.00 F ?
14	1		*1 PC RADIATOR	0.00	0.00	*420.00 F ?
15	1		*1 PC FRT WIPER GARNISH	0.00	0.00	*185.00 F CRA
16	1		*7 PCS FRT SUPPORT TOP COVER CLIPS @2/PC	0.00	0.00	*14.00 F NEC
17	1		*2 PCS HEADLAMP TOP PANELS @50/PC	0.00	0.00	*100.00 F ?

F=Franchise part.

Sub Total (\$\$)	2,804.00
+ Margin on L,N Items 10.00% (\$\$)	280.40
Total Parts (\$\$)	3,084.40

Cheng Hoe Motor Pte Ltd/SMJ4888Y/13/04/2023 14:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
----	-----	-------------	--------

Miscellaneous Items

1	1	1 PC FRT NUMBER PLATE	35.00, BT
---	---	-----------------------	-----------

Sub Total (S\$)	35.00
-----------------	-------

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Labour Items

1	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00
2	PANEL BEATING	New	500 700.00
3	PUTTY & RESPRAY PAINTING	New	400 700.00

Gross Labour Cost (S\$)	1,500.00
-------------------------	----------

Cheng Hoe Motor Pte Ltd/SMJ4888Y/13/04/2023 14:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 4 DAYS

- NOT AUTHORISE
- EXCESS \$600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: