

Mon 08/05 @ 10am
S&R

SND4329P

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 APR 2023

Estimate No. : b1 65627
Date Estimated : 12/04/2023
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

CHIA CHOON SENG
481 Yio Chu Kang Road
#08-07

Singapore 787056

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND4329P	WBA70DY0008C30990	29/12/2021	318i Sedan	9739

DESCRIPTION

To replace rear bumper, boot lid includ- ing to knock out tail panel and dented area

2975 / 2850 2975.00

To respray rear bumper, boot lid and tail panel

2532 / 2572 2666.00

To remove and install boot compartment carpet and garnish to facilitate repair.

257 271.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

Sundries.

150.00

Total Labour 1: 6,416.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID	1	1,408.30	1,408.30
# Set of mount	1	70.45	70.45
# REAR RH LATERAL MOUNT	1	211.85	211.85
# REAR BUMPER CARRIER	1	516.20	516.20
# ADAPTER	1	50.55	50.55
TRIM STRIP (SPORT)	1	96.10	96.10
# REAR LH TRIM PANEL	1	99.75	99.75
# REAR BUMPER LH SIDE GUIDE	1	136.30	136.30
# REAR BUMPER RH SIDE GUIDE	1	136.30	136.30
# REAR BUMPER PANEL PRIMED (SP	1	1,280.35	1,280.35
PLAQUE 74MM	1	72.85	72.85
LETTERING 318i	1	65.60	65.60
GROMMET	2	0.80	1.60
EXPANDING RIVET D=8MM	14	1.15	16.10
# REAR DIFFUSER	1	74.50	74.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 65627
Date Estimated : 12/04/2023
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND4329P	WBA70DY0008C30990	29/12/2021	318i Sedan	9739

DESCRIPTION	QTY	PRIC	VALUE
# TRUNK LID SEALING <i>new</i>	1	135.15	135.15
(DG/SL) ADHESIVE SET K6 <i>new</i>	1	53.05	53.05
Total Parts :			4,425.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date & Time <i>05/05/23 @ 1230</i>	Excess S\$
Surveyor's Name <i>RASU</i>	Sign
Surveyor's Tel <i>90010068</i>	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No	PML Yes / No
Surveyor's E-mail	
No. of Working Days Recommend <i>5-6 days</i>	



Labour 1	:	6,416.00
Parts	:	4,425.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	867.28
Grand Total	:	11,708.28

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 65627
Date Estimated : 12/04/2023
Prepared By : Han Kwan Yong

Page No. :

- ESTIMATE REPAIR FOR -

CHIA CHOON SENG

481 Yio Chu Kang Road

#08-07

Singapore 787056

- ACCOUNT - 224093

Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road

#09-01

Singapore 068897

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND4329P	WBA70DY0008C30990	29/12/2021	318i Sedan	9739

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
** To replace rear bumper panel, boot lid, rear carrier, rear LH lateral mount, trim strip, rear LH trim panel, rear LH/RH side guide, rear diffuser include making good the tail end panel and carrying out necessary repairs caused by the accident	2,975.00		2,975.00 ✓
** To replace rear exhaust silencer include alignment of system and conducting checks for leak	504.00		504.00 ✓
* To carry out body cavity preservation (Per panel)	112.00		112.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HEX NUT M8 m ✓	1.30	3.00	0.00	3.90
# SILENCER CLAMPING BUSH m ✓	66.25	1.00	0.00	66.25
# REAR SILENCER lt ✓	1,231.30	1.00	0.00	1,231.30
# TAILPIPE TRIM CHROME D=90MM est ✓	136.15	1.00	0.00	136.15
# REAR LH LATERAL MOUNT ca ✓	211.85	1.00	0.00	211.85
# REAR LH REAR REFLECTOR ca ✓	41.00	1.00	0.00	41.00

SUPPLEMENTARY ITEMS

Total Labour :	3,591.00
Total Parts :	1,690.45
Total Labour & Parts (before GST) :	5,281.45

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company