

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SJN 8422 X
Chassis No: RN61086736

Hui Rong
TP Allianz.

Make/Model : HONDA STREAM
Accident date : 10.04.2023

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front bumper <i>Deland</i>	1	\$ 948.00 <i>688.</i>
2	Front bumper side holder <i>Ream</i>	1	\$ 48.50 <i>X</i>
3	Front bumper LH side lower garnish <i>Ream</i>	1	\$ 85.00 <i>X.</i>
4	Front bumper clips <i>Ream</i>	1	\$ 60.00 <i>30. 685</i>
5	Front LH head lamp <i>lit.</i>	1	\$ 1,389.60 <i>1,389.60</i>
6	Front LH fender <i>Ream</i>	1	\$ 826.40 <i>X.</i>
7	Front LH fender inner shield <i>Not in</i>	1	\$ 202.40 <i>X.</i>
8	Front LH fender inner shield clips <i>Ream</i>	1	\$ 60.00 <i>30.</i>
			\$ 3,619.90
		Less 20% Disc	\$ 723.98
		Total	\$ 2,895.92

1433

1146.40

Labour Cost

1	Remove replace + repair consistent to the accident	1	\$ 1,000.00 <i>300</i>
2	Respray painting	1	\$ 1,000.00 <i>400.</i>
	Total		\$ 2,000.00

Grand Total

\$ 4,895.92 *700*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1846.40

✓ 4/5: 1.41K.

03 Days