

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Chew Seng Zhang 656C Punggol East #08-842 Singapore 823656 Contact No Mobile: 91167895 10/05/	Cust No/Name	/Mr CHEW SENG ZHANG
	Reg No/Reg Date	SMQ8312D / 04/12/201
	Date In/Mileage	08/05/2023/ 40596
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	11/05/2023/ 08:02	REN	979 / Renemer Ramirez Bag	18726		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
Z TEXT							
ACCIDENT ON 11/04/2023 ALONG ECP(CHANGI) BEF BEDOK SOUTH AVE 1 EXIT							
OWNER CLAIMING THIRD PARTY							
REQUIRED REPLACEMENT VEHICLE							
TP#: SHD6356T TP INS : MS FIRST CAPITAL							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE							
A 90000001							
TO CHECK WIRING AND ELECTRICAL SYSTEM							
E PNT88000							
TO REPLACE RH SIDE MIRROR,RHF & RHR DOOR MOULDING							
TO REPAIR RHF FENDER,RHF & RHR DOOR PANEL							
STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS							
E PNT98000							
SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS							
(RH SIDE MIRROR,RHF FENDER,RHF & RHR DOOR PANEL)							
M SUNDRY							
TO SUPPLY HYBRID EMBLEM							
M SUNDRY							
SUNDRIES							
Z TEXT							
FINALIZATION							
NO. OF TOTAL REPAIR DAYS - 4 DAYS							
ATTENTION TO: MR. MOHD TAUFIKH							
X	RH MIRROR ASSY-OUTSIDE RR VIEW	1.00	753.00	00.00	753.00		
X	RH MOULDING ASSY-FRT DR W/LINE	1.00	171.00	00.00	171.00		
X	RH MOULDING ASSY-RR DR W/LINE	1.00	113.00	00.00	113.00		

Confirm & accepted by

	Nett	4,077.00
8% GST on	4077.00	326.16
Total Payable		4,403.16

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.