

TICK HAI MOTOR & WELDING SERVICES
 1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
 TEL: 6842 9089 FAX: 6841 2869
 REG NO : 48992400W

not allowed
 her
 19/4/23
 4 days.
 time for the repair
 2/5 \$5700

Vehicle Number : SMZ5765C
 Vehicle Model : Toyota Lexus NX300H Luxury S/R
 Chassis Number : JTJBJRBZX02043946
 Year of Manufacture : 2016

not item

S/N	Item Description	Amount (\$)
1	Rear Boot <i>2871.20 DD/seat</i>	\$ 4,349.72 ✓
2	Rear Boot Inner Lock <i>su</i>	\$ 1,149.32 X
3	Rear Boot Catch <i>11</i>	\$ 81.18 X
4	Rear Boot Inner Trimboard <i>11</i>	\$ 802.99 X
5	Rear Boot Inner Trimboard Clip x 1 set <i>11</i>	\$ 64.90 X
6	Rear Boot Rubber <i>11</i>	\$ 580.44 X
7	Lexus Centre Logo <i>11</i>	\$ 234.11 X
8	"Lexus" Emblem <i>111</i>	\$ 96.76 /
9	"NX300h" Emblem <i>111</i>	\$ 112.57 /
10	Taillamp x 2 pcs <i>11</i>	\$ 2,009.78 X
11	Taillamp Lower Retainer x 2 pcs <i>11</i>	\$ 331.11 X
12	Rear Bumper <i>7011</i>	\$ 908.60 /
13	Rear Bumper <i>brockets</i> x 2 pcs <i>seat</i>	\$ 259.84 /
14	Rear Bumper Reflector x 2 pcs <i>11</i>	\$ 170.39 X
15	Rear Bumper Clip x 1 set <i>111</i>	\$ 64.90 /
16	Rear Bumper Reinforcement <i>11</i>	\$ 1,164.90 X
17	End Panel <i>845.11 DD/seat</i>	\$ 1,281.36 /
18	End Panel Top Garnish <i>366.00 TW1</i>	\$ 848.18 /
19	Air Duct x 2 pcs <i>one</i>	\$ 145.85 /
20	Spare Tyre Undercover <i>11</i>	\$ 359.31 X
21	Rear Windscreen Moulding x 1 Set <i>111</i>	\$ 64.63 /
Total :		\$ 15,080.84
Less 10% :		\$ 1,508.08
Amount :		\$ 13,572.75

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 4 pcs <i>no Reflector</i>	\$ 2,577.59 <i>17C</i>
2	Windscreen Sealant <i>1 ec</i>	\$ 50.00 <i>40</i>
3	End Panel Sealant <i>111</i>	\$ 50.00 ✓

2-5685-46
 102
 511691
 395
 1690

Amount :	\$ 2,677.59
-----------------	--------------------

Labour	Amount (\$)
To check rear electrical wiring system	\$ 120.00
To apply anti-rusting coating on affected areas	\$ 150.00
To transfer rear boot components from old boot to new boot	\$ 120.00
To remove & refix rear interior trims, garnishes etc to facilitate repair	\$ 250.00
To remove & reinstall reverse sensors	\$ 120.00
To remove & install rear windscreen	\$ 150.00
To straighten, repair, realign on rear affected area and replace damaged parts	\$ 1,800.00
To spray paint on affected areas	\$ 1,500.00
Labour Total :	\$ 4,210.00
Total (Parts & Labour)	\$ 20,460.34

20
60
60
80
50
120
600
700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Handwritten notes on the left side of the page, including numbers like 24-28224, 18/1/12, and other illegible scribbles.