



Your Ref: S2M0486J

Date: 21<sup>st</sup> April 2023

Our Ref: CS3/ASM22008811/Dvp3e2-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard  
#48-01 Marina Bay Financial Centre Tower 2  
Singapore 018983  
(The Motor Claims Department)

Attn: Chong Arnold

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBF 3728J  
INSURED VEHICLE: SHB 4751J  
ACCIDENT DATE: 02/08/2022**

We thank you for your instruction on 14/04/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBF 3728J from WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles FBF 3728J and SHB 4751J.
- c) Police Report of Vehicles FBF 3728J and SHB 4751J.
- d) Final Repair Bill of FBF 3728J from M/s Tuck Life Pte Ltd.
- e) Colour damaged vehicle photographs of FBF 3728J.

Pre-Repair Inspection Date: 07/09/2022 at M/s Tuck Life Pte Ltd, 25 Kaki Bukit Road 4, #01-68 Synergy@KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBF 3728J  
Make & Model : Honda CBR1000RR  
Year of Registration : 2011  
Chassis Number : JH2SC59A1BK301237  
Engine Capacity : 999 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.