

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 IOB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Ezlynk

Quotation

DATE : 13.04.2023
 VEH NO : GBL4488M
 MODEL : Nissan NV200
 D O A : 06.04.2023
 YR REF : SLD8231J

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBL4488M (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>new</i>	2	104.80 <i>+</i>
2	Rear Bumper <i>Delend</i>	1	632.70 ✓
3	Rear Bumper Side Holder - LH & RH <i>Rid Bend</i>	2	80.40 <i>40.20</i>
4	Rear Bumper Sponge <i>crackd</i>	1	121.50 ✓
5	Rear Bumper Towing Cover <i>new</i>	1	25.90 <i>+</i>
6	Tail Lamp - LH & RH <i>RH crackd</i>	2	566.40 <i>283.20</i>
7	Tail Lamp Panel - LH & RH <i>Repis</i>	2	847.00 <i>+</i>
8	Rear End Panel - Outer <i>Distorted</i>	1	411.50 ✓
9	Rear End Panel - Inner <i>Repis</i>	1	620.60 <i>+</i>
10	Rear End Panel Top Cover <i>Delend</i>	1	185.30 ✓
11	Tailgate <i>Distorted</i>	1	1,835.40 ✓
12	Tailgate Lock <i>Distorted</i>	1	260.60 ✓
13	Tailgate Lock Catch <i>new</i>	2	44.20 <i>+</i>
14	Tailgate Weatherstripe <i>cut</i>	1	241.20 ✓
15	Tailgate Outer Garnish	1	366.90 <i>+</i>
16	Tailgate Inner Trim Board <i>Delend</i>	1	210.50 ✓
17	Tailgate Pull Pocket <i>Delend</i>	1	32.10 ✓
18	Tailgate Glass Moulding <i>new</i>	1	140.80 ✓
19	Nissan Logo	1	79.90 ✓
20	NV200 Emblem <i>new</i>	1	94.40 ✓
21	Vanette Emblem	1	68.60 ✓
22	Floor Panel <i>Repis</i>	1	2,061.10 <i>+</i>
23	Spare Tyre Carrier <i>Best</i>	1	284.30 ✓
24	Spare Tyre Lock Bolt <i>new</i>	1	59.10 <i>+</i>
25	Rear Exhaust Pipe	1	551.70 <i>+</i>
26	Rear Exhaust Mounting <i>new</i>	1	34.90 <i>+</i>
27	Rear Exhaust Gasket	1	30.50 <i>+</i>

RE : ESTIMATE FOR ACCIDENT REPAIR GBL4488M (NISSAN NV200)

4922.20
 4429.98 Less 10%

\$ 9,992.30
 (999.23)
 \$ 8,993.07

S/NET ITEMS

1	Rear Number Plate	<i>Best</i>	1	30.00	✓
2	Rear Number Plate Holder	<i>Red</i>	1	30.00	✓
3	Rear Bumper Clips	<i>m</i>	1	30.00	✓
4	Reverse Sensor	<i>Red</i>	1	280.00	<i>200</i>
5	Rear End Panel Clips	<i>new</i>	1	20.00	✓
6	Rear End Panel Sealant	<i>m</i>	1	60.00	✓
7	Tailgate Outer Garnish Clips	<i>new</i>	1	20.00	✓
8	Tailgate Inner Trim Board Clips	<i>m</i>	1	30.00	✓
9	Tailgate Glass Sealant	<i>m</i>	1	60.00	✓
10	70km/h Sticker	<i>new</i>	1	15.00	✓
11	6pax Sticker	<i>new</i>	1	15.00	✓
12	Rear Camera	<i>new</i>	1	480.00	✗
13	Floor Panel Sealant	<i>new</i>	1	100.00	✗

490

1,170.00

Total parts

\$ 10,163.07

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,600.00	<i>1200.</i>
2	To putty & spray up paint works	\$ 1,500.00	<i>800.</i>
3	To check wiring	\$ 50.00	<i>30.</i>
4	To remove reverse sensor	\$ 100.00	<i>50</i>
5	To remove rear camera	\$ 100.00	<i>50</i>
6	To remove video recorder	\$ 100.00	<i>50</i>
7	To apply tuff coat	\$ 150.00	<i>80</i>
8	To remove upholstery	\$ 150.00	<i>60</i>
9	To remove tailgate glass	\$ 180.00	<i>120</i>
10	To transfer tailgate fittings	\$ 150.00	<i>80</i>
11	To remove exhaust pipe	\$ 150.00	<i>X.</i>

2520

4,230.00

RE : ESTIMATE FOR ACCIDENT REPAIR GBL4488M (NISSAN NV200)

Grand Total

\$ 14,393.07

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7439.88
H/S: 5950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: