



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF CHIU DAVID		Ref: CS/TP23003903/Uny3m4 Date: 27/04/2023 Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	Veh. Inspected		SNC 3232X
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		17/04/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	AUDI A5 SB 2.0 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZF51JA124758	Colour	SILVER
Odometer	81284 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	265/30 ZR20	CONTINENTAL	6 mm
L/H Front Tyre	265/30 ZR20	CONTINENTAL	6 mm
R/H Rear Tyre	265/30 ZR20	CONTINENTAL	6 mm
L/H Rear Tyre	265/30 ZR20	CONTINENTAL	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	08/04/2023	Inspection Date	17/04/2023
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	