

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 IOB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Quotation

DATE : 17.04.2023
 VEH NO : PC5856J
 MODEL : Nissan NV350
 D O A : 12.04.2023
 YR REF : SMQ6285L

Ezlym

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

JN17C7E262090580

RE : ESTIMATE FOR ACCIDENT REPAIR PC5856J (NISSAN NV350)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>new</i>	2	124.80 <i>X.</i>
2	Rear Bumper <i>Distorted</i>	1	696.70 ✓
3	Rear Bumper Side Holder - LH & RH <i>Dmgd</i>	2	70.80 ✓
4	Rear Bumper Reinforcement <i>Dented</i>	1	240.50 ✓
5	Rear Bumper Exhaust Garnish <i>Behind</i>	1	49.60 ✓
6	Rear End Panel <i>Dented</i>	1	452.90 ✓
7	Rear End Panel Top Plate <i>Bent</i>	1	159.40 ✓
8	Tail Lamp - LH & RH <i>crushed.</i>	2	568.60 ✓
9	Tail Lamp Panel - LH & RH <i>Dented</i>	2	830.20 ✓
10	Tail Lamp Inner Panel - LH & RH <i>LH Buckled</i>	2	1,008.40 <i>504.20.</i>
11	Tailgate <i>Distorted</i>	1	2,101.40 ✓
12	Tailgate Lock <i>Jammed.</i>	1	287.10 ✓
13	Tailgate Lock Catch <i>new</i>	1	54.10 <i>X.</i>
14	Tailgate Lock Actuator <i>Dmgd.</i>	1	302.40 ✓
15	Tailgate Weatherstripe <i>cut</i>	1	217.80 ✓
16	Tailgate Damper - LH & RH <i>new</i>	2	500.80 <i>X.</i>
17	Tailgate Outer Chrome Garnish <i>new</i>	1	482.30 <i>X.</i>
18	Tailgate Inner Trim Board <i>torn</i>	1	162.10 ✓
19	Tailgate Glass Moulding <i>new</i>	1	155.20 ✓
20	Nissan Logo	1	68.70 ✓
21	NV350 Emblem <i>new</i>	1	75.70 ✓
22	Urban Emblem	1	60.40 ✓
23	Rear Body Panel - LH <i>Buckled</i>	1	1,867.50 ✓
24	Rear Body Panel Sliding Door Railing - LH <i>new</i>	1	255.40 <i>X.</i>
25	Rear Body Panel Sliding Door Railing End Piece - LH <i>new</i>	1	45.40 <i>X.</i>
26	Rear Body Panel - RH <i>Repair</i>	1	4,086.50 <i>X.</i>
27	Rear Body Panel Air Vent - RH <i>new</i>	1	65.20 <i>X.</i>
28	Floor Panel <i>Distorted</i>	1	1,883.20 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR PC5856J (NISSAN NV350)

29	Rear Exhaust Pipe <i>Phs</i>	1	691.40 <i>+</i>
30	Rear Exhaust Mounting <i>3 new</i>	1	38.20 <i>+</i>
31	Rear Exhaust Gasket	1	34.10 <i>+</i>
32	Spare Tyre Lock Regulator <i>Qyd</i>	1	269.30 <i>✓</i>

11023.70

9921.33

Less 10%

\$	17,906.10
	<u>(1,790.61)</u>
\$	16,115.49

S/NET ITEMS

1	Rear Number Plate <i>Best</i>	1	30.00 <i>✓</i>
2	Rear Bumper Clips <i>new</i>	1	30.00 <i>✓</i>
3	Rear End Panel Top Plate Rivets <i>new</i>	1	30.00 <i>✓</i>
4	Tailgate Outer Garnish Clips <i>new</i>	1	20.00 <i>+</i>
5	Tailgate Inner Trim Board Clips <i>new</i>	1	30.00 <i>✓</i>
6	Tailgate Glass Sealant <i>new</i>	1	60.00 <i>✓</i>
7	70km/h Sticker <i>new</i>	1	15.00 <i>✓</i>
8	Rear Body Panel Sealant - LH <i>new</i>	1	100.00 <i>80</i>
9	Rear Body Panel Glass Sealant - LH <i>new</i>	1	100.00 <i>60</i>
10	Rear Body Panel Glass Sealant - RH <i>new</i>	1	100.00 <i>+</i>
11	Floor Panel Top Carpet <i>torn</i>	1	600.00 <i>350</i>
12	Floor Panel Top Carpet Clips <i>new</i>	1	50.00 <i>✓</i>
13	Floor Panel Sealant <i>new</i>	1	100.00 <i>80</i>

1,265.00

Total parts

\$ 17,380.49

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	2,400.00 <i>1800</i>
2	To putty & spray up paint works	\$	2,000.00 <i>1600</i>
3	To check wiring	\$	100.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>80</i>
6	To remove rear passenger seat	\$	300.00 <i>180</i>
7	To remove tailgate glass	\$	180.00 <i>120</i>
8	To transfer tailgate fittings	\$	150.00 <i>80</i>
9	To remove rear LH and RH body panel glasses	\$	280.00 <i>80</i>

RE : ESTIMATE FOR ACCIDENT REPAIR PC5856J (NISSAN NV350)

10 To remove exhaust pipe

4100

\$

150.00 ~~80,~~

5,810.00

Grand Total

\$ 23,190.49

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 14836.33
L/S: 11850.

14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: