

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/GRB23003914/Upa3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SYN7987P

at Workshop m/s: Choo nhor

of _____

Insured: SLP6468T

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 444k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

448h

Date: _____ Person Contacted: LTA 23637

Vehicle: IN / OUT

Veh No: SYN7987P Yr Regn: 07/01/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / AMALINE

Make: Mer Benz CLA180 c.c. 1595

Colour: red A/C: Insured / Std / NI / NA

Sp. Reading: 96973 T/Radio: Insured / Std / NI / NA

Eng/No: _____ C/No: WDD173422N152963

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/04/23 D.O.I. 17/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>9/5/23</u>	<u>have vides of folder Rep 18k.</u>
<u>4/5</u>	<u>4400 in Road A Car.</u>

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$) S + RS, SI

Transportation:

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

CHOO MOTOR SPRAY PAINTER
 1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
 SINGAPORE 417883

*not allowed
 an
 17/4/23
 d/s \$4400
 5 days.*

VEHICLE No: SJN 7987P

NETT ITEM

1PC	BOOTLID	<i>1</i>		\$2,245.00	X
1PC	BOOTLID OUTER CHROME MOULDING	<i>11</i>		\$461.50	X
1PC	BOOTLID ' CLA 180 ' EMBLEM	<i>11</i>		\$95.00	X
1PC	BOOTLID C&C LOGO	<i>11</i>		\$50.00	Y
1PC	BOOTLID ' 7G-TRONIC ' EMBLEM	<i>11</i>		\$95.00	X
2PCS	BOOTLID HINGES @\$365.00	<i>11</i>		\$730.00	X
1PC	BOOTLID WEATHERSTRIP	<i>11</i>		\$368.00	X
1SET	BOOTLID INNER TRIM CLIPS	<i>11</i>		\$60.00	X
2PCS	TAILLAMPS @\$ 950.00	<i>see</i>		\$1,900.00	X
2PCS	TAILLAMP BLACK GARNISHS @\$68.00	<i>11</i>		\$136.00	X
2PCS	TAILLAMP LOWER BRACKETS @\$105.00	<i>n/s one</i>	<i>68.50</i>	\$210.00	<i>1pc</i>
1PC	REAR BUMPER	<i>TD</i>		\$1,615.00	—
1PC	REAR BUMPER LOWER GARNISH	<i>7w1</i>	<i>541.20</i>	\$680.00	—
2PCS	REAR BUMPER SIDE HOLDERS @\$115.00	<i>n/s one</i>	<i>0/s m</i>	\$230.00	<i>1pc</i>
1SET	REAR BUMPER CLIPS	<i>see</i>		\$60.00	—
1PC	REAR BUMPER INNER TOP RETAINER	<i>11</i>		\$345.00	X
1PC	REAR BUMPER BEAM	<i>see</i>		\$750.00	—
1PC	REAR END PANEL	<i>TD</i>	<i>715.32</i>	\$1,215.00	—
1PC	REAR END PANEL TOP GARNISH	<i>11</i>	<i>781.20</i>	\$485.00	X
1PC	REAR FLOOR PANEL	<i>11</i>		\$1,480.00	X
1PC	REAR FLOOR PANEL TOP BOARD	<i>11</i>		\$820.00	X
1PC	REAR END PANEL SEALANT	<i>see</i>		\$50.00	—
1SET <i>1pc</i>	REAR BUMPER REVERSE SENSOR <i>ALS</i>	<i>mal function</i>	<i>(102) 205</i>	\$380.00	—
				\$14,460.50	

TO CHECK WIRING	\$50.00	<i>20</i>
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	<i>50</i>
TO DISMANTLE & REFIX REAR WINDSCREEN	<i>11</i> \$150.00	X
TO TRANSFER BOOTLID MECHANISM	<i>11</i> \$100.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	<i>80</i>
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$100.00	<i>60</i>
TO SPRAY RUST PROOFING	\$120.00	<i>30</i>
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00	<i>600</i>
TO PUTTY & SPRAY PAINTING	\$1,500.00	<i>750</i>
TOTAL	\$18,210.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*P-4351.22
 107
 3916.09*