

DATE : 03.4.2023

TO : AIG INSURANCE
VEHICLE NO : SLH 5246 P
MODEL : HONDA CIVIC
DATE OF ACCIDENT : 29.03.2023
CHASSIS :
DATE OF REG :

Ezlyna.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repair</i>	1	\$ 598.60	\$ 598.60
2	FRONT BUMPER LOWER GRILLE <i>3AP</i>	1	\$ 98.60	\$ 98.60
3	FRONT BUMPER FOGLAMP COVER <i>Ja</i>	1	\$ 65.90	\$ 65.90
4	FRONT BUMPER BOTTOM GARNISH (CENTER) <i>He n</i>	1	\$ 178.30	\$ 178.30
5	FRONT BUMPER TOP BEAM <i>2</i>	1	\$ 235.90	\$ 235.90
6	FRONT BUMPER TOP RUBBER <i>He n</i>	1	\$ 49.80	\$ 49.80
7	FRONT BUMPER REINFORCEMENT <i>He n</i>	1	\$ 389.20	\$ 389.20
8	FRONT BUMPER RETAINER <i>He n</i>	1	\$ 48.90	\$ 48.90
9	FRONT BUMPER SIGNAL LAMP <i>He n</i>	1	\$ 78.50	\$ 78.50
10	FRONT SIDE MIRROR <i>Repair</i>	1	\$ 685.30	\$ 685.30
11	FRONT FENDER RH <i>Repair</i>	1	\$ 408.60	\$ 408.60
12	FRONT FENDER TOP SPONGE RH <i>He n</i>	1	\$ 45.30	\$ 45.30
13	FRONT FENDER COWLING <i>He n</i>	1	\$ 125.90	\$ 125.90
14	HEADLAMP (HID) RH <i>He n</i>	1	\$ 1,186.90	\$ 1,186.90
15	HEADLAMP LOWER BRACKET <i>He n</i>	1	\$ 48.90	\$ 48.90
16	HEADLAMP TOP GARNISH <i>3AP</i>	1	\$ 144.20	\$ 144.20
17	HEADLAMP TOP RUBBER <i>Ja</i>	1	\$ 45.30	\$ 45.30
18	FRONT GRILLE <i>He n</i>	1	\$ 208.60	\$ 208.60
19	FRONT GRILLE LOGO <i>He n</i>	1	\$ 38.40	\$ 38.40
20	FRONT GRILLE CHROME <i>He n</i>	1	\$ 170.40	\$ 170.40
21	FRONT SUPPORT PANEL <i>He n</i>	1	\$ 510.20	\$ 510.20
22	FRONT SUPPORT PANEL TOP GARNISH <i>3AP</i>	1	\$ 37.70	\$ 37.70
23	RADIATOR SIDE GARNISH RH <i>He n</i>	1	\$ 42.10	\$ 42.10
24	FRONT DOOR RH <i>Repair</i>	1	\$ 1,354.80	\$ 1,354.80
25	SIDE SKIRT RH <i>He n</i>	1	\$ 758.90	\$ 758.90
26	FRONT RIM RH <i>He n</i>	1	\$ 897.60	\$ 897.60
27	FRONT LOWER ARM <i>3AP</i>	1	\$ 385.60	\$ 385.60
28	FRONT KNUCKLE ARM <i>Ja</i>	1	\$ 485.30	\$ 485.30
29	FRONT ABSORBER	1	\$ 398.50	\$ 398.50

30	FRONT STABILIZER LINKAGE	1	\$ 145.20	\$ 145.20	+
31	FRONT WHEEL HUB BEARING	1	\$ 425.90	\$ 425.90	+

TOTAL PRICE \$ 10,293.30
 LESS 20% \$ 2,058.66
 SUB TOTAL PRICE \$ 8,234.64

685.30
 548.24

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00	+
2	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00	+
3	FRONT BUMPER BOTTOM GARNISH (CENTER) CLIP (SET)	1	\$ 40.00	\$ 40.00	+
4	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00	+
5	HEADLAMP TOP GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00	+
6	FRONT GRILLE CLIP (SET)	1	\$ 30.00	\$ 30.00	+
7	FRONT SUPPORT PANEL SEALANT	1	\$ 80.00	\$ 80.00	+
8	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET)	1	\$ 40.00	\$ 40.00	+

TOTAL \$ 370.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	200
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	500
3	WIRING CHECK	\$ 120.00	30
4	REFOCUS HEADLAMP BEAM	\$ 80.00	x
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

730

TOTAL \$ 2,900.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,604.64
 TOTAL LABOUR COST : \$ 2,900.00
 TOTAL REPAIR COST : \$ 11,504.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian G
 n/s 04/04/23.
 03 Days

Total: 1278.24
 n/s: 1K. ✓