

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0376/2023/EQ  
**DATE** : 17-Apr-23  
**WIP** : 16756

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/4/2023**  
**YOUR INSURED VEH NO : SFL 5009 J**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MS TSANG HIU HUNG  
**ADDRESS** : 91 BUKIT DRIVE  
#09-23  
SINGAPORE 587845  
**TELEPHONE** : HP +65 98479802  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 2070147602-01  
**VEHICLE NO** : **SKC 910 C**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S-TRONIC  
**MODEL YEAR** : 15/10/2020  
**ENGINE NO** : CZD C04420  
**CHASSIS NO** : WAUZZZF36M1004084  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 11-Apr-23  
**PLACE OF ACCIDENT** : CLEMENTI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 910 C**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 4,152.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 910 C**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	REAR BUMPER	1	\$ 1,839.00	
2	REAR BUMPER FIXING PARTS	1	\$ 230.00	
3	REAR BUMPER BRACKET	1	\$ 57.00	
4	REAR BUMPER SPOILER	1	\$ 540.00	
5	REAR BUMPER REFLECTOR - RH	1	\$ 49.00	
6	REAR BUMPER GUIDE SECTION - RH	1	\$ 75.00	
7	REAR WHEEL HOUSING LINER	1	\$ 283.00	
8	REAR WHEEL COVER - LH / RH	2	\$ 598.00	
9	REAR UNDERBODY TRIM - RH	1	\$ 62.00	
10	SUNDRIES		\$ 400.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 4,133.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 4,152.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 8,285.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT