



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 06-05-2023

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SLL6351S

ACCIDENT DATE : 11-04-2023 17:00

THIRD PARTY REF. : SHA6596H

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SLL6351S HONDA SHUTTLE

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BUMPER BEAM (LH)	35.00 <i>bt</i>
1	SIDE SKIRT LH	260.00 <i>de</i>
1	FRONT FENDER SPLASH GUARD LH	35.00 <i>fr</i>
1	ENGINE UNDER COVER (CENTRE)	70.00 <i>de</i>
2	ENGINE UNDER COVER CLIP @\$3.00	6.00 <i>net</i>
		406.00
	ADD 10 %	40.60
	TOTAL (A)	446.60
LABOUR CHARGES		
1	TO RESET AIR BAG SYSTEM,	<i>200</i> 500.00
	TOTAL (D)	500.00
	SUPPLEMENTARY TOTAL	946.60