

KFS Motor

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
VEHICLE NO. : SLL6351S
ACCIDENT DATE : 11-04-2023 17:00
THIRD PARTY REF. : SHA6596H

INVOICE NO : TEST
DATE : 06-05-2023

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE SLL6351S HONDA SHUTTLE

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT SUPPORT PANEL	300.00
1	STEERING AIR BAG	700.00
1	STEERING AIR BAG WIRE	120.00
1	DASHBOARD	550.00
1	DASHBOARD AIR BAG	850.00
2	AIR BAG IMPACT SENSOR@\$60.00	120.00
1	AIR BAG ECU	520.00
2	FRONT SEAT BELT@\$350.00	700.00
1	FRONT FENDER LH	120.00
2	FRONT FENDER SHIELD@\$75.00	150.00
20	FRONT FENDER SHIELD CLIP@\$1.50	30.00
1	FRONT FENDER EXTENSION PANEL OUTER LH	60.00
1	FRONT FENDER EXTENSION PANEL INNER LH	60.00
1	FRONT FENDER EXTENSION BRACKET OUTER LH	35.00
1	FRONT FENDER EXTENSION BRACKET INNER LH	35.00
1	FRONT HEADLAMP LH	1300.00
1	FRONT HEADLAMP LOWER BRACKET LH	30.00
1	FRONT BUMPER	450.00
1	FRONT BUMPER SIDE RETAINER LH	6.00
1	FRONT BUMPER LOWER COVER	95.00
20	FRONT BUMPER CLIP@\$1.50	30.00
1	FRONT SHOCK ABSORBER LH (OEM)	210.00
1	FRONT SHOCK ABSORBER MOUNTING LH	25.00
1	FRONT LOWER ARM LH	115.00
1	FRONT KNUCKLE ARM LH	190.00

VEHICLE NO. : SLL6351S
ACCIDENT DATE : 11-04-2023 17:00
THIRD PARTY REF. : SHA6596H

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT KNUCKLE BEARING LH	65.00
1	FRONT STABILIZER LINK LH	30.00
1	STEERING TIE ROD LH	65.00
1	STEERING TIE ROD END LH	35.00
1	ENGINE CROSS MEMBER	420.00
1	RESONATOR BOX	70.00
1	FRONT BUMPER BEAM (LH)	35.00
1	SIDE SKIRT LH	260.00
1	FRONT FENDER SPLASH GUARD LH	35.00
1	ENGINE UNDER COVER (CENTRE)	70.00
2	ENGINE UNDER COVER CLIP @\$3.00	6.00
		7,892.00
ADD 10 %		
		789.20
TOTAL (A)		
		8,681.20

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO CHECK ALIGNMENT	80.00
1	TO REMOVE/REFIT/REFILL AIR CON GAS	100.00
1	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	150.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	800.00
1	SPRAYPAINTING CHARGES	900.00

VEHICLE NO. : SLL6351S
ACCIDENT DATE : 11-04-2023 17:00
THIRD PARTY REF. : SHA6596H

<u>QTY</u>	<u>PARTS DESCRIPTION</u>
1	TO RESET AIR BAG SYSTEM,

<u>AMOUNT (SG\$)</u>
500.00

TOTAL (D)	2,560.00
TOTAL REPAIR COST :	11,241.20
G S T % :	811.29
EXCESS AMOUNT :	1,100.00
INVOICE AMOUNT :	10,952.49



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 06-05-2023

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SLL6351S

ACCIDENT DATE : 11-04-2023 17:00

THIRD PARTY REF. : SHA6596H

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SLL6351S HONDA SHUTTLE

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT BUMPER BEAM (LH)	35.00
1	SIDE SKIRT LH	260.00
1	FRONT FENDER SPLASH GUARD LH	35.00
1	ENGINE UNDER COVER (CENTRE)	70.00
2	ENGINE UNDER COVER CLIP @\$3.00	6.00
		406.00
	ADD 10 %	40.60
	TOTAL (A)	446.60
LABOUR CHARGES		
1	TO RESET AIR BAG SYSTEM,	500.00
		500.00
	TOTAL (D)	500.00
	SUPPLEMENTARY TOTAL	946.60



簡福星嘜多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000996576	Date of Loss:	11/04/2023
Vehicle Reg. No.:	SLL6351S	Driveable?	
Driver Age/Info:	32 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Injured/Claimant:	TAN JUAY NAM	Contact No:	+6590019765
Driver:	TAN YAN CHING, MAUREEN		

Make/Model:	HONDA SHUTTLE, 1.5 (A)	Vehicle Reg. Date:	02/03/2017
Vehicle Colour:	METALLIC LIME GREEN		
Engine No:	L15B3539126	Chassis No:	GK81007800
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 15

Tan Yan Ching 9749574 9 / 62563561
Not Authorise, Ex 8/100
Resumy before paint
Tan Yan Ching e/hk auto
10 days

Description of Accident/Loss: REFER ATTACHED
Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

17/4/23 @ 230pm

COST OF CLAIMS

	Amount
Parts	12,953.60
Miscellaneous Items	300.00
Labour	1,730.00
Paintwork Labour	1,200.00
Towing	0.00

Calculated Gross Total (\$\$)	16,183.60
- Excess (\$\$)	600.00
(\$\$)	15,583.60
+ GST 8.00% (\$\$)	1,246.69
Nett Amount (\$\$)	16,830.29

This claim is handled by: MT TAN

AIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Apr 2023)
Parts:	N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	X *70.00F
2	1		*FRONT SUPPORT PANEL	0.00	0.00	? *300.00F
3	1		*STEERING AIR BAG	0.00	0.00	act *950.00F 700
4	1		*STEERING AIR BAG WIRE	0.00	0.00	act *235.00F 120
5	1		*DASHBOARD	0.00	0.00	de *550.00F
6	1		*DASHBAORD AIR BAG	0.00	0.00	act *950.00F 850
7	1		*AIR BAG IMPACT SENSOR RH	0.00	0.00	act *65.00F 60
8	1		*AIR BAG IMPACT SENSOR LH	0.00	0.00	act *65.00F 60
9	1		*AIR BAG ECU	0.00	0.00	act *550.00F 520
10	1		*FRONT SEAT BELT RH	0.00	0.00	act *420.00F 350
11	1		*FRONT SEAT BLET LH	0.00	0.00	act *420.00F 350
12	1		*FRONT FENDER LH	0.00	0.00	bt *120.00F
13	1		*FRONT FENDER SHIELD RH	0.00	0.00	m *65.00F 75
14	1		*FRONT FENDER SHIELD LH	0.00	0.00	m *65.00F 75
15	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	new *50.00F 30
16	1		*FRONT FENDER EXTENSION PANEL INNER LH	0.00	0.00	? *100.00F 60
17	1		*FRONT FENDER EXTENSION PANEL OUTER LH	0.00	0.00	bt *100.00F 60
18	1		*FRONT FENDER EXTENSION BRACKET LH	0.00	0.00	bt *95.00F 35
19	1		*FRONT FENDER EXTENSION INNER LH	0.00	0.00	? *95.00F 35
20	1		*FRONT GRILLE	0.00	0.00	? *130.00F
21	1		*FRONT GRILLE CHROME	0.00	0.00	? *130.00F
22	8		*FRONT GRILLE TOP GARNISH CLIP	0.00	0.00	? *20.00F
23	1		*FRONT HEADLAMP LH	0.00	0.00	new *1,400.00F 120
24	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	new *25.00F 30
25	1		*FRONT BUMPER	0.00	0.00	m *450.00F
26	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	de *6.00F
27	1		*FRONT BUMPER FOGLAMP COVER LH	0.00	0.00	de *48.00F
28	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	de *55.00F
29	1		*FRONT BUMPER LOWER COVER	0.00	0.00	de *120.00F 95
30	10		*FRONT BUMPER CLIP	0.00	0.00	new *25.00F 30
31	1		*FRONT SHOCK ABSORBER LH	0.00	0.00	? *200.00F 210
32	1		*FRONT SHOCK ABSORBER MOUNTING LH	0.00	0.00	? *22.00F 25
33	1		*FRONT LOWER ARM LH	0.00	0.00	? *120.00F 115
34	1		*FRONT KNUCKLE ARM LH	0.00	0.00	? *155.00F 190
35	1		*FRONT KNUCKLE BEARING LH	0.00	0.00	? *60.00F 65
36	1		*FRONT STABILIZER LINK LH	0.00	0.00	? *35.00F 30
37	1		*FRONT DIRVE SHAFT LH	0.00	0.00	X *650.00F
38	1		*STEERING RACK AND PINION	0.00	0.00	? *950.00F
39	1		*STEERING TIE ROD LH	0.00	0.00	? *75.00F 65
40	1		*STEERING TIE ROD END LH	0.00	0.00	? *50.00F 35
41	1		*ENGINE CROSS MEMBER	0.00	0.00	? *400.00F 420
42	1		*RESONATOR BOX	0.00	0.00	new *80.00F 70
43	1		*RESONATOR BOX	0.00	0.00	? *25.00F
44	1		*AIR CON CONDENSER	0.00	0.00	X *480.00F
45	1		*RADIATOR	0.00	0.00	X *700.00F

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*ABS SENSOR	0.00	0.00	<i>act</i> 1130.00 F
Franchise part.					
Sub Total (\$\$)					11,776.00
+ Margin on L,N Items 10.00% (\$\$)					1,177.60
Total Parts (\$\$)					12,953.60

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 FRONT TYRE LH	300.00
Sub Total (S\$) <i>out</i>		300.00
		<i>80%</i>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New <i>900</i>	1,200.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New <i>30</i>	50.00
3	TO CHECK ALIGNMENT	New <i>80</i>	120.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New <i>1000</i>	120.00
5	TO REMOVE/REFIT FRONT UNDERCARRIAGE LH	New <i>1500</i>	160.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New <i>800</i>	1,280.00
Gross Labour Cost (S\$)			2,930.00

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >