



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8883

check with Taufik

*Taufik agreed
+ 100%

T

1976

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000996576	Date of Loss:	11/04/2023
Vehicle Reg. No.:	SLL6351S	Driveable?	
Driver Age/Info:	32 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Injured/Claimant:	TAN JUAY NAM	Contact No:	+6590019765
Driver:	TAN YAN CHING, MAUREEN		

Make/Model:	HONDA SHUTTLE, 1.5 (A)
Vehicle Colour:	METALLIC LIME GREEN
Engine No:	L15B3539126
Odometer:	0 KM

Vehicle Reg. Date:	02/03/2017
Chassis No:	GK81007800

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	15

Taufik 9749574 9 / 62563861
Not Authorise, Ex \$1100
Resumy before paint
taufik e/ku authorise
10 days

Description of Accident/Loss	REFER ATTACHED
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)

17/4/23 @ 230pm

COST OF CLAIMS

	Amount
Parts	12,953.60
Miscellaneous Items	300.00
Labour	1,730.00
Paintwork Labour	1,200.00
Towing	0.00

Calculated Gross Total (S\$)	16,183.60
- Excess (S\$)	600.00
(S\$)	15,583.60
+ GST 8.00% (S\$)	1,246.69
Nett Amount (S\$)	16,830.29

This claim is handled by: MT TAN

AIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Apr 2023)
Parts:	N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	X *70.00F M
2	1		*FRONT SUPPORT PANEL	0.00	X 0.00	? *300.00F bt
3	1		*STEERING AIR BAG	0.00	X 0.00	act *950.00F 700
4	1		*STEERING AIR BAG WIRE	0.00	X 0.00	act *235.00F 120
5	1		*DASHBOARD	0.00	X 0.00	de *550.00F
6	1		*DASHBAORD AIR BAG	0.00	X 0.00	act *950.00F 850
7	1		*AIR BAG IMPACT SENSOR RH	0.00	X 0.00	act *65.00F 60
8	1		*AIR BAG IMPACT SENSOR LH	0.00	X 0.00	act *65.00F 60
9	1		*AIR BAG ECU	0.00	X 0.00	act *550.00F 520
10	1		*FRONT SEAT BELT RH	0.00	X 0.00	act *420.00F 350
11	1		*FRONT SEAT BLET LH	0.00	X 0.00	act *420.00F 350
12	1		*FRONT FENDER LH	0.00	X 0.00	bt *120.00F
13	1		*FRONT FENDER SHIELD RH	0.00	X 0.00	m *65.00F 75
14	1		*FRONT FENDER SHIELD LH	0.00	X 0.00	m *65.00F 75
15	20		*FRONT FENDER SHIELD CLIP	0.00	X 0.00	new *50.00F 30
16	1		*FRONT FENDER EXTENSION PANEL INNER LH	0.00	X 0.00	bt? *100.00F 60
17	1		*FRONT FENDER EXTENSION PANEL OUTER LH	0.00	X 0.00	bt? *100.00F 60
18	1		*FRONT FENDER EXTENSION BRACKET LH	0.00	X 0.00	bt? *95.00F 35
19	1		*FRONT FENDER EXTENSION INNER LH	0.00	X 0.00	bt? *95.00F 35
20	1		*FRONT GRILLE	0.00	0.00	? *130.00F X un
21	1		*FRONT GRILLE CHROME	0.00	0.00	? *130.00F X un
22	8		*FRONT GRILLE TOP GARNISH CLIP	0.00	0.00	? *20.00F X un
23	1		*FRONT HEADLAMP LH	0.00	X 0.00	un *1,400.00F 1300
24	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	X 0.00	un *25.00F 30
25	1		*FRONT BUMPER	0.00	X 0.00	m *450.00F
26	1		*FRONT BUMPER SIDE RETAINER LH	0.00	X 0.00	de *6.00F
27	1		*FRONT BUMPER FOGLAMP COVER LH	0.00	0.00	de *48.00F X un
28	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	de *55.00F X un
29	1		*FRONT BUMPER LOWER COVER	0.00	X 0.00	de *120.00F 95
30	10		*FRONT BUMPER CLIP	0.00	X 0.00	un *25.00F 30
31	1		*FRONT SHOCK ABSORBER LH	X 0.00	bt 0.00	? *200.00F 210
32	1		*FRONT SHOCK ABSORBER MOUNTING LH	X 0.00	bt 0.00	? *22.00F 25
33	1		*FRONT LOWER ARM LH	X 0.00	bt 0.00	? *120.00F 115
34	1		*FRONT KNUCKLE ARM LH	X 0.00	bt 0.00	? *155.00F 190
35	1		*FRONT KNUCKLE BEARING LH	X 0.00	bt 0.00	? *60.00F 65
36	1		*FRONT STABILZIER LINK LH	X 0.00	bt 0.00	? *35.00F 30
37	1		*FRONT DIRVE SHAFT LH	0.00	0.00	X *650.00F un
38	1		*STEERING RACK AND PINION	0.00	0.00	? *950.00F un
39	1		*STEERING TIE ROD LH	0.00	X 0.00	bt *75.00F 65
40	1		*STEERING TIE ROD END LH	0.00	X 0.00	bt *50.00F 35
41	1		*ENGINE CROSS MEMBER	0.00	X 0.00	bt *400.00F 420
42	1		*RESONATOR BOX	0.00	X 0.00	un *80.00F 70
43	1		*RESONATOR BOX	0.00	0.00	X *25.00F un
44	1		*AIR CON CONDENSER	0.00	0.00	X *480.00F un
45	1		*RADIATOR	0.00	0.00	X *700.00F un

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*ABS SENSOR	0.00	0.00	alt 130.00 <i>kin.</i>
Franchise part.					
Sub Total (\$\$)					11,776.00
+ Margin on L,N Items 10.00% (\$\$)					1,177.60
Total Parts (\$\$)					12,953.60

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT TYRE LH

~~300.00~~

Sub Total (\$\$) *ant* 300.00

85% XHM

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New *900* 1,200.00

Labour Items

2 TO CHECK WIRING SYSTEM

New *30* 50.00

3 TO CHECK ALIGNMENT

New *80* 120.00

4 TO REMOVE/REFIT/REFILL AIR CON GAS

New *1000* 120.00

5 TO REMOVE/REFIT FRONT UNDERCARRIAGE LH

New *1500* 160.00

TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING
NEW PARTS

New *800* 1,280.00

Gross Labour Cost (\$\$)

2,930.00

Kan Fook Sing Motor Workshop/SLL6351S/14/04/2023 13:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 06-05-2023

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SLL6351S

ACCIDENT DATE : 11-04-2023 17:00

THIRD PARTY REF. : SHA6596H

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SLL6351S HONDA SHUTTLE

QTY	PARTS DESCRIPTION
1	FRONT BUMPER BEAM (LH)
1	SIDE SKIRT LH
1	FRONT FENDER SPLASH GUARD LH
1	ENGINE UNDER COVER (CENTRE)
2	ENGINE UNDER COVER CLIP @\$3.00

AMOUNT (SG\$)

✓	35.00	bt
✓	260.00	de
✓	35.00	fr
	70.00	de
✓	6.00	nt

406.00

ADD 10 %

40.60

TOTAL (A)

446.60

LABOUR CHARGES

1 TO RESET AIR BAG SYSTEM,

200
500.00 200

TOTAL (D)

500.00

SUPPLEMENTARY TOTAL

946.60