

KBS Motorsports Pte Ltd



YOUR REF.: SME5354R
OUR REF.: SNE8238L

*Not Notified
Remy B4pam
5 days*

TO: ALLIANZ INSURANCE
CC: Claims Services Department

DATE: 13/4/2023
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA YARIS CROSS
1.5X B-PACKAGE CVT
CHASSIS NO.: MXPB102018717
ENGINE NO.: M15AY319085
YEAR MADE: 2022
ACCIDENT DATE: 3 April 2023

FAX:

ESTIMATE FOR VEHICLE NO.: SNE8238L

NO.	DESCRIPTION	QTY.	LIST PRICE
1	REAR WINDSCREEN	1	\$ 1,800.00 X
2	REAR WINDSCREEN MOULDING	1	\$ 250.00 ✓
3	TAILGATE	1	\$ 1,500.00 ✓
4	TAILGATE WEATHERSTRIP	1	\$ 370.00 X
5	TAILGATE TRIM	1	\$ 250.00 X
6	TAILGATE HANDLE PULL	1	\$ 65.00 X
7	TAILGATE CUSHION	1	\$ 20.00 X
8	TAILGATE LICENSE PLATE CUSHION	1	\$ 50.00 X
9	TAILGATE LICENSE PLATE LAMP	1	\$ 250.00 X
10	TAILGATE GARNISH	1	\$ 150.00 X
11	TAILGATE BOARD TRIM	1	\$ 800.00 X
12	TAILGATE HINGE LH	1	\$ 130.00 X
13	TAILGATE HINGE RH	1	\$ 130.00 Y
14	TAILGATE STAY LH	1	\$ 200.00 X
15	TAILGATE STAY RH	1	\$ 200.00 X
16	TAILGATE UPPER DAMPER STAY BRACKET LH	1	\$ 180.00 X
17	TAILGATE LOWER DAMPER STAY BRACKET LH	1	\$ 180.00 X
18	TAILGATE UPPER DAMPER STAY BRACKET RH	1	\$ 180.00 X
19	TAILGATE LOWER DAMPER STAY BRACKET RH	1	\$ 180.00 X
20	TAILGATE LOCK	1	\$ 450.00 ?
21	TAILGATE LOCK STRIKER	1	\$ 110.00 X
22	TAILGATE LAMP LH	1	\$ 250.00 X
23	TAILGATE LAMP RH	1	\$ 250.00 X
24	TAILGATE TOYOTA LOGO	1	\$ 110.00 X
25	TAILGATE "YARIS" EMBLEM	1	\$ 100.00 ✓
26	TAILGATE "CROSS" EMBLEM	1	\$ 110.00 ✓
27	TAIL LAMP LH	1	\$ 450.00 X

28	TAIL LAMP RH	1	\$	RM	450.00	X
29	CENTER STOP LAMP	1	\$	RM	550.00	X
30	REAR BUMPER	1	\$	RM	800.00	✓
31	REAR BUMPER SIDE SEAL LH	1	\$	RM	110.00	X
32	REAR BUMPER SIDE SEAL RH	1	\$	RM	110.00	X
33	REAR BUMPER RETAINER LH	1	\$	RM	110.00	X
34	REAR BUMPER RETAINER RH	1	\$	RM	110.00	X
35	REAR BUMPER REINFORCEMENT	1	\$	NIR	650.00	X
36	REAR BUMPER LOWER SPOILER	1	\$	RM	780.00	✓
37	REAR BUMPER SENSOR	2	\$		500.00	?
38	REAR BUMPER CLIP	10	\$	RM	50.00	✓
39	REAR REFLECTOR LH	1	\$	RM	90.00	X
40	REAR REFLECTOR RH	1	\$	RM	90.00	X
41	END PANEL	1	\$	RM	600.00	X
42	END PANEL TOP GARNISH	1	\$	RM	180.00	X
43	SPARE TYRE PANEL	1	\$	RM	550.00	X
44	SPARE TYRE TOP COVER	1	\$	RM	300.00	X
TOTAL:				\$	14,745.00	
LESS 25%:				\$	(3,686.25)	
PARTS TOTAL:				\$	11,058.75	

SPECIAL NETT

BODY SEALANT	1	\$	RM	80.00	X
REAR NUMBER PLATE & HOLDER	1	\$	RM	60.00	X
CUSTOMISED DETAILING (3 LAYERS)	1	\$	?	900.00	
WINDSCREEN SEALANT	1	\$	RM	80.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	1,600.00	
TO REMOVE & REPLACE REAR WINDSCREEN	\$	120.00	✓
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	\$	60.00	✓
TO REMOVE & REFIT ALL SENSOR	\$	50.00	✓
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE	\$	60.00	✓
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	200.00	✓
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	250.00	X
TO APPLY ANTI RUST COATING	\$	30.00	
TO SPRAY PAINTING ON THE AFFECTED AREA	\$	800.00	
TOTAL:	\$	15,928.75	
8% GST:	\$	1,274.30	
GRAND TOTAL:	\$	17,203.05	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature of Repairer