



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG1256U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 64316
Reg No/Reg Date SNG1256U / 13/11/2020
Date In/Mileage 0
Chassis No W1K1770842J2866595
Engine No 28291480397305
Make/Model MB/A 180 COMPACT SALOON
Colour/Trim 021 149 Polar White/ 041 111 Leather Bla

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	14/04/2023/ 16:35	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : SP200463150-01 / 13.04.2023 TOW IN/EXCESS : 4.04.2023 // DATE IN/DATE SURVEY: 14.04.2023 // BY/AUTHORIZED ON :				162.00
S BPNTOW ACCIDENT TOWING FROM 25 KAKI BUKIT RD 4,05-23 (MSCP) TO PLSC USING: KING DOLLEY REFER TO: 1318290				380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	15.00
M BPNSUN SUNDRIES				60.00
S BPNSUB SUPPLY 1 SET NUMBER PLATE WITH HOUSING NETT FRONT				120.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS : NETT				960.00
A BPILAB REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS- VACUUM AND RE-GAS. NETT				4800.00
A BPILAB PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				4000.00
A BPIRES RESPRAY ON BONNET, FRONT BUMPER, RH/LH FRONT FENDER, AND ACCIDENT AFFECTED AREA			0.02	
M LEFT FENDER FRONT	1.00	678.54	00.00	678.54
M RIGHT FENDER FRONT	1.00	678.54	00.00	678.54
M LHF FENDER EDGE GUARD	1.00	11.62	00.00	11.62
M RIGHT FRONT FENDER EDGE GUARD	1.00	11.31	00.00	11.31
M RHF FENDER OUTER LINEAR	1.00	234.98	00.00	234.98

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG1256U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No **64316**
Reg No/Reg Date **SNG1256U / 13/11/2020**
Date In/Mileage **0**
Chassis No **WUK1770842J2866595**
Engine No **28291480397305**
Make/Model **MB/A 180 COMPACT SALOON**
Colour/Trim **021 149 Polar White/ 041 111 Leather Bla**

SNG1256U

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	14/04/2023/ 16:35	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LHF FENDER LOWER COVER, WHEEL ARCH	1.00	30.79	00.00	30.79
M RHF FENDER LOWER COVER, WHEEL ARCH	1.00	30.79	00.00	30.79
M COVER, LHF FENDER	1.00	62.20	00.00	62.20
M BRACKET, LHF FENDER	1.00	42.50	00.00	42.50
M BRACKET, RHF FENDER	1.00	42.57	00.00	42.57
M COMPANY SIGN	1.00	81.64	00.00	81.64
M FRONT BUMPER	1.00	1262.84	00.00	1262.84
M ENG LOWER COVER SUPPORT	1.00	303.77	00.00	303.77
M IMPACT ABSORBER	1.00	164.61	00.00	164.61
M UPP CTR BASIC CARRIER FOR BUMPER	1.00	173.09	00.00	173.09
M UPP LHF BASIC CARRIER FOR BUMPER	1.00	100.84	00.00	100.84
M UPP RHF BASIC CARRIER FOR BUMPER	1.00	100.84	00.00	100.84
M ELECTRICAL WIRING HARNESS	1.00	165.55	00.00	165.55
M PRESSURE SENSOR	1.00	218.01	00.00	218.01
M INNER DISTANCE SENSOR	4.00	205.45	00.00	821.80
M OUTER DISTANCE SENSOR	2.00	205.45	00.00	410.90
M SPACER RING	6.00	7.85	00.00	47.10
M LHF BASIC CARRIER FOR BUMPER	1.00	91.41	00.00	91.41
M RHF BASIC CARRIER FOR BUMPER	1.00	78.66	00.00	78.66
M RIVET	2.00	6.09	00.00	12.18
M UPP LHF MOUNTING RAIL-SMALL	1.00	15.39	00.00	15.39
M UPP RHF MOUNTING RAIL-SMALL	1.00	16.96	00.00	16.96
M UPP LHF MOUNTING RAIL-BIG	1.00	16.02	00.00	16.02
M UPP RHF MOUNTING RAIL-BIG	1.00	16.02	00.00	16.02
M RADAR SENSOR	1.00	1233.72	00.00	1233.72
M MOUNT RADAR	1.00	50.58	00.00	50.58
M FRONT BUMPER LOWER GRILLE	1.00	144.82	00.00	144.82
M LICENSE PLATE HOLDER	1.00	102.10	00.00	102.10
M LHF HEADLAMP UNIT	1.00	3180.29	00.00	3180.29
M RHF HEADLAMP UNIT	1.00	3180.29	00.00	3180.29
M LHF HEADLIGHT CONTROL UNIT, COMPLETE	1.00	525.24	00.00	525.24
M RHF HEADLIGHT CONTROL UNIT, COMPLETE	1.00	525.24	00.00	525.24
M LEFT WATER DEFLECTOR	1.00	81.68	00.00	81.68

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNG1256U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 64316
Reg No/Reg Date SNG1256U / 13/11/2020
Date In/Mileage 0
Chassis No W1K1770842J2366595
Engine No 28291480397305
Make/Model MB/A 180 COMPACT SALOON
Colour/Trim 021 149 Polar White/ 041 111 Leather Bla

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	14/04/2023/ 16:35	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M FRONT SUPPORT CONNECTING CARRIER	1.00	713.10	00.00	713.10
M CROSS MEMBER	1.00	442.50	00.00	442.50
M RIGHT AIR DUCT	1.00	50.11	00.00	50.11
M LHF/RHF ABSORBER	2.00	153.21	00.00	306.42
M LHF CONNECTING CARRIER	1.00	62.95	00.00	62.95
M RHF CONNECTING CARRIER	1.00	62.95	00.00	62.95
M THREADED HOLE PLATE	2.00	17.59	00.00	35.18
M LHF/RHF MOUNT	2.00	14.14	00.00	28.28
M LHF STRUT	1.00	24.97	00.00	24.97
M RHF STRUT	1.00	24.97	00.00	24.97
M HOOD	1.00	1610.19	00.00	1610.19
M LHF HINGE	1.00	89.22	00.00	89.22
M RHF HINGE	1.00	89.22	00.00	89.22
M BONNET ACTUATOR	2.00	221.78	00.00	443.56
M LIMIT SWITCH	1.00	124.09	00.00	124.09
M STOP BUFFER	2.00	31.10	00.00	62.20
M SPRING ELEMENT	1.00	47.12	00.00	47.12
M LATCH, LOWER PART	1.00	169.32	00.00	169.32
M LOCK UPPER PART	1.00	54.66	00.00	54.66
M RADIATOR TRIM	1.00	832.47	00.00	832.47
M STAR CARRIER TRIM STRIP-SILVER	1.00	252.88	00.00	252.88
M LH CHROME TRIM STRIP	1.00	58.43	00.00	58.43
M RH CHROME TRIM STRIP	1.00	63.46	00.00	63.46
M STAR CARRIER	1.00	162.69	00.00	162.69
M LOWER AIR DUCT SEGMENT	1.00	138.57	00.00	138.57
M UPP AIR DUCT SEGMENT	1.00	132.10	00.00	132.10
M LOWER AIR DUCT MOUNT	1.00	61.57	00.00	61.57
M RAD. LOWER AIR DUCT SEGMENT	1.00	59.37	00.00	59.37
M CONDENSER	1.00	1171.74	00.00	1171.74
M AIR DUCT SEGMENT	1.00	49.32	00.00	49.32
M RADIATOR	1.00	1280.78	00.00	1280.78
M BLOWER	1.00	836.87	00.00	836.87

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Pass
Ap 5000008
7 days
17/04/23 @ 1610
EXCERS: 3100
Revert
Repay before
paint

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Nett 34,983.69
8% GST on 34983.69 2798.70
Total Payable 37,782.39

Validity of this estimate is 14 days. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. If additional or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg