

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000035(00)

DATE : 14/04/2023

POLICY NO : SP2003905032

VEH REG NO : PC9349E

MAKE/MODEL : MERCEDES BENZ SPRINTER
316CDI 4X2 3665 HIGH ROOF

CHASSIS NO : W1V9076332P203783

ENGINE NO : 65195835233790

REG. DATE : 2019

Estimate Repair Cost to Vehicle No.: PC9349E

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Steering air bag <i>Repl</i>	1	0.00	0.00
2 Passenger air bag <i>Repl</i>	1	0.00	0.00
3 Front safety belt - RH <i>Repl</i>	1	0.00	0.00
4 Air bag control unit <i>Repl</i>	1	0.00	0.00
5 Front safety belt - LH <i>Repl</i>	1	0.00	0.00
6 Battery cut off switch <i>Repl</i>	1	0.00	0.00
7 Front windscreen <i>Repl</i>	1	0.00	0.00
8 Front wiper arm - LH <i>Repl</i>	1	0.00	0.00
9 Bonnet <i>Repl</i>	1	0.00	0.00
10 Bonnet insulation <i>Repl</i>	1	0.00	0.00
11 Bonnet hinges - LH / RH <i>Repl</i>	2	0.00	0.00
12 Bonnet garnish - LH <i>Repl</i>	1	0.00	0.00
13 Bonnet centre lock level <i>Repl</i>	1	0.00	0.00
14 Bonnet cable <i>Repl</i>	1	0.00	0.00
15 Bonnet seal - upper <i>Repl</i>	1	0.00	0.00
16 Bonnet seal - lower <i>Repl</i>	1	0.00	0.00
17 Bonnet lock <i>Repl</i>	1	0.00	0.00
18 Bonnet lock panel <i>Repl</i>	1	0.00	0.00
19 Front fender - LH <i>Repl</i>	1	0.00	0.00
20 Front fender inner shield - LH <i>Repl</i>	1	0.00	0.00
21 Front bumper <i>Repl</i>	1	0.00	0.00
22 Front bumper reinforcement <i>Repl</i>	1	0.00	0.00
23 Front bumper fog lamp cover - RH / LH <i>Repl</i>	2	0.00	0.00
24 Front bumper fog lamp - RH / LH <i>Repl</i>	2	0.00	0.00
25 Front number plate garnish <i>Repl</i>	1	0.00	0.00
26 Front bumper towing cover <i>Repl</i>	1	0.00	0.00
27 Front bumper side retainer - RH / LH <i>Repl</i>	2	0.00	0.00
28 Front bumper step garnish - LH <i>Repl</i>	1	0.00	0.00
29 Front bumper sensor <i>Repl</i>	6	0.00	0.00
30 Front bumper sensor harness <i>Repl</i>	1	0.00	0.00
31 Headlamp assy - RH / LH <i>Repl</i>	2	0.00	0.00
32 Support Panel <i>Repl</i>	1	0.00	0.00
33 Engine sub frame <i>Repl</i>	1	0.00	0.00

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 24/03/2023

ESTIMATE

NO : QUOT202304-000035(00)

DATE : 14/04/2023

POLICY NO : SP2003905032

VEH REG NO : PC9349E

MAKE/MODEL : MERCEDES BENZ SPRINTER
316CDI 4X2 3665 HIGH ROOF

CHASSIS NO : W1V9076332P203783

ENGINE NO : 65195835233790

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : PC9349E

Description	Quantity	Unit Price	Amount
		S\$	S\$
34 front chassis frame - RH / LH <i>Rx</i>	2	0.00	0.00
35 Steering rack & pinion <i>?</i>	1	0.00	0.00
36 Air-con condenser <i>BA</i>	1	0.00	0.00
37 Radiator assy <i>BA</i>	1	0.00	0.00
38 Radiator fan motor assy <i>CRA</i>	1	0.00	0.00
39 Radiator spare tank <i>BA</i>	1	0.00	0.00
40 Radiator fan cowlng <i>?</i>	1	0.00	0.00
41 Radiator top hose <i>?</i>	1	0.00	0.00
42 Radiator bottom hose <i>?</i>	1	0.00	0.00
43 Inter-cooler assy <i>BA</i>	1	0.00	0.00
44 Front shock absorber - RH / LH <i>?</i>	2	0.00	0.00
45 Front lower arm - RH / LH <i>ols BA nls? 4</i>	2	0.00	0.00
46 Front knuckle arm - RH / LH <i>nls BA ols? 4</i>	2	0.00	0.00
47 Front wheel rim - LH <i>BA</i>	1	0.00	0.00
48 Rear wheel rim - LH <i>BA</i>	1	0.00	0.00
49 Front tyre - LH <i>pu 808m</i>	1	0.00	0.00
50 Rear tyre - LH <i>pu 608m</i>	1	0.00	0.00
51 Front wheel hub cap - LH <i>nls</i>	1	0.00	0.00
52 Rear wheel hub cap - LH <i>nls</i>	1	0.00	0.00
53 Sliding door stepboard - LH <i>BA</i>	1	0.00	0.00
54 Washer tank <i>?</i>	1	0.00	0.00
55 Air-cleaner assy <i>CRA</i>	1	0.00	0.00
56 Engine mountings <i>?</i>	2	0.00	0.00
57 Gear box mounting <i>?</i>	1	0.00	0.00
58 Steering tie-rod - LH <i>?</i>	1	0.00	0.00
59 Steering tie-rod end - LH <i>?</i>	1	0.00	0.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			0.00
Add 10%			0.00
TOTAL			S\$ 0.00
ADD GST @ 8%			0.00
GRAND TOTAL			S\$ 0.00

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR THREE HUNDRED FORTY-NINE AND CENTS TWENTY-SEVEN ONLY