

ASS. REC. BY:

REF:

F02/23.003940tkv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. D23001270MFVS

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YP 687LP

Yr Regn:

03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A)

Make:

Zuzu NHR #5

c.c

3193

Colour

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

393293

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JAANPR 73K-177101486

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: N/A S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/85R16 (O)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

d

mm

R/Bal.

9 9

mm

L/Bal.

d

mm

L/Bal.

9 9

mm

D.O.A.

10/4/23

D.O.I.

17/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Unable to search for DOR. LRA abat \$17,154.00

2016 L/Ry @ 20,300k Cash (red 52,143.35, 71%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 16

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: OD

Lump Sum / T.B.T. (\$ 20,300

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/04/2023 16:45 (SGT)
Reported by	Actual Driver
Date of Accident	10/04/2023 19:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	OLD UPPER THOMSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6878P
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Company Reg No	2XXXXX882K
Email Address	JEREMYC_QUEK@CERTISGROUP.COM
Mobile Phone No	(Phone) +65-68428849
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	Nhr69e
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3000

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	-

DRIVER

Name of Driver	KALITHASAN S/O MUTHUSAMY RAMASAMY
NRIC No	SXXXX612J
Date Of Birth	10/10/1976
Occupation	Outdoor

Date Of Driving Pass	04/12/2010
Driving experience	12 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94558525
Alt. Phone Number	-
Email Address	JEREMYC_QUEK@CERTISGROUP.COM
Address	267 BUKIT BATOK EAST AVE 4 #03-194
Address complement	-
Postcode	650267
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	RAHMAN BIN IBRAHIM
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio Division Headquarters
Police Station Phone No	(Phone) +65-18002180000
Alt. Police Station Phone No	(Fax) +65-64814246
Police Station Address	51 Ang Mo Kio Avenue 9 Singapore 569784
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6107G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SECTION PLAN

IMPORTANT NOTICE

1. This sketch plan is a preliminary drawing of the accident scene. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

2. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

3. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

4. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

5. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

6. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

7. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

8. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

9. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

10. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

11. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

12. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

13. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

14. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.

15. The sketch plan is based on the information provided by the witnesses and the police. It is not a final report and should not be used for legal purposes. It is intended for use as a reference only.



Duration Circumstance of the Accident

Sketch Plan #2

Direction

See sketch 1 for description of road and location of accident

Accident Date

Accident Time



SINGAPORE
POLICE FORCE



F/20230410/7090

1 of 1

POLICE REPORT (NP299)

Report No. F/20230410/7090

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
589784
Tel No: 1300-2180000

Date/Time Report Made 10/04/2023 23 42	Video Report No.	Station Diary No.
Name Of Informant KALITHASAN S/O MUTHUSAMY RAMASAMY	Address 267 BUKIT BATOK EAST AVENUE 4 #03-194 SINGAPORE 650267	
ID Type / ID No NRIC NO / S7631612J	Contact No Home/Office	Mobile 94558525
Nationality SINGAPORE CITIZEN	Email Address kalithasan@live.com.sg	
Occupation Senior recovery officer	Sex Male	Age 46
Institution/School Name	Date of Birth 10/10/1976	Race Indian
Date/Time Of Incident 10/04/2023 19:00	Location Of Incident OLD UPPER THOMSON ROAD	

Brief details.

I was driving along SLE towards BKE. I was on the lane 4. VEHICLE XD6107G was driving in front of me had E-Brake in front of me and I did not have enough time to react as there was no brake lights coming from him and it was drizzling and the road was wet as such I had collided into him. No one was injured and no damage to the vehicle I had collided into.

I am lodging this report as my company requested for it.

Signature Of Officer Recording The Report Not applicable	Signature Of Informant The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter Not applicable	Date/Time 10/04/2023 23 42
Officer In-Charge Of Case	Classification Of Case

Not Notified
1/1pm &
Mercury After Rain
Ex @ 3000p

TO : MS FIRST CAPITAL INSURANCE LTD

ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SMP472H

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD

CONTACT : _____

ADDRESS : _____

VEHICLE NO. YP6878P TRANS

CHASSIS NO. : _____

MAKE / MODEL : ISUZU

ENGINE NO. : _____

OWNER'S INSURER : FIRST CAPITAL

JOB-CODE : OD S/A : JOEY

ACCIDENT DATE : 10-Apr-23

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	MARK UP	DISC-PRICE	SUR	EV. PRIC
1	FRONT BUMPER	B ₁ 1.00	\$ 1,170.00	15.00	\$ 1,345.50	Y	✓
2	FRONT BUMPER BRACKET RH	B ₂ 1.00	\$ 250.00	15.00	\$ 287.50	Y	✓
3	FRONT BUMPER BRACKET LH	B ₃ 1.00	\$ 250.00	15.00	\$ 287.50	Y	✓
4	FRONT BUMPER FOG LAMP LH	S ₄ 1.00	\$ 305.00	15.00	\$ 350.75	Y	X
5	FRONT BUMPER FOG LAMP RH	S ₅ 1.00	\$ 305.00	15.00	\$ 350.75	Y	X
6	HEADLAMP LH	mgcm S ₆ 1.00	\$ 750.00	15.00	\$ 862.50	Y	X
7	HEADLAMP RH	S ₇ 1.00	\$ 750.00	15.00	\$ 862.50	Y	X
8	HEADLAMP LOWER GARNISH LH	S ₈ 1.00	\$ 280.00	15.00	\$ 322.00	Y	X
9	HEADLAMP LOWER GARNISH RH	S ₉ 1.00	\$ 280.00	15.00	\$ 322.00	Y	X
10	HEADLAMP BRACKET LH	S ₁₀ 1.00	\$ 150.00	15.00	\$ 172.50	Y	X
11	HEADLAMP BRACKET RH	S ₁₁ 1.00	\$ 150.00	15.00	\$ 172.50	Y	X
12	HEADLAMP WIRE HARDNESS LH	S ₁₂ 1.00	\$ 220.00	15.00	\$ 253.00	Y	X
13	HEADLAMP WIRE HARDNESS RH	S ₁₃ 1.00	\$ 220.00	15.00	\$ 253.00	Y	X
14	FRONT GRILLE	CM 1.00	\$ 480.00	15.00	\$ 552.00	Y	✓
15	FRONT PANEL TOP	B ₁₅ 1.00	\$ 1,050.00	15.00	\$ 1,207.50	Y	✓
16	FRONT PANEL BOTTOM	B ₁₆ 1.00	\$ 865.00	15.00	\$ 994.75	Y	✓
17	FRONT CORNER PANEL LH	CM 1.00	\$ 650.00	15.00	\$ 747.50	Y	✓
18	FRONT CORNER PANEL RH	CM 1.00	\$ 650.00	15.00	\$ 747.50	Y	✓
19	FRONT CORNER PANEL TOP COVER LH	mi 1.00	\$ 95.00	15.00	\$ 109.25	Y	✓
20	FRONT CORNER PANEL TOP COVER RH	mi 1.00	\$ 95.00	15.00	\$ 109.25	Y	✓
21	FRONT WING MIRROR LH	mi 1.00	\$ 350.00	15.00	\$ 402.50	Y	✓
22	FRONT WING MIRROR BRACKET COVER LH	mi 1.00	\$ 250.00	15.00	\$ 287.50	Y	✓
23	FRONT WING MIRROR BRACKET LH	mi 1.00	\$ 420.00	15.00	\$ 483.00	Y	✓

24	FRONT WING MIRROR RH	<i>Sm</i>	1.00	\$	350.00	15.00	\$	402.50	Y	X
25	FRONT WING MIRROR BRACKET COVER RH	<i>Sm</i>	1.00	\$	250.00	15.00	\$	287.50	Y	X
26	FRONT WING MIRROR BRACKET RH	<i>R</i>	1.00	\$	420.00	15.00	\$	483.00	Y	X
27	FRONT WINDSCREEN GLASS	<i>CM</i>	1.00	\$	1,350.00	15.00	\$	1,552.50	Y	✓
28	FRONT WINDSCREEN MOULDING TOP	<i>Rm</i>	1.00	\$	190.00	15.00	\$	218.50	Y	✓
29	FRONT WINDSCREEN MOULDING BOTTOM	<i>Rm</i>	1.00	\$	150.00	15.00	\$	172.50	Y	✓
30	FRONT WIPER PANEL	<i>Apical</i>	1.00	\$	1,191.00	15.00	\$	1,369.65	Y	X
31	FRONT WIPER GARNISH	<i>NIP</i>	1.00	\$	650.00	15.00	\$	747.50	Y	X
32	FRONT WIPER ARM LH	<i>R</i>	1.00	\$	300.00	15.00	\$	345.00	Y	✓
33	FRONT WIPER ARM RH	<i>R</i>	1.00	\$	300.00	15.00	\$	345.00	Y	✓
34	FRONT WINDSCREEN NOZZLE LH	<i>Sm</i>	1.00	\$	102.00	15.00	\$	117.30	Y	X
35	FRONT WINDSCREEN NOZZLE RH	<i>Sm</i>	1.00	\$	102.00	15.00	\$	117.30	Y	X
36	FRONT ROOF TOP PANEL	<i>R</i>	1.00	\$	4,280.00	15.00	\$	4,922.00	Y	X
37	FRONT ROOF LINING		1.00	\$	1,680.00	15.00	\$	1,932.00	Y	X
38	FRONT DOOR RH	<i>Bu</i>	1.00	\$	910.00	15.00	\$	1,046.50	Y	✓
39	FRONT DOOR TRIM BOARD RH	<i>CM</i>	1.00	\$	550.00	15.00	\$	632.50	Y	✓
40	FRONT DOOR RUBBER RH	<i>Gr</i>	1.00	\$	230.00	15.00	\$	264.50	Y	50/100
41	FRONT DOOR SIGNAL LAMP RH	<i>Sm</i>	1.00	\$	189.00	15.00	\$	217.35	Y	X
42	FRONT DOOR PROTECTOR RH	<i>Sm</i>	1.00	\$	295.00	15.00	\$	339.25	Y	X
43	FRONT DOOR LOWER GARNISH RH	<i>Sm</i>	1.00	\$	280.00	15.00	\$	322.00	Y	X
44	FRONT DOOR HINGE UPPER RH		1.00	\$	468.00	15.00	\$	538.20	Y	✓
45	FRONT DOOR HINGE LOWER RH	<i>R</i>	1.00	\$	388.00	15.00	\$	446.20	Y	X
46	FRONT DOOR CHANNEL RH	<i>D/I</i>	1.00	\$	380.00	15.00	\$	437.00	Y	✓
47	FRONT DOOR PILLAR INNER RH	<i>R</i>	1.00	\$	680.00	15.00	\$	782.00	Y	✓
48	FRONT DOOR PILLAR OUTER RH	<i>R</i>	1.00	\$	750.00	15.00	\$	862.50	Y	✓
49	FRONT DOOR LH	<i>Bu</i>	1.00	\$	910.00	15.00	\$	1,046.50	Y	✓
50	FRONT DOOR TRIM BOARD LH	<i>CM</i>	1.00	\$	550.00	15.00	\$	632.50	Y	✓
51	FRONT DOOR RUBBER LH	<i>Gr</i>	1.00	\$	180.00	15.00	\$	207.00	Y	✓
52	FRONT DOOR SIGNAL LAMP LH	<i>Sm</i>	1.00	\$	189.00	15.00	\$	217.35	Y	X
53	FRONT DOOR PROTECTOR LH	<i>Sm</i>	1.00	\$	295.00	15.00	\$	339.25	Y	X
54	FRONT DOOR LOWER GARNISH LH	<i>Sm</i>	1.00	\$	280.00	15.00	\$	322.00	Y	X
55	FRONT DOOR HINGE UPPER LH		1.00	\$	468.00	15.00	\$	538.20	Y	✓
56	FRONT DOOR HINGE LOWER LH	<i>R</i>	1.00	\$	388.00	15.00	\$	446.20	Y	X
57	FRONT DOOR CHANNEL LH	<i>D/I</i>	1.00	\$	280.00	15.00	\$	322.00	Y	✓
58	FRONT DOOR PILLAR INNER LH	<i>R</i>	1.00	\$	680.00	15.00	\$	782.00	Y	✓
59	FRONT DOOR PILLAR OUTER LH	<i>R</i>	1.00	\$	750.00	15.00	\$	862.50	Y	✓
60	FRONT DASHBOARD <i>PR</i>	<i>mtm</i>	1.00	\$	4,650.00	15.00	\$	5,347.50	Y	✓
61	FRONT DASHBOARD INNER HOUSING <i>PR</i>	<i>mtm</i>	1.00	\$	2,950.00	15.00	\$	3,392.50	Y	✓
62	FRONT DASHBOARD CENTRE COVER	<i>mtm</i>	1.00	\$	2,850.00	15.00	\$	3,277.50	Y	✓
63	FRONT DASHBOARD LOWER COVER	<i>mtm</i>	1.00	\$	2,050.00	15.00	\$	2,357.50	Y	✓

64	FIREWALL	<i>R</i>	1.00	\$	3,800.00	15.00	\$	4,370.00	Y	<i>X</i>
65	AIRCON CONDENSOR	<i>Sn</i>	1.00	\$	1,120.00	15.00	\$	1,288.00	Y	<i>X</i>
66	AIRCON COOLING COIL SYSTEM	<i>CM</i>	1.00	\$	2,800.00	15.00	\$	3,220.00	Y	<i>2</i>
67	AIRCON PIPE - CONDENSOR TO COOLING COIL	<i>Sn</i>	1.00	\$	350.00	15.00	\$	402.50	Y	<i>X</i>
68	AIRCON PIPE - COMPRESSOR TO COOLING COIL	<i>Sn</i>	1.00	\$	318.00	15.00	\$	365.70	Y	<i>X</i>
69	AIR DUCT	<i>Sn</i>	1.00	\$	135.00	15.00	\$	155.25	Y	<i>X</i>
70	AIRCON BLOWER	<i>ngcm</i>	1.00	\$	650.00	15.00	\$	747.50	Y	<i>2</i>
71	AIRCON MOTOR	<i>Sn</i>	1.00	\$	768.00	15.00	\$	883.20	Y	<i>X</i>
72	AIR RESONATOR	<i>Sn</i>	1.00	\$	248.00	15.00	\$	285.20	Y	<i>✓</i>
73	WASHER TANK	<i>Sn</i>	1.00	\$	150.00	15.00	\$	172.50	Y	<i>X</i>
TOTAL (PARTS):					\$ 54,229.00	\$ 62,363.35				

SPECIAL NETT ITEM

1	FRONT DOOR EMAS STICKER LH	<i>Intermed 7?</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>7</i>
2	FRONT DOOR EMAS STICKER RH	<i>~</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>7</i>
3	FRONT PANEL REFLECTIVE STICKERS BLUE & ORANGE		1.00	\$	350.00	0.00	\$	350.00	Y	<i>7</i>
4	FRONT PANEL EMAS STICKER		1.00	\$	180.00	0.00	\$	180.00	Y	<i>7</i>
5	FRONT HEADLAMP CLIPS LH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
6	FRONT HEADLAMP CLIPS RH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
7	FRONT SIGNAL LAMP CLIPS LH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>✓</i>
8	FRONT SIGNAL LAMP CLIPS RH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>✓</i>
9	FRONT SIDE PANEL CLIPS	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>X</i>
10	FRONT GRILLE CLIPS	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>X</i>
11	FRONT NO PLATE	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>201a</i>
12	FRONT WINDSCREEN SEALANT	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>401a</i>
13	FRONT WINDSCREEN INNER SEAL	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>301a</i>
14	FRONT WINDSCREEN CLEANER & PRIMER	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>301a</i>
15	COOLANT	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
16	ROOF LINING CLIPS		1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
TOTAL (PARTS):					\$ 1,640.00	\$ 1,640.00				

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS		1.00	\$	2,500.00	0.00	\$	2,500.00	Y	<i>200d</i>
2	SPRAY PAINTING ON ACCIDENT AREA		1.00	\$	2,000.00	0.00	\$	2,000.00	Y	<i>160d</i>
3	CHECK & REPAIR WIRING SYSTEM		1.00	\$	120.00	0.00	\$	120.00	Y	<i>201</i>
4	RESPRAY TUFF KOTE ON AFFECTED AREA	<i>NZ</i>	1.00	\$	120.00	0.00	\$	120.00	Y	<i>X</i>
5	RESET & PROGRAMME LTA SYSTEM		1.00	\$	480.00	0.00	\$	480.00	Y	<i>7</i>
6	POST ACCIDENT REPAIR INSPECTION		1.00	\$	180.00	0.00	\$	180.00	Y	<i>7</i>
7	R&R FRONT WINDSCREEN TO ASSIST REPAIR		1.00	\$	180.00	0.00	\$	180.00	Y	<i>1201</i>
8	R&R FRONT DOOR ASSY LH & RH		1.00	\$	380.00	0.00	\$	380.00	Y	<i>1601</i>
9	R&R AIRCON CONDESOR & CHARGE UP GAS		1.00	\$	180.00	0.00	\$	180.00	Y	<i>100d</i>

- 10 R&R DAHSBOARD ASSY TO ASSIST REPAIR
 11 R&R COOLING COIL SYSTEM
 12 CONDUCT CHASSIC ALIGMENT
 13 LABOUR TO REMOVE & REFIT ROOFTOP ASSY
 14 LABOUR TO REMOVE & REFIT ROOF LINING

1.00	\$	680.00	0.00	\$	680.00	Y	<u>2801</u>
1.00	\$	380.00	0.00	\$	380.00	Y	<u>1001</u>
1.00	\$	380.00	0.00	\$	380.00	Y	<u>X</u>
1.00	\$	580.00	0.00	\$	580.00	Y	<u>?</u>
1.00	\$	280.00	0.00	\$	280.00	Y	<u>1001</u>

TOTAL (LABOUR) :

\$ 8,440.00 \$ 8,440.00

TOTAL PARTS & LABOUR

\$ 64,309.00 \$ 72,443.35

EXCESS : : S\$ 3000h

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINING

PA. BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 17, 4, 23

SURVEY BY : Memerh

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
11 May @ 20,300h
Recovery After Rain
Ex @ 3000h

TO : **MS FIRST CAPITAL INSURANCE LTD**

ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : **SMP472H**

ESTIMATE REPORT 1st QUOTATION

JOB NO. :

OWNER'S PARTICULAR

NAME : **CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD**

CONTACT :

ADDRESS :

VEHICLE NO. **YP6878P** TRANS

CHASSIS NO. :

MAKE / MODEL : **ISUZU**

ENGINE NO. :

OWNER'S INSURER : **FIRST CAPITAL**

JOB-CODE : **OD** S/A : **JOEY**

ACCIDENT DATE : **10-Apr-23**

CLAIM DETAIL

MATERIALS

			QTY	QUO-PRICE	MARK UP	DISC-PRICE	SUR	EV. PRIC
1	FRONT BUMPER	600	B ₁	1.00 \$ 1,170.00	15.00 \$	1,345.50	Y	✓
2	FRONT BUMPER BRACKET RH	150	B ₁	1.00 \$ 250.00	15.00 \$	287.50	Y	✓
3	FRONT BUMPER BRACKET LH	150	B ₁	1.00 \$ 250.00	15.00 \$	287.50	Y	✓
4	FRONT BUMPER FOG LAMP LH		S ₁	1.00 \$ 305.00	15.00 \$	350.75	Y	X
5	FRONT BUMPER FOG LAMP RH		S ₁	1.00 \$ 305.00	15.00 \$	350.75	Y	X
6	HEADLAMP LH		S ₁	1.00 \$ 750.00	15.00 \$	862.50	Y	X
7	HEADLAMP RH		S ₁	1.00 \$ 750.00	15.00 \$	862.50	Y	X
8	HEADLAMP LOWER GARNISH LH		S ₁	1.00 \$ 280.00	15.00 \$	322.00	Y	X
9	HEADLAMP LOWER GARNISH RH		S ₁	1.00 \$ 280.00	15.00 \$	322.00	Y	X
10	HEADLAMP BRACKET LH		S ₁	1.00 \$ 150.00	15.00 \$	172.50	Y	X
11	HEADLAMP BRACKET RH		S ₁	1.00 \$ 150.00	15.00 \$	172.50	Y	X
12	HEADLAMP WIRE HARDNESS LH		S ₁	1.00 \$ 220.00	15.00 \$	253.00	Y	X
13	HEADLAMP WIRE HARDNESS RH		S ₁	1.00 \$ 220.00	15.00 \$	253.00	Y	X
14	FRONT GRILLE	265	CM	1.00 \$ 480.00	15.00 \$	552.00	Y	✓
15	FRONT PANEL TOP	520	B ₁	1.00 \$ 1,050.00	15.00 \$	1,207.50	Y	✓
16	FRONT PANEL BOTTOM	420	B ₁	1.00 \$ 865.00	15.00 \$	994.75	Y	✓
17	FRONT CORNER PANEL LH	245	CM	1.00 \$ 650.00	15.00 \$	747.50	Y	✓
18	FRONT CORNER PANEL RH	245	CM	1.00 \$ 650.00	15.00 \$	747.50	Y	✓
19	FRONT CORNER PANEL TOP COVER LH		M ₁	1.00 \$ 95.00	15.00 \$	109.25	Y	✓
20	FRONT CORNER PANEL TOP COVER RH		S ₁	1.00 \$ 95.00	15.00 \$	109.25	Y	X
21	FRONT WING MIRROR LH	160	M ₁	1.00 \$ 350.00	15.00 \$	402.50	Y	✓
22	FRONT WING MIRROR BRACKET COVER LH	85	M ₁	1.00 \$ 250.00	15.00 \$	287.50	Y	✓
23	FRONT WING MIRROR BRACKET LH	250	M ₁	1.00 \$ 420.00	15.00 \$	483.00	Y	✓

3185

24	FRONT WING MIRROR RH	Sm	1.00	\$	350.00	15.00	\$	402.50	Y	X
25	FRONT WING MIRROR BRACKET COVER RH	Sm	1.00	\$	250.00	15.00	\$	287.50	Y	X
26	FRONT WING MIRROR BRACKET RH	R	1.00	\$	420.00	15.00	\$	483.00	Y	X
27	FRONT WINDSCREEN GLASS 750	CM	1.00	\$	1,350.00	15.00	\$	1,552.50	Y	✓
28	FRONT WINDSCREEN MOULDING TOP	Mc	1.00	\$	190.00	15.00	\$	218.50	Y	✓
29	FRONT WINDSCREEN MOULDING BOTTOM	Mc	1.00	\$	150.00	15.00	\$	172.50	Y	✓
30	FRONT WIPER PANEL	Apex	1.00	\$	1,191.00	15.00	\$	1,369.65	Y	X
31	FRONT WIPER GARNISH	NJP	1.00	\$	650.00	15.00	\$	747.50	Y	X
32	FRONT WIPER ARM LH 195	R	1.00	\$	300.00	15.00	\$	345.00	Y	✓
33	FRONT WIPER ARM LH 195	B. B. B.	1.00	\$	300.00	15.00	\$	345.00	Y	✓
34	FRONT WINDSCREEN NOZZLE LH	Sm	1.00	\$	102.00	15.00	\$	117.30	Y	X
35	FRONT WINDSCREEN NOZZLE RH	Sm	1.00	\$	102.00	15.00	\$	117.30	Y	X
36	FRONT ROOF TOP PANEL	R	1.00	\$	4,280.00	15.00	\$	4,922.00	Y	X
37	FRONT ROOF LINING	Sm	1.00	\$	1,680.00	15.00	\$	1,932.00	Y	X
38	FRONT DOOR RH	Bu	1.00	\$	910.00	15.00	\$	1,046.50	Y	✓
39	FRONT DOOR TRIM BOARD RH	CM	1.00	\$	550.00	15.00	\$	632.50	Y	✓
40	FRONT DOOR RUBBER RH	CM	1.00	\$	230.00	15.00	\$	264.50	Y	5000 ✓
41	FRONT DOOR SIGNAL LAMP RH	Sm	1.00	\$	189.00	15.00	\$	217.35	Y	X
42	FRONT DOOR PROTECTOR RH	Sm	1.00	\$	295.00	15.00	\$	339.25	Y	X
43	FRONT DOOR LOWER GARNISH RH	Sm	1.00	\$	280.00	15.00	\$	322.00	Y	X
44	FRONT DOOR HINGE UPPER RH 125	R	1.00	\$	468.00	15.00	\$	538.20	Y	✓
45	FRONT DOOR HINGE LOWER RH	R	1.00	\$	388.00	15.00	\$	446.20	Y	X
46	FRONT DOOR CHANNEL RH 150	D. I.	1.00	\$	380.00	15.00	\$	437.00	Y	✓
47	FRONT DOOR PILLAR INNER RH 420	R	1.00	\$	680.00	15.00	\$	782.00	Y	✓
48	FRONT DOOR PILLAR OUTER RH 510	R	1.00	\$	750.00	15.00	\$	862.50	Y	✓
49	FRONT DOOR LH 600	Bu	1.00	\$	910.00	15.00	\$	1,046.50	Y	✓
50	FRONT DOOR TRIM BOARD LH 280	CM	1.00	\$	550.00	15.00	\$	632.50	Y	✓
51	FRONT DOOR RUBBER LH	CM	1.00	\$	180.00	15.00	\$	207.00	Y	✓
52	FRONT DOOR SIGNAL LAMP LH	Sm	1.00	\$	189.00	15.00	\$	217.35	Y	X
53	FRONT DOOR PROTECTOR LH	Sm	1.00	\$	295.00	15.00	\$	339.25	Y	X
54	FRONT DOOR LOWER GARNISH LH	Sm	1.00	\$	280.00	15.00	\$	322.00	Y	X
55	FRONT DOOR HINGE UPPER LH 125	R	1.00	\$	468.00	15.00	\$	538.20	Y	✓
56	FRONT DOOR HINGE LOWER LH	R	1.00	\$	388.00	15.00	\$	446.20	Y	X
57	FRONT DOOR CHANNEL LH 150	D. I.	1.00	\$	280.00	15.00	\$	322.00	Y	✓
58	FRONT DOOR PILLAR INNER LH 420	R	1.00	\$	680.00	15.00	\$	782.00	Y	✓
59	FRONT DOOR PILLAR OUTER LH 510	R	1.00	\$	750.00	15.00	\$	862.50	Y	✓
60	FRONT DASHBOARD 2100	M. J. CM	1.00	\$	4,650.00	15.00	\$	5,347.50	Y	✓
61	FRONT DASHBOARD INNER HOUSING 18501	L	1.00	\$	2,950.00	15.00	\$	3,392.50	Y	✓
62	FRONT DASHBOARD CENTRE COVER 1050	L	1.00	\$	2,850.00	15.00	\$	3,277.50	Y	✓
63	FRONT DASHBOARD LOWER COVER 850	L	1.00	\$	2,050.00	15.00	\$	2,357.50	Y	✓

12290

64	FIREWALL	<i>R</i>	1.00	\$	3,800.00	15.00	\$	4,370.00	Y	<i>X</i>
65	AIRCON CONDENSOR	<i>Sn</i>	1.00	\$	1,120.00	15.00	\$	1,288.00	Y	<i>X</i>
66	AIRCON COOLING COIL SYSTEM <i>1950</i>	<i>cm</i>	1.00	\$	2,800.00	15.00	\$	3,220.00	Y	<i>2</i>
67	AIRCON PIPE - CONDENSOR TO COOLING COIL	<i>Sn</i>	1.00	\$	350.00	15.00	\$	402.50	Y	<i>X</i>
68	AIRCON PIPE - COMPRESSOR TO COOLING COIL	<i>Sn</i>	1.00	\$	318.00	15.00	\$	365.70	Y	<i>X</i>
69	AIR DUCT	<i>Sn</i>	1.00	\$	135.00	15.00	\$	155.25	Y	<i>X</i>
70	AIRCON BLOWER	<i>mg cm</i>	1.00	\$	650.00	15.00	\$	747.50	Y	<i>2</i>
71	AIRCON MOTOR	<i>Sn</i>	1.00	\$	768.00	15.00	\$	883.20	Y	<i>X</i>
72	AIR RESONATOR	<i>Sn</i>	1.00	\$	248.00	15.00	\$	285.20	Y	<i>✓</i>
73	WASHER TANK	<i>Sn</i>	1.00	\$	150.00	15.00	\$	172.50	Y	<i>X</i>
TOTAL (PARTS) :					\$ 54,229.00	\$ 62,363.35				

SPECIAL NETT ITEM

1	FRONT DOOR EMAS STICKER LH	<i>Inter 7.2</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>X</i>
2	FRONT DOOR EMAS STICKER RH	<i>7.2</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>X</i>
3	FRONT PANEL REFLECTIVE STICKERS BLUE & ORANGE	<i>7.2</i>	1.00	\$	350.00	0.00	\$	350.00	Y	<i>X</i>
4	FRONT PANEL EMAS STICKER	<i>7.2</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>X</i>
5	FRONT HEADLAMP CLIPS LH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
6	FRONT HEADLAMP CLIPS RH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
7	FRONT SIGNAL LAMP CLIPS LH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>✓</i>
8	FRONT SIGNAL LAMP CLIPS RH	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>✓</i>
9	FRONT SIDE PANEL CLIPS	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>X</i>
10	FRONT GRILLE CLIPS	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>X</i>
11	FRONT NO PLATE	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>201a</i>
12	FRONT WINDSCREEN SEALANT	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>401a</i>
13	FRONT WINDSCREEN INNER SEAL	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>301a</i>
14	FRONT WINDSCREEN CLEANER & PRIMER	<i>na</i>	1.00	\$	80.00	0.00	\$	80.00	Y	<i>301a</i>
15	COOLANT	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
16	ROOF LINING CLIPS	<i>na</i>	1.00	\$	50.00	0.00	\$	50.00	Y	<i>X</i>
TOTAL (PARTS) :					\$ 1,640.00	\$ 1,640.00				

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS		1.00	\$	2,500.00	0.00	\$	2,500.00	Y	<i>200d</i>
2	SPRAY PAINTING ON ACCIDENT AREA		1.00	\$	2,000.00	0.00	\$	2,000.00	Y	<i>160d</i>
3	CHECK & REPAIR WIRING SYSTEM		1.00	\$	120.00	0.00	\$	120.00	Y	<i>201</i>
4	RESPRAY TUFF KOTE ON AFFECTED AREA	<i>NZ</i>	1.00	\$	120.00	0.00	\$	120.00	Y	<i>X</i>
5	RESET & PROGRAMME LTA SYSTEM	<i>na</i>	1.00	\$	480.00	0.00	\$	480.00	Y	<i>X</i>
6	POST ACCIDENT REPAIR INSPECTION	<i>na</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>X</i>
7	R&R FRONT WINDSCREEN TO ASSIST REPAIR		1.00	\$	180.00	0.00	\$	180.00	Y	<i>120d</i>
8	R&R FRONT DOOR ASSY LH & RH		1.00	\$	380.00	0.00	\$	380.00	Y	<i>160d</i>
9	R&R AIRCON CONDESOR & CHARGE UP GAS		1.00	\$	180.00	0.00	\$	180.00	Y	<i>100d</i>

10	R&R DAHSBOARD ASSY TO ASSIST REPAIR	1.00	\$	680.00	0.00	\$	680.00	Y	<u>2801</u>
11	R&R COOLING COIL SYSTEM	1.00	\$	380.00	0.00	\$	380.00	Y	<u>1001</u>
12	CONDUCT CHASSIC ALIGMENT	1.00	\$	380.00	<i>an</i> 0.00	\$	380.00	Y	<u>X</u>
13	LABOUR TO REMOVE & REFIT ROOFTOP ASSY	1.00	\$	580.00	0.00	<i>an</i> 580.00		Y	<u>X</u>
14	LABOUR TO REMOVE & REFIT ROOF LINING	1.00	\$	280.00	0.00		280.00	Y	<u>1001</u>
TOTAL (LABOUR) :			\$	8,440.00		\$	8,440.00		
TOTAL PARTS & LABOUR			\$	64,309.00		\$	72,443.35		

EXCESS : : S\$ 3000h

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART BY PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 17/4/23

SURVEY BY : Hemmerh

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: