



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : HSBC Life (Singapore) Pte Ltd

DATE: 27/06/2023

Survey details

| | |
|---------------------|----------------------------------|
| Date of loss | 13/4/2023 |
| Date of appointment | 17/4/2023 |
| Date of survey | 17/4/2023 |
| Location of survey | HUA MENG SPRAY PAINTING WORKSHOP |

Vehicle Details:

| | |
|----------------------|---|
| Claim Type: | THIRD PARTY |
| Vehicle number | SNF 1083G |
| Make and Model | MERCEDES BENZ GLA180 URBAN EDITION AUTO |
| Date of registration | 20/8/2020 |
| Excess | |
| Market Value | \$135,000.00 |
| Parf Rebate | \$47,298.00 |
| Nett Loss | \$87,702.00 |

Repair details

| | |
|------------------|-------------|
| Initial Estimate | \$17,085.03 |
|------------------|-------------|

Proposed/Revised repair cost:

| | |
|--------------------------|--------------|
| Parts | \$7,073.37 |
| "Check items (Estimated) | |
| Labour | \$1,570.00 |
| Total | \$8,643.37 |
| Lump Sum (Estimated) | \$6,900.00 |
| | |
| Number of days of repair | 6 days (est) |

Remarks:

The vehicle sustained damages at the rear portion.

Damages Consistent.

The above survey was conducted on a "Without Prejudice" basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.