



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: ANG YVONNE		Ref: CS/HSB23003953/Acy3e2 Date: 30/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2224Y	Veh. Inspected	SNF 1083G
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04LLO	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	17/04/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	W1N1569422J693908	Colour	BLACK
Odometer	39352 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/04/2023	Inspection Date	17/04/2023
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	