

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06807

Vehicle Insured : SMM2463L
Accident Date : 09-Apr-2023

Date : 12-Apr-2023

Our Ref : 023080 (III) / CHAN

PAGE : 1

KWAN YONG CONSTRUCTION PTE LTD
11 JOO KOON CRESCENT
Singapore 629022

Not Authorized
1/12/23
Accident After Rain
3 days

ESTIMATED COST OF REPAIR FOR VOLVO XC60 SKT9867X

1 pc	Rear bumper fascia		<i>Per</i> 2,305.00	<i>—</i>
1 pc	Rear bumper top pad		526.00	<i>?</i>
1 pc	Rear bumper tow cover		<i>mt</i> 84.00	<i>—</i>
1 pc	Rear bumper lower spoiler		<i>pol/di</i> 1,230.00	<i>—</i>
1 pc	Rear lower spoiler ctr garnish		<i>nd/warp</i> 1,423.00	<i>—</i>
2 pcs	Rear bumper side top bracket	@ S\$118.00	236.00	<i>?</i>
2 pcs	Rear bumper side bracket	@ S\$136.00	272.00	<i>?</i>
1 pc	Rear bumper inner parts		256.00	<i>?</i>
1 pc	Rear bumper reinforcement		1,463.00	<i>?</i>
2 pcs	Rear bumper reflector	@ S\$175.00	<i>sn</i> 350.00	<i>X</i>
2 pcs	Rear exhaust pipe heat shield	@ S\$472.00	<i>cl/mw</i> 944.00	<i>✓</i>
1 pc	Rear exhaust heat shield (ctr)		586.00	<i>?</i>
2 pcs	Rear centre parking sensor	@ S\$267.00	534.00	<i>?</i>
4 pcs	Rear parking sensor holder	@ S\$ 25.00	100.00	<i>?</i>
1 pc	Rear end panel		<i>K</i> 984.00	<i>X</i>

11,293.00

Less 10% : 1,129.30

1 pc Rear bumper rivet (set)
1 pc Rear exhaust heat shield rivet

10,163.70
mc 30.00 *sn*
mc 20.00 *sn*

To remove roof lining, front and
rear seats, trim board and carpet

150.00 *?*

To apply undersealing

mc 60.00 *X*

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMM2463L

Page : 2

To putty and spray replaced parts

600.00 ✓

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

3001
800.00

Total : S\$11,823.70

=====

Singapore Dollars Eleven Thousand Eight Hundred
and Twenty Three and Cents Seventy Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: