OMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Model

vehicle No.: SHA7746K

: IONIQ(G3)

Date: 17.04.2023 Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour		Type	Unit Price	Amount	
i .	REAR BUMPER COVER		5.00 to 10.00 to 10.0	LA TAMORIE - L. L. E. M. A. L. L. L. STOPLE	\$ 459.40	100
	REAR BUMPER CLIPS				\$ 22.00	
	REAR BUMPER SIDE BRACKET RH				\$ 55.80	_
	REAR WHEEL HUB CAP RH				\$ 346.40	
1	REAR BUMPER CTR MOULDING				\$ 451.2	1
				1220 .5		
		SUB TOTAL		[-71.0]	\$ 1,334.8	- 1
		LESS 20%		1023.24	\$ 266.9	
		DISCOUNTED TOTAL			\$ 1,067.8	5
	RENEW ADVERTISEMENT STICKER			100	\$ 100.0	0 2
				NETT	\$ 100.0	0
	Labour Charge					
	PANEL BEATING			880	\$ 400.0	0 13
	SPRAY PAINTING CHARGE			90	\$ 600.0	0 5
	REMOVE/ REFIX REVERSE SENSOR				\$ 60.0	0 3
	TUFF KOTE				\$ 60.0	<u>0</u> *
		TOTAL LABOUR		W3.V4	\$ 1,120.0	0
		ESTIMATE TOTAL		2003.24 Coff600 2days \$	\$ 2,287.8	8
				-2 days \$		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfihn 97495749

"WPI 17/4/13 C 330pm

1/3 Resum after report

2 days

fanfhing [Huntown

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signa ure:

Date: