

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 19 Apr 2023

Preliminary Advice

Vehicle No	: SCG90S	Accident Date	: 06/04/2023
Make	: BMW M4	Policy No.	: DMPCSNW00258482200
Assignment Date	: 18/04/2023	Excess	: S\$3,500.00
Date of Inspection	: 18/4/2023	Est. Duration of Repair	: 5
Inspection At	: PERFORMANCE MOTORS LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,694.35
Revised Amount	:S\$	15,638.45
Check Items (Estimated)	:S\$	28,886.90
Total	:S\$	44,525.35
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	451,000.00
COE / PARF Rebate	:S\$	195,207.00
Salvage Value	:S\$	
Margin for Repair	:S\$	255,793.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .