

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / 11123003973 / 4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMY9336Lat Workshop m/s precize

of _____

Insured: SMN 64154

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8115k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

B 5017

Vehicle: IN / OUT

Date: _____ Person Contacted: Rep 13k.Veh No: SMY9336L Yr Regn: 30/03/24Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or 1.5604XMake: SSANGYONG KORANDO 1497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 48149 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPT70A1Y SMP 050007Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 13/4/23 D.O.I. 18/4/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/6/23 NO 2nd hand parts, 21A & 57993 handling \$2950
 4/5 & 16,200 informed Yan Hong (Red & 9564.79, 37%)

Date/Time, File Pass to?

☐ : Preli. Report1) 1☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10Resurvey No. of Trip: 3

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: CAAMALump Sum / I.B.I. (\$) 16200

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

06-06-2023

Date of Accident : 13/04/2023

OUR REF : SMY 9336L/T/23

ROZROCK

Blk 302 Clementi Ave 4

#15-543

Singapore 120302

ESTIMATE BILL ON VEH. NO. : SMY 9336L

MODEL : SSANGYONG KORANDO

CHASSIS NO: KPT70A1YSMP050007

LIST ITEM

Tail Gate		3oddy 120	1,940.60	—
Tail Gate Lock		00/ym	498.10	—
Tail Gate Striker		11	31.65	X
Tail Gate Weather Stripe		1w1	286.10	—
Tail Gate Stopper	2pcs @ 18.10	11	36.20	X
Tail Gate Badge		11	62.40	X
Tail Gate Emblum "Ssangyong"		rec	60.10	—
Tail Gate Emblum "Korando"		rec	78.10	—
Tail Gate Chorme		11	297.40	X
Tail Gate Chorme Clips	8pcs @ 6.00	11	48.00	X
Rear floor panel Tools sponge		1w1	596.10	—
Tail Gate Inner Trim Board Clips	8pcs @ 6.00	11	48.00	X
Tail Gate Reflector	2pcs @ 409.80	11	819.60	X
Tail Gate Reflector Sealant	2pcs @ 50.00	11	100.00	X
Tail Gate Reflector Clips	4pcs @ 6.00	11	24.00	X
Tail Gate Emblum "Turbo"		NT	49.75	X
Tail Gate Outer Keyless Antenna		CNa	390.15	—

Not Allowed
rec
18/4/23
4/5 @ 16,200
telephone the way
10 days
Date input: 14/04/23 to 30/04/23

LKK - Marcus

Rear Windscreen Glass Inner Seal		1m	50.00	40 S/N
Rear Windscreen Glass Clips	14pcs @ 6.00	11	84.00	X
Rear Bumper - Top		Dis	820.92	—
Rear Bumper Side Retainer	2pcs @ 49.65	Self	99.30	—
Rear Bumper Lower Bracket	4pcs @ 42.40	twi	169.60	—
Rear Bumper Reinforcement		BAO	430.65	—
Rear Bumper Lower Diffuser		Dis	596.40	—
Rear Bumper Lower Center Spoiler		Dis	310.60	—
Rear Bumper Clips	10pcs @ 6.00	1m	60.00	—
Rear Bumper Tow Cover		twi	28.40	—
Rear Bumper Lamp	2pcs @ 390.97	one	781.94	—
Rear Number Plate Lamp	2pcs @ 45.50	11	91.00	X
Rear Number Plate Lamp Garnish with Switch		one	138.63	—
Rear End Panel		Self	635.10	—
Rear End Panel Top Trim		twi	288.14	—
Rear End Panel Top Trim Clips	4pcs @ 6.00	11	24.00	X
Rear Floor Panel Board		waged	618.40	—
Rear Floor Panel Insulator Cloth		1m	169.41	—
Exhaust Silencer		DD	985.10	—
Exhaust Silencer Mounting	2pcs @ 33.40	11	66.80	X
Exhaust Silencer Heater Shield		Self	92.15	—
Rear Fender Wheel Arc Garnish - LH		Self/twi	197.65	—
Rear Fender Wheel Arc Garnish Clips	20pcs @ 6.00	11	120.00	X
Front Bumper		Dis	1,494.68	—
Front Bumper Lower Diffuser		Dis	510.65	—
Front Bumper Clips	10pcs @ 6.00	1m	60.00	—
Front Bumper Center Air Grille Garnish		Self/one	363.45	—
Front Bumper Day Light - LH		11	981.42	X

Front Bumper Day Light Cover		11	183.15	X
Front Bumper Tow Cover		11	28.40	X
Font Bumper Sponge	260	7111	301.81	/
Head Lamp - LH		holder one	2,491.85	/
Head Lamp Bracket		one	49.16	/
Front Grille		one	985.18	/
Front Grille Center Bracket		one	96.14	/
Front Grille Clips	6pcs @ 6.00	11	36.00	X
Front Support Panel		one	1,450.16	/
Bonnet Emblem "Korando"		111	82.14	/
Front Fender Wheel Arc Garnish - LH		7111	197.65	/
Front Fender Wheel Arc Garnish Clips	8pcs @ 6.00	11	48.00	X
Front Fender Splash Shield 111		7111	164.15	/
Front Fender Splash Shield Clips	8pcs @ 6.00	111	48.00	/
			21,796.43	
Less Discount 10%:			2,179.64	
			19,616.79	

SPECIAL NETT ITEM

Rear Windscreen Glass Sealant		111	60.00	40
Rear Number Plate		5111/1115	45.00	40
Rear Number Plate Casing			29.00	
Front Number Plate		one	45.00	40
Front Number Plate Casing			29.00	
1604 Reverse Sensor		should	880.00	200

LABOUR CHARGE

Towing.		11	120.00	X
To Check Wiring.			80.00	30
To Tuff Coat Affected Areas.			180.00	60
To Remove & Refix Interior Upholstery.			180.00	80

To Remove & Refix Tail Gate Mechanism.	220.00 60
To Remove & Refix Rear Windscreen Glass.	180.00 120
To Remove & Refix Reverse Sensor and Camera.	280.00 50
To Remove & Refix Radiator & Top Up Coolant.	180.00 X
To Remove & Refix Air Cond Condensor & Top Up Gas.	180.00 100
To Reset Electrical Module System.	280.00 X
To Renew Damaged Parts, Straighten and Repair Bonnet, Front LH Fender, Rear Fender and Aligned All Parts.	1,500.00 / 400
To Remove & Refix Exhaust Silencer and Straighten Exhaust Center Pipe.	280.00 80
To Respray Affected Areas.	1,400.00 / 380

	25,764.79
GST 8% :	2,061.18
TOTAL AMOUNT :	27,825.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-18524.85
100
16672.36
320
3360
20352.76
22
16200