

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

06-06-2023

Date of Accident : 13/04/2023

OUR REF : SMY 9336L/T/23

ROZROCK

Blk 302 Clementi Ave 4

#15-543

Singapore 120302

ESTIMATE BILL ON VEH. NO. : SMY 9336L

MODEL : SSANGYONG KORANDO

CHASSIS NO: KPT70A1YSMP050007

LIST ITEM

Tail Gate		3oddy 120	1,940.60	—
Tail Gate Lock		00/ym	498.10	—
Tail Gate Striker		11	31.65	X
Tail Gate Weather Stripe		1w1	286.10	—
Tail Gate Stopper	2pcs @ 18.10	11	36.20	X
Tail Gate Badge		11	62.40	X
Tail Gate Emblum "Ssangyong"		her	60.10	—
Tail Gate Emblum "Korando"		her	78.10	—
Tail Gate Chorme		11	297.40	X
Tail Gate Chorme Clips	8pcs @ 6.00	11	48.00	X
Rear floor panel Tools sponge		1w1	596.10	—
Tail Gate Inner Trim Board Clips	8pcs @ 6.00	11	48.00	X
Tail Gate Reflector	2pcs @ 409.80	11	819.60	X
Tail Gate Reflector Sealant	2pcs @ 50.00	11	100.00	X
Tail Gate Reflector Clips	4pcs @ 6.00	11	24.00	X
Tail Gate Emblum "Turbo"		NT	49.75	X
Tail Gate Outer Keyless Antenna		cna	390.15	—

Not Allowed
her
18/4/23
4/5 @ 16,200
telephone the way
10 days
Date input: 14/04/23 to 30/04/23

LKK - Marcus

Rear Windscreen Glass Inner Seal		1m	50.00	40 S/N
Rear Windscreen Glass Clips	14pcs @ 6.00	11	84.00	X
Rear Bumper - Top		Dis	820.92	—
Rear Bumper Side Retainer	2pcs @ 49.65	Self	99.30	—
Rear Bumper Lower Bracket	4pcs @ 42.40	twl	169.60	—
Rear Bumper Reinforcement		BAO	430.65	—
Rear Bumper Lower Diffuser		Dis	596.40	—
Rear Bumper Lower Center Spoiler		Dis	310.60	—
Rear Bumper Clips	10pcs @ 6.00	1m	60.00	—
Rear Bumper Tow Cover		twl	28.40	—
Rear Bumper Lamp	2pcs @ 390.97	one	781.94	—
Rear Number Plate Lamp	2pcs @ 45.50	11	91.00	X
Rear Number Plate Lamp Garnish with Switch		one	138.63	—
Rear End Panel		Self	635.10	—
Rear End Panel Top Trim		twl	288.14	—
Rear End Panel Top Trim Clips	4pcs @ 6.00	11	24.00	X
Rear Floor Panel Board		waged	618.40	—
Rear Floor Panel Insulator Cloth		1m	169.41	—
Exhaust Silencer		DD	985.10	—
Exhaust Silencer Mounting	2pcs @ 33.40	11	66.80	X
Exhaust Silencer Heater Shield		Self	92.15	—
Rear Fender Wheel Arc Garnish - LH		Self/twl	197.65	—
Rear Fender Wheel Arc Garnish Clips	20pcs @ 6.00	11	120.00	X
Front Bumper		Dis	1,494.68	—
Front Bumper Lower Diffuser		Dis	510.65	—
Front Bumper Clips	10pcs @ 6.00	1m	60.00	—
Front Bumper Center Air Grille Garnish		Self/one	363.45	—
Front Bumper Day Light - LH		11	981.42	X

12700.42

Front Bumper Day Light Cover		11	183.15	X
Front Bumper Tow Cover		11	28.40	X
Font Bumper Sponge	260	7111	301.81	/
Head Lamp - LH		holder one	2,491.85	/
Head Lamp Bracket		one	49.16	/
Front Grille		one	985.18	/
Front Grille Center Bracket		one	96.14	/
Front Grille Clips	6pcs @ 6.00	11	36.00	X
Front Support Panel		one	1,450.16	/
Bonnet Emblem "Korando"		111	82.14	/
Front Fender Wheel Arc Garnish - LH		7111	197.65	/
Front Fender Wheel Arc Garnish Clips	8pcs @ 6.00	11	48.00	X
Front Fender Splash Shield 111		7111	164.15	/
Front Fender Splash Shield Clips	8pcs @ 6.00	111	48.00	/
			21,796.43	
Less Discount 10%:			2,179.64	
			19,616.79	

SPECIAL NETT ITEM

Rear Windscreen Glass Sealant		111	60.00	40
Rear Number Plate		5111/1115	45.00	40
Rear Number Plate Casing			29.00	
Front Number Plate		one	45.00	40
Front Number Plate Casing			29.00	
1604 Reverse Sensor		shock	880.00	200

LABOUR CHARGE

Towing.		11	120.00	X
To Check Wiring.			80.00	30
To Tuff Coat Affected Areas.			180.00	60
To Remove & Refix Interior Upholstery.			180.00	80

To Remove & Refix Tail Gate Mechanism.	220.00 60
To Remove & Refix Rear Windscreen Glass.	180.00 120
To Remove & Refix Reverse Sensor and Camera.	280.00 50
To Remove & Refix Radiator & Top Up Coolant.	180.00 X
To Remove & Refix Air Cond Condensor & Top Up Gas.	180.00 100
To Reset Electrical Module System.	280.00 X
To Renew Damaged Parts, Straighten and Repair Bonnet, Front LH Fender, Rear Fender and Aligned All Parts.	1,500.00 / 400
To Remove & Refix Exhaust Silencer and Straighten Exhaust Center Pipe.	280.00 80
To Respray Affected Areas.	1,400.00 / 380

	25,764.79
GST 8% :	2,061.18
TOTAL AMOUNT :	27,825.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-18524.85
100
16672.36
320
3360
20352.76
22
16200