

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM23D202503/C01/CHEESC Date: 08<sup>th</sup> May 2023

Our Ref : CS/CTI23003976/Kqp3e2

## M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMN 5555E ACCIDENT ON 30/03/2023

Instruction was received to inspect the vehicle Reg. No. SMN 5555E. The inspection was conducted on 18/04/2023 at the premises of M/s Ding Auto Pte Ltd, Blk 10 #01-20 Sin Ming Ind Est Sec C, Singapore 575645.

The following vehicle information was recorded:

Registration Number : SMN 5555E

Make/Model : B.M.W. M6 Gran Coupe 4DR Led DSC NAV HUD

Year of Registration : 2014

Body Colour : Metallic Blue

Chassis Number : WBS6C92080DV74205

Engine Capacity : 4395 cc Speedometer Reading : 109142 km

The vehicle sustained damages at the front, o/s front portion and undercarriage. The Estimated repair cost of such vehicle is \$\$64,029.20 (Sin Dollars: Sixty-Four Thousand Twenty-Nine and Twenty Cents only.) (Exclude check items \$\$86,678.45Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a)	If the vehicle to be "Total Loss"

Market Value

S\$ 160,000.00 (est)

Less: LTA Reimbursement Value (RV) S\$ 110,557.00)

S\$ 49,443.00

Less: Excess (S\$ 2,500.00)

Nett Liability S\$ 46,943.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 64,029.20

(Exclude check items S\$86,678.45Nett)

Less: Excess (S\$ 2,500.00)

\_\_\_\_\_

Nett Liability

S\$ 61,529.20

(a) - (b) = (S\$ 14,586.20)

=========

The amount of estimated saving of S\$14,586.20 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

 $AM\ CATARI(CAN), M.MATA(USA), M.MdATA(USA),$ 

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.