

Ass. P.C. BY:

REF:

OS/MSG 23003977/Drv³

ASSIGNMENT

COE May 2027

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

9

days

Res.: Yes or No

Lim Sum: _____

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHC 3879 B

Yr Regn: _____

2019 / May

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Prius

c.c 1798

Colour: _____

Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

607760

T/Radio: Insured / Std / NI / NA

Eng/No: _____

22R2C27058

C/No: _____

JTDKB3FU303081248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MBC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: _____

S

mm

R/Bal: _____

S

mm

L/Bal: _____

S

mm

L/Bal: _____

S

mm

D.O.A: _____

17/04/2023

D.O.L: _____

18/04/2023

Survey held at _____

21st St Sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front 4 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSG SDS 2181 A

To seek approval 2/5 16,000/- with 9 days of work

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS SI

Photos

Others

Add Fee: _____

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inve (\$)

Report Form: _____

1 unit Form 11 P to 12

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	5HC3879B
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Apr 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	2ZR2C27058
Chassis No.:	JTDKB3FU303081248
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	31 May 2019
First Registration Date:	31 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,309.00
COE Rebate Amount:	\$11,379.00
Total Rebate Amount:	\$22,064.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Apr 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/04/2023 23:57 (SGT)
Reported by	Actual Driver
Date of Accident	17/04/2023 11:45 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	ANG MO KIO AVE SLIP ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3879B
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-98717455
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	HSBC Life (Singapore) Pte. Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	NG POH CHUAN
NRIC No	SXXXX384F
Date Of Birth	27/04/1962
Occupation	Outdoor

Date Of Driving Pass	14/02/1984
Driving experience	39 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98717455
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 351A CANBERRA ROAD # 06-317
Address complement	-
Postcode	751351
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 17.04.2023 AT ABOUT 1145HRS I WAS DRIVING MY VEHICLE A SHC3879B FETCHING MY PASSENGER TO SERANGOON NORTH. MY VEHICLE A WAS ON THE LEFT LANE OF SLIP ROAD FROM CTE /SLE TOWARDS ANG MO KIO AVE 3. VEHICLE B SGT471K WHICH WAS IN FRONT BRAKE AND I MANAGED TO STOP IN TIME. VEHICLE C SDS2181A THEN REAR ENDED MY VEHICLE A PUSHING IT FORWARD TO REAR END VEHICLE B.

IT IS A 4 CAR CHAIN.

MY PASSENGER IS NOT INJURED AND HE GET HIMSELF TO DESTINATION

SCENE PHOTOS TAKEN.

PARTICULARS TAKEN ONLY WITH VEHICLE C.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT471K
Vehicle Manufacturer	Mitsubishi
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT AND REAR
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SDS2181A
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SOH
Contact Number	(Phone) +65-97383848
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	REAR
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLANIMPORTANT NOTICE

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (Collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date &
Time

Sketch Plan

 Driver's Signature (if driver is not the policyholder) / Date
& Time 17.04.2023. 1540HRS

 FLASH ACCIDENT
REPORTING OFFICER
KYMI

 Witnessed by Reporting Centre
Personnel

A - SHC3879B	
B - SGT471K	
C - SDS2181A	
D - UNKNOWN	

Describe Circumstances of the Accident

ON 17.04.2023 AT ABOUT 1145HRS I WAS DRIVING MY VEHICLE A SHC3879B FETCHING MY PASSENGER TO SERANGOON NORTH. MY VEHICLE A WAS ON THE LEFT LANE OF SLIP ROAD FROM CTE /SLE TOWARDS ANG MO KIO AVE 3. VEHICLE B SGT471K WHICH WAS IN FRONT BRAKE AND I MANAGED TO STOP IN TIME. VEHICLE C SDS2181A THEN REAR ENDED MY VEHICLE A PUSHING IT FORWARD TO REAR END VEHICLE B.
IT IS A 4 CAR CHAIN.
MY PASSENGER IS NOT INJURED AND HE GET HIMSELF TO DESTINATION
SCENE PHOTOS TAKEN.
PARTICULARS TAKEN ONLY WITH VEHICLE C.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time
17.04.2023. 1545HRS

FLASH ACCIDENT
REPORTING OFFICER
KYMI



Witnessed by Reporting Centre
Personnel

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 18-Apr-23

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC 3879 B

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>St/Dealt</i>	1	\$1,303.29	\$1,303.29
REAR TRUNK LID LOCK <i>Done</i>	1	\$530.79	\$530.79
REAR TRUNK LID LOCK COVER <i>Src</i>	1	\$ 129.80	\$ 129.80
REAR TRUNK LID LOCK SWITCH <i>HH</i>	1	\$ 468.90	\$ 468.90
REAR TRUNK LID COVER TRIM BOARD <i>mainly crsdc</i>	1	\$254.40	\$254.40
Boot Lid Trimboard, Centre <i>HH</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	2	\$92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HH</i>	1	\$124.80	\$ 124.80
BOOT HANDLE <i>HH</i>	1	\$31.80	\$31.80
REAR TRUNK LID RUBBER <i>deformed</i>	1	\$365.20	\$365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>HH</i>	1	\$969.70	\$969.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>cut/mainly inner 1</i>		\$1,054.71	\$1,054.71
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (HYBRID) <i>Hec</i>	1	\$62.14	\$62.14
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$81.43	\$81.43
THIRD BRAKE LIGHT <i>HH</i>	1	\$394.70	\$394.70
REAR TRUNK LID STRIKER <i>leg</i>	1	\$98.70	\$98.70
REAR TRUNK LID HINGE (LH/RH) <i>HH</i>	2	\$189.50	\$379.00
REAR TRUNK LID ABSORBER (LH/RH) <i>HH</i>	2	\$287.50	\$575.00
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>HH</i>	2	\$127.90	\$255.80
REAR TRUNK LID STOPPER (LH/RH) <i>HH</i>	2	\$84.80	\$169.60
SPOILERSUB-ASSY, REAR <i>HH</i>	1	\$1,787.79	\$1,787.79
REAR WINDSCREEN GLASS W/ MOULDING <i>HH</i>	1	\$1,884.32	\$1,884.32
REAR NO. PLATE LAMP LH/RH <i>HH</i>	2	\$163.50	\$327.00
REAR BUMPER <i>Dealt</i>	1	\$503.04	\$503.04
REAR BUMPER RE-INFORCEMENT <i>St</i>	1	\$378.32	\$378.32

REAR BUMPER LOWER COVER <i>dislodged</i>	1	\$654.96	\$654.96	✓
REAR BUMPER SIDE RETAINER <i>SW</i>	2	\$112.70	\$225.40	X
REAR BUMPER TOWING COVER <i>dislodged</i>	1	\$82.70	\$82.70	✓
REAR BUMPER CLIPS <i>HW</i>	1	\$22.00	\$22.00	✓
REAR BUMPER SIDE CLIP <i>HW</i>	2	\$25.00	\$50.00	X
REAR BUMPER UPPER STOPPER (LH/RH) <i>HW</i>	2	\$76.40	\$152.80	X
SEAL, REAR BUMPER SIDE, LH/RH <i>O/S HW W/S dislodged</i>	2	\$148.40	\$296.80	✓
REAR BUMPER UNDER SIDE COVER (LH/RH) <i>broken / dislodged</i>	2	\$232.00	\$464.00	✓
ARM SUB-ASSY, REAR BUMPER, (LH/RH) <i>HW</i>	2	\$139.60	\$279.20	X
REAR BUMPER REVERSE SENSOR <i>Down</i>	1	\$235.70	\$235.70	✓
TAIL LAMP ASSY (UPPER) <i>mainly broken</i>	2	\$557.90	\$1,115.80	✓
TAIL LAMP ASSY (LOWER) <i>mainly broken</i>	2	\$570.00	\$1,140.00	✓
TAIL LAMP QUARTER PANEL <i>HW</i>	2	\$216.00	\$432.00	X
TAIL LAMP SIDE COVER <i>HW</i>	2	\$256.00	\$512.00	X
REAR TAILLAMP GUIDE - WHITE <i>HW</i>	1	\$95.30	\$95.30	X
REAR END PANEL <i>Rebel</i>	1	\$738.96	\$738.96	✓
REAR END PANEL GARNISH <i>dislodged</i>	1	\$294.80	\$294.80	✓
REAR SPARE TYRE PANEL <i>HW</i>	1	\$960.80	\$960.80	X
REAR END PANEL GARNISH COVER <i>HW</i>	1	\$138.90	\$138.90	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>HW</i>	1	\$668.90	\$668.90	X
REAR FIBER TOOL BOX TRIM (LH/RH) <i>O/S HW W/S trim</i>	2	\$598.00	\$1,196.00	✓
REAR FIBER TOOL BOX CENTER <i>HW</i>	1	\$186.20	\$186.20	X
SPARE TYRE LOCK NUT <i>broken</i>	1	\$88.40	\$88.40	✓
SPARE TYRE LOCK NUT BRACKET <i>HW</i>	1	\$113.50	\$113.50	X
REAR EXHAUST PIPE RH <i>HW</i>	1	\$1,163.40	\$1,163.40	X 7850.25
REAR EXHAUST PIPE HANGER <i>HW</i>	1	\$40.70	\$40.70	X
REAR EXHAUST PIPE INSULATOR <i>BT</i>	1	\$314.60	\$314.60	✓
REAR EXHAUST PIPE (FRONT) <i>HW</i>	1	\$2,966.20	\$2,966.20	X
BONNET <i>BT</i>	1	\$1,117.93	\$1,117.93	✓
INSULATOR, HOOD <i>HW</i>	1	\$398.10	\$398.10	X
INSULATOR CLIPS 10 PCS <i>HW</i>	1	\$36.80	\$36.80	X
BONNET RUBBER <i>HW</i>	1	\$35.50	\$35.50	X
BONNET HINGE (LH/RH) <i>BT</i>	2	\$87.70	\$175.40	✓
BONNET LOCK <i>BT</i>	1	\$132.60	\$132.60	✓
CATCH, HOOD AUXILIARY HOOK <i>HW</i>	1	\$8.60	\$8.60	X
RADIATOR GRILLE <i>broken</i>	1	\$438.00	\$438.00	✓
RADIATOR GRILLE EMBLEM <i>mainly broken</i>	1	\$88.00	\$88.00	✓

FRONT BUMPER COVER <i>distorted</i>	1	\$591.75	\$591.75	✓
FRONT BUMPER REINFORCEMENT <i>4x</i>	1	\$812.89	\$812.89	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>HH</i>	1	\$115.70	\$115.70	X
FRONT BUMPER LOWER REINFORCEMENT <i>HH</i>	1	\$364.20	\$364.20	X
FT BUMPER LOWER REINFORCEMENT BRACKET LH/RH <i>HH</i>	2	\$330.00	\$660.00	X
ABSORBER, FRONT BUMPER, LOWER <i>HH</i>	1	\$127.70	\$127.70	X
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HH</i>	2	\$ 320.70	\$641.40	X
FRONT SIDE MEMBER SIDE COVER <i>HH</i>	2	\$ 172.50	\$345.00	X
FRONT BUMPER SPONGE <i>4x</i>	1	\$78.80	\$78.80	✓
FRONT BUMPER LOWER GRILLE <i>HH</i>	1	\$193.18	\$193.18	X
LAMP ASSY, FOG, RH <i>HH</i>	1	\$920.00	\$920.00	X
LAMP ASSY, FOG, LH <i>HH</i>	1	\$920.00	\$920.00	X
FRONT NO. PLATE GARNISH <i>broken</i>	1	\$99.00	\$99.00	✓
FRONT BUMPER SIDE RETAINER <i>HH</i>	2	\$77.00	\$154.00	X
FRONT LOWER PANEL <i>HH</i>	1	\$320.65	\$320.65	X 11,173.02
FRONT LOWER SIDE RAIL (LH/RH) <i>HH</i>	2	\$230.80	\$461.60	X
FRONT LOWER CROSSMEMBER <i>HH</i>	1	\$357.70	\$357.70	X
FRONT UNDER COVER <i>HH</i>	1	\$180.80	\$180.80	X
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40	X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00	✓ 2637.60
UNIT ASSY, HEADLAMP, LH (LED) <i>wornly broken</i>	1	\$3,455.00	\$3,455.00	✓ 2637.60
HEAD LAMP PANEL (RH) <i>4x</i>	1	\$240.10	\$240.10	✓
HEAD LAMP PANEL (LH) <i>4x</i>	1	\$240.10	\$240.10	✓
TOP PANEL CENTRE <i>4x</i>	1	\$364.98	\$364.98	✓
TOP PANEL SIDE <i>4x</i>	2	\$145.90	\$291.80	✓
BRACE PANEL <i>HH</i>	1	\$75.20	\$75.20	X
RADIATOR ASSY <i>4x</i>	1	\$1,841.80	\$1,841.80	✓
RADIATOR FAN MOTOR ASSY <i>HH</i>	1	\$1,093.90	\$1,093.90	X
DEFLECTOR, RADIATOR SIDE, RH <i>HH</i>	1	\$83.50	\$83.50	X
DEFLECTOR, RADIATOR SIDE, LH <i>HH</i>	1	\$83.50	\$83.50	X
HORN (1 PC) <i>HH</i>	2	\$112.71	\$225.42	X
CONDENSER ASSY, W/RECEIVER <i>4x</i>	1	\$1,336.60	\$1,336.60	✓
SUB TOTAL			\$49,954.59	23,618.73
LESS 20% 25%			\$9,990.92	17,714.04
DISCOUNTED TOTAL			\$39,963.67	

REVERSE CAMERA ASSY <i>HW</i>	SN	1	\$380.00	\$380.00	X
REAR TRUNK LOWER W/S MOULDING <i>HW</i>	SN	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT <i>HW</i>	SN	1	\$46.00	\$46.00	✓
REAR WINDSCREEN SEALANT <i>HW</i>	SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH COVER <i>SWC</i>	SN	1	\$100.00	\$100.00	X
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>HW</i>	SN	1	\$60.00	\$60.00	✓
FRONT NO. PLATE <i>WT</i>	SN	1	\$25.00	\$25.00	} 45/-
FRONT NO. PLATE TRIM COVER <i>WT</i>	SN	1	\$30.00	\$30.00	
COOLANT <i>HW</i>	SN	1	\$45.00	\$45.00	X
SUB TOTAL				\$912.00	197.00/-
Labour Charge					
Panel Beating		1	\$2,400.00	\$2,400.00	1000/-
Spray Painting Charge		1	\$1,800.00	\$1,800.00	1000/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$100.00	\$100.00	40/-
Towing Charge		1	\$80.00	\$80.00	HW
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00	80/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	HW
Remove/Refix Radiator		1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	80/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	HW
TOTAL LABOUR				\$5,570.00	2280.00/-
ESTIMATE TOTAL				\$46,445.67	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com					

18/04/2023 @ 1700h

HW And

2/sum

Sign

LKK And

20,191.04

4/5 16,000/-

9 days. Check part prices.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: