



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0423-9117
Policy No:	DMCG23003903	Date of Loss:	13/04/2023
Vehicle Reg. No.:	GBL1582T	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FIT TRANSPORT SYSTEMS PTE. LTD.	Contact No:	+6598316501
Driver:	ZHANG FANG CHAO		

Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Vehicle Reg. Date:	26/03/2021
Vehicle Colour:	SILVER	Chassis No:	JTFHT02P900251773
Engine No:	1KDB073132		
Odometer:	92181 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 7

*Take photo before painting.
Excess \$500
20/4/23*

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	3,487.00
Miscellaneous Items	560.00
Labour	2,155.00
Paintwork Labour	1,000.00
Towing	0.00

P/P & not followed

Gross Total (\$\$)	7,202.00
+ GST 8.00% (\$\$)	576.16
Nett Amount (\$\$)	7,778.16

This claim is handled by: LIANG SIEW CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Workshop Estimate: \$7,202.00

Adjusted Amount : \$4,135.50

Check: \$143.00

Total: \$4,278.50

Repair Duration: 7 days

Pre Review By : Carma Tech

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Apr 2023)

Parts: 213

TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/GBL1582T/17/04/2023 18:04

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR FENDER PANEL (OUTER) - RH <i>800.00</i>	0.00	0.00	*800.00 F
2	1	NA	*REAR FENDER PANEL (INNER) - RH <i>650.00</i>	0.00	0.00	*650.00 F
3	1	NA	*REAR FENDER PANEL INNER TRIM - RH <i>350.00</i>	0.00	0.00	*350.00 F
4	12	NA	*REAR FENDER PANEL INNER TRIM CLIPS - RH <i>30.00</i>	0.00	0.00	*30.00 F
5	1	NA	*REAR FENDER PANEL OUTER ROLLER RAIL BAR - RH <i>230.00</i>	0.00	0.00	*230.00 F
6	1	NA	*REAR WHEEL HOUSE PANEL (OUTER) - RH <i>500.00</i>	0.00	0.00	*500.00 F
7	1	NA	*REAR MUDFLAP - RH <i>55.00</i>	0.00	0.00	*55.00 F
8	1	NA	*TAIL LAMP - RH <i>130.00</i>	0.00	0.00	*130.00 F
9	1	NA	*TAIL LAMP LOWER GARNISH - RH <i>50.00</i>	0.00	0.00	*50.00 F
10	1	NA	*REAR RIM - RH <i>300.00</i>	0.00	0.00	*300.00 F
11	1	NA	*REAR RIM HUB CAP - RH <i>75.00</i>	0.00	0.00	*75.00 F

F=Franchise part.

Sub Total (\$\$) 3,170.00

+ Margin on L,N Items 10.00% (\$\$) 317.00

Total Parts (\$\$) 3,487.00

Progressive Car Care Pte Ltd/GBL1582T/17/04/2023 18:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER SENSOR 11	280.00
2	1	REAR TYRE - RH 11	280.00
Sub Total (S\$)			560.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New 600	1,000.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS;LHR FENDER INNER PANEL; CUT/WELD LHR FENDER; REMOVE; REPLACE ACCIDENT PARTS	New 1200	2,000.00
3	TO CHECK WIRING	New 20	30.00
4	TO TRANSFER REAR BUMPER SENSOR	New 11X	50.00
5	TO 4 WHEEL ALIGNMENT	New 11X	75.00
Gross Labour Cost (S\$)			3,155.00

Progressive Car Care Pte Ltd/GBL1582T/17/04/2023 18:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.